# BHUTAN POWER CORPORATION LIMITED BHUTAN POWER SYSTEM OPERATOR

**THIMPHU: BHUTAN** 



# ANNUAL TRANSMISSION SYSTEM PERFORMANCE REPORT FOR THE YEAR 2021

JANUARY-2022

Sl. No	Table of Contents	Page No.
1.0	INTRODUCTION	3
2.0	PERFORMANCE OF GENERATING STATIONS	3
2.1	POWER GENERATION	
2.2	PLANT FACTOR	5
3.0	PEAK DEMAND, ENERGY AVAILABILITY AND REQUIREMENT FOR THE COUNTRY	8
3.1	NATIONAL LOAD	8
3.2	WESTERN GRID PEAK LOAD	
3.3	EASTERN GRID PEAK LOAD	11
4.0	EXPORT AND IMPORT OF ELECTRICITY TO/FROM NEIGHBORING COUNTRIES	12
4.1	EXPORT OF ELECTRICITY TO NEIGHBORING COUNTRY	
4.2	IMPORT OF ELECTRICITY FROM NEIGHBORING COUNTRY	13
5.0	FREQUENCY PROFILE: MAXIMUM AND MINIMUM FREQUENCY RECORDED AND THE FREQUENCY DURATION IN DI	
FREQ	UENCY BANDS	
6.0	VOLTAGE PROFILE OF SELECTED SUBSTATIONS	16
7.0	MAJOR GENERATING AND TRANSMISSION OUTAGE	
8.0	TRANSMISSION CONSTRAINTS	19
9.0	INSTANCES OF PERSISTENT OR SIGNIFICANT NON-COMPLIANCE WITHIN THE GIRD CODE REGULATION	19

#### 1.0 INTRODUCTION

In compliance to Grid Code Regulation 2008, Clause No. 6.14.2.1, this office prepared an annual report covering the performance of the Transmission System and details as required by the Ministry and the Authority annually for development of power system master plan and formulation of other policy decisions, thus this report contains the performance of Transmission System for the year 2019.

All the index and other calculations in this report have been executed based on the data received from substations and generating plants.

#### 2.0 PERFORMANCE OF GENERATING STATIONS


#### 2.1 POWER GENERATION

The maximum individual plant generation was recorded as 1122.00 MW by the Tala Hydropower Plant, followed by 792.05 MW by Mangdichu Hydropower Plant.


Table: 2.1.1 Monthly maximum and minimum generation summary

Sl. No	Hydropowe	r Plant				1	Monthly Max	imum and N	Iinimum Ge	neration (M	IW)				Max/Min	of year
51. 140	Hydropowe	i i iant	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	(MW	)
1	ВНР	Max	25.50	19.43	26.44	21.83	65.84	65.79	66.22	66.55	66.63	66.34	59.91	50.02	66.63	
1	БПГ	Min	6.54	14.81	2.93	4.41	4.12	0.00	24.51	2.24	0.00	47.05	4.15	8.47		0.00
2	СНР	Max	169.33	101.90	171.12	182.08	278.79	369.79	66.00	371.92	369.70	371.66	365.32	185.32	371.92	
2	CHF	Min	66.80	66.62	3.00	49.24	124.81	217.70	31.62	275.68	275.86	11.15	172.54	58.57		3.00
3	THP	Max	270.00	320.00	300.00	263.81	1,122.00	1,122.00	1,122.00	1,122.00	1,122.00	1,122.00	750.00	440.00	1,122.00	
3	IHF	Min	130.00	70.00	60.00	27.60	270.00	430.00	360.00	100.00	100.00	280.00	240.00	130.00		27.60
4	КНР	Max	31.68	31.15	64.49	60.33	66.18	66.00	66.00	66.00	66.00	66.00	60.62	45.33	66.18	
7	KHI	Min	10.13	10.11	11.09	10.08	31.58	12.67	31.62	30.23	16.50	48.26	27.97	10.46		10.08
5	DHP	Max	27.72	26.66	40.29	25.02	126.92	127.47	95.10	100.70	100.79	100.70	52.27	40.03	127.47	
3	DHF	Min	19.19	1.23	9.75	11.06	17.16	0.00	5.50	1.13	40.30	48.74	31.31	23.06		0.00
6	МПВ	Max	144.91	179.50	264.71	357.70	792.05	594.06	594.16	790.86	790.56	789.00	441.67	363.67	792.05	
0	6 MHP	Min	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00		0.00


Graph: 2.1.1 Basochhu generation summary




Graph: 2.1.3 Tala generation summary




Graph: 2.1 Chhukha generation summary




Graph: 2.1.4 Kurichhu generation summary



Graph: 2.1.5 Dagachhu generation summary



Graph: 2.1.6 Mangdichu generation summary



#### 2.2 PLANT FACTOR

The plant factor of each generating plant was calculated as below:


= (Actual output of a plant over a period of time) / (Output when operated at name plate rated capacity for Plant factor entire time)

> = (Total energy plant has produced over a period) / (Total energy plant would produce when operated at *full rated capacity)*


Table: 2.2.1 Monthly plant factor of the hydropower plants

CI No	Hydropowe						Monthly 1	Plant Factor	r (%)					Max/Min of year	
Sl. No	r Plant	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	Max	Min
1	ВНР	33.23	24.23	23.77	20.76	37.81	62.00	102.32	99.48	99.64	93.84	69.92	45.04	102.32	20.76
2	СНР	27.96	20.74	24.45	25.97	65.93	96.71	19.33	108.76	105.64	99.04	70.17	43.78	108.76	19.33
3	THP	18.14	14.12	16.23	13.04	56.25	82.38	78.63	96.48	87.56	78.47	45.41	28.10	96.48	13.04
4	KHP	34.63	26.87	39.37	43.86	97.93	102.30	108.23	106.79	101.73	105.07	64.16	45.25	108.23	26.87
5	DHP	18.18	13.44	13.92	11.58	32.59	56.93	93.50	86.62	81.25	64.58	44.39	28.29	93.50	11.58
6	MHP	0.00	0.12	11.92	0.00	56.25	0.00	0.00	25.68	28.08	30.75	23.93	31.55	56.25	0.00


Graph: 2.2.1 Plant factor of Basochhu Hydropower Plant




Graph: 2.2.2 Plant factor of Chhukha Hydropower Plant




Graph: 2.2.3 Plant factor of Tala Hydropower Plant





Graph: 2.2.4 Plant factor of Kurichhu Hydropower Plant



Graph: 2.2.4 Plant factor of Dagachhu Hydropower Plant







### 3.0 PEAK DEMAND, ENERGY AVAILABILITY AND REQUIREMENT FOR THE COUNTRY

Calculation of coincidental peak load for the eastern grid, western grid and national load, we use the following methods:

- 1. National Demand = (Sum of all total generation of each plant) (Sum of all Export/Import)
- 2. National Demand = (Sum of all feeders loading at hydropower plant) (Sum of all Export/Import)
- 3. National Demand = (Sum of all substation loading)

The national load calculated using method-3 is considered in the report.

#### 3.1 NATIONAL LOAD


The national coincidental peak load for the year was recorded 43535 MW (Increased by 16 % compare to 2020 (374.53 MW)) on December 27, 2020 at 18:02:18 Hrs. using method-2 (sum of all feeder loading at hydropower plant minus sum of export/import). The main factor contributing towards the increase in Bhutan peak load in 2021 could be because of more production by the industries numbers of new substations came up in 2020. It had been also observed that the total sale of energy to BPC is less by about 50 MU this year compare to 2018. The table below shows the coincidental peak load summary from 2007:

Year	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021
Peak Load (MW)	157.36	187.05	237.17	256.95	276.24	282.44	313.94	333.41	336.52	335.87	362.09	399.35	387.66	374.53	435.35
% Growth over previous Year	-	18.87	26.79	8.34	7.51	2.24	11.15	6.20	0.93	-0.19	7.81	10.29	-2.93	-3.39	16.24

Monthly national peak load and corresponding generation using method-3 Table: 3.1.2

				Total Gr	id (MW)	Western C	Frid (MW)	Eastern G	rid (MW)
Sl. No	Months	Date	Time	Load	Generatio n	Load	Generatio n	Load	Generatio n
1	Jan	23-Jan-21	19:00	330.32	408.90	259.39	277.62	70.93	131.28
2	Feb	6-Feb-21	19:00	321.55	363.75	248.79	258.85	2.38	104.90
3	Mar	14-Mar-21	19:00	332.75	570.68	252.60	355.78	2.52	214.90
4	Apr	14-Feb-21	19:00	320.23	372.57	251.38	219.29	1.92	153.28
5	May	6-May-21	19:00	304.53	966.50	235.12	630.70	1.69	335.80
6	Jun	28-Jun-21	22:00	362.79	1,506.50	328.00	973.60	0.99	532.90
7	Jul	2-Jul-21	20:00	302.81	1,751.05	0.71	1,317.29	103.31	433.76
8	Aug	15-Aug-21	21:00	429.77	2,280.06	16.03	1,620.83	1.26	659.23
9	Sep	2-Sep-21	19:00	345.54	2,475.19	18.38	1,619.82	2.03	855.37
10	Oct	30-Oct-21	18:00	426.92	1,562.45	0.00	1,220.36	6.73	342.09
11	Nov	7-Oct-21	18:00	391.05	1,156.09	0.00	872.44	6.50	283.65
12	Dec	26-Dec-21	18:00	435.35	700.94	65.53	405.53	16.12	295.41
Na	tional Peak	Load of the yea	r (MW)	435.35					

Graph: 3.1.2 Monthly national peak load and corresponding generation using method- 3




#### 3.2 WESTERN GRID PEAK LOAD

Using method-3, the peak load for the western grid was 46251 MW which occurred on May 23, 2021.

Table: 3.2.1 Monthly western peak load and corresponding generation

				Western C	Frid (MW)
Sl. No	Months	Date	Time	Load	Generatio n
1	Jan	4-Jan-21	19:00	299.24	378.12
2	Feb	10-Feb-21	19:00	116.08	227.77
3	Mar	4-Mar-21	19:00	328.29	406.03
4	Apr	12-Apr-21	19:00	305.60	262.65
5	May	23-May-21	21:00	462.51	1,418.90
6	Jun	19-Jun-21	11:00	326.16	1,598.14
7	Jul	22-Jul-21	6:00	269.01	195.70
8	Aug	15-Aug-21	21:00	281.43	1,620.83
9	Sep	24-Sep-21	13:00	261.28	1,326.30
10	Oct	29-Oct-21	11:00	303.81	1,174.76
11	Nov	10-Nov-21	9:00	305.34	857.05
12	Dec	19-Nov-21	22:00	329.04	414.79
W	estern Peak	Load of the year	r (MW)	462.51	

Graph: 3.2.1 Monthly western peak load and corresponding generation




#### 3.3 **EASTERN GRID PEAK LOAD**

Using method-2, the peak load for the eastern grid was 12759 which occurred on July, 2021.

Table: 3.3.1 Monthly eastern peak load and corresponding generation

genera				Eastern G	rid (MW)
Sl. No	Months	Date	Time	Load	Generatio n
1	Jan	31-Jan-21	14:00	87.73	118.31
2	Feb	5-Feb-21	19:00	75.47	105.39
3	Mar	9-Mar-21	8:00	88.62	115.66
4	Apr	21-Apr-21	19:00	57.06	157.65
5	May	3-May-21	19:00	65.04	226.39
6	Jun	13-Jun-21	7:00	68.00	657.35
7	Jul	27-Jul-21	6:00	127.59	639.17
8	Aug	17-Aug-21	4:00	119.85	659.19
9	Sep	2-Sep-21	0:00	121.56	853.38
10	Oct	21-Oct-21	5:00	69.10	647.46
11	Nov	26-Nov-21	23:00	68.60	226.97
12	Dec	1-Nov-21	4:00	70.32	212.92
Ea	stern Peak	Load of the year	(MW)	127.59	

Graph: 3.3.1 Monthly eastern peak load and corresponding generation



#### 4.0 EXPORT AND IMPORT OF ELECTRICITY TO/FROM NEIGHBORING COUNTRIES


#### 4.1 EXPORT OF ELECTRICITY TO NEIGHBORING COUNTRY

Maximum export of electricity for the year was 1,114.00MW to Binaguri substation in September, 2021, followed by 361.00MW to Birpara substation. The minimum export was 0.00 MW to Binaguri substation.


Table: 4.1.1 Monthly power export summary


<b>S1.</b> I	No Substation	n in India				M	onthly Ma	ximum and	l Minimun	a Export (I	MW)				Max/Min of year	
51. 1	Substation	I III IIIUIA	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	(MV	V)
1	Binaguri	Max	192.00	79.00	204.00	194.00	1,041.00	238.00	355.00	1,113.00	1,114.00	453.00	0.00	457.00	1,114.00	
1	Binaguii	Min	41.00	1.00	1.00	11.00	211.00	1.00	0.90	1.09	1.00	1.00	0.00	21.00		0.00
-	Divnava	Max	50.40	35.30	58.40	67.40	228.47	319.50	216.89	361.00	324.80	292.87	194.73	53.31	361.00	
	Birpara	Min	0.10	0.60	0.10	0.30	2.10	11.00	68.08	160.46	129.00	8.76	0.28	0.04		0.04
2	Salakoti	Max	14.20	11.02	32.35	33.61	106.55	165.23	109.41	102.47	99.36	48.57	50.56	23.73	165.23	
3	& Rangia	Min	1.02	0.56	0.13	0.16	0.59	16.94	29.80	9.04	7.56	0.56	0.10	0.08		0.08

Graph: 4.1.1 Monthly power export to Binaguri substation



Graph: 4.1.2 Monthly power export to Birpara substation





Graph: 4.1.3 Monthly net power export to Salakoti and Rangia substation


#### 4.2 IMPORT OF ELECTRICITY FROM NEIGHBORING COUNTRY

Maximum import of power was 116.20 MW from Birpara substation which occurred in February, 2019 followed by 89.50 MW and 75 MW from Salakoti and Rangia and Binaguri respectively.


Table: 4.2.1 Monthly power import summary

S1. N	Substation	in India				M	onthly Ma	ximum and	Minimum	Import (N	MW)				Max/Min of year	
51. IV	Substation	III IIIUIA	Jan	Feb	Mar	Apr	May	Jun	Jul	Aug	Sep	Oct	Nov	Dec	(MV	V)
1	Binaguri	Max	40.00	101.00	43.00	0.00	0.00	297.00	188.00	23.00	27.00	300.00	358.00	108.00	358.00	
1	Billaguii	Min	40.00	2.00	1.00	0.00	0.00	1.00	0.30	0.36	2.00	1.00	2.00	9.00		0.00
2	Divnava	Max	62.40	70.00	102.23	65.02	25.30	0.00	0.00	0.00	0.00	0.00	100.90	69.18	102.23	
2	Birpara	Min	0.30	0.05	0.40	0.03	1.20	0.00	0.00	0.00	0.00	0.00	0.38	0.04		0.00
2	Salakoti	Max	64.05	54.90	54.22	45.50	29.03	18.03	0.00	0.00	1.16	0.00	4.00	17.20	64.05	
3	& Rangia	Min	0.19	1.50	0.07	0.03	0.17	18.03	0.00	0.00	0.26	0.00	1.53	0.03		0.00


Graph: 4.2.1 Power import from Binaguri substation summary



Graph: 4.2.2 Power import from Birpara substation summary



Graph: 4.2.3 Power import from Salakoti and Rangia substation summary



# 5.0 FREQUENCY PROFILE: MAXIMUM AND MINIMUM FREQUENCY RECORDED AND THE FREQUENCY DURATION IN DIFFERENT FREQUENCY BANDS

As per the Grid Code Regulation 2008, Clause 6.4.1 the transmission system frequency was classified into three different bands as follows:

- 1. Normal state
  The transmission system frequency is within the limit of 49.5Hz to 50.5Hz
- 2. Alert state
  The transmission system frequency is beyond the normal operating limit but within 49.0Hz to 51.0Hz
- 3. Emergency state
  There is generation deficiency and frequency is below 49.0Hz.

We base our frequency at 220kV Bus frequency at 220/66/11kV Semtokha substation in the western grid and 132kV Bus frequency at 50Hz and Kurichhu Hydropower Plant in the eastern grid.

Table: 5.0.1 Frequency profile at Semtokha substation

220/66/11k	V Semtokha Su	ıbstation			
		220kV Bu	s Frequency	<b>Operation</b>	State (%)
Sl. No	Months	Normal	Alert	Emergenc	Blackout/
		Normai	Alert	у	Other
1	Jan	100.00	0.00	0.00	0.00
2	Feb	100.00	0.00	0.00	0.00
3	Mar	100.00	0.00	0.00	0.00
4	Apr	96.51	0.13	0.00	3.36
5	May	100.00	0.00	0.00	0.00
6	Jun	100.00	0.00	0.00	0.00
7	Jul	100.00	0.00	0.00	0.00
8	Aug	99.23	0.00	0.00	0.00
9	Sep	96.51	0.13	0.00	3.36
10	Oct	100.00	0.00	0.00	0.00
11	Nov	100.00	0.00	0.00	0.00
12	12 Dec		0.00	0.00	0.00
Operation	Operation State for the		0.02%	0.00%	0.56%
у	ear	91.02%	0.02%	0.00%	0.30%

Graph: 5.0.1 Frequency profile at Semtokha substation





Table: 5.0.2 Frequency profile at Kurichhu Hydropower plant

132kV Bus Frequency Operation State (%) Emergenc Blackout/ Sl. No Months Normal Alert Other 99.87 0.00 0.00 0.13 1 Jan 90.32 9.68 0.00 0.00 2 Feb 3 99.60 0.00 0.27 0.13 Mar 4 96.37 0.00 0.00 3.63 Apr 5 May 100.00 0.00 0.00 0.00 6 Jun 96.77 0.00 0.00 3.23 7 100.00 0.00 0.00 0.00 Jul 8 Aug 100.00 0.00 0.13 0.00 9 96.77 0.00 0.00 3.23 Sep 10 99.73 0.00 0.13 0.13 Oct 11 Nov 96.37 0.13 0.13 3.36 12 Dec 0.00 0.00 0.00 0.13 Operation State for the 89.65% 0.02% 0.06% 1.96% vear

Graph: 5.0.2 Frequency profile at Kurichhu Hydropower Plant



#### 6.0 VOLTAGE PROFILE OF SELECTED SUBSTATIONS

As the Grid Code Regulation 2008, Clause 6.4.1, the voltage at all connection points was classified into three different bands as follows:


- 1. Normal state
  - The voltages at all connection point are within the limits of 0.95 times and 1.05 times of the normal values
- 2. Alert state
  - The voltage at all connection points are outside the normal limit but within the limits of 0.9 times and 1.1 times of the normal values
- 3. Emergency state
  - *Transmission system voltages are outside the limits of 0.9 times and 1.1 times of nominal values.*

The voltage profile of 400/220/66/11kV Malbase substation in western grid and 132/33/11kV Nangkhor substation in the eastern grid are considered in the report.

Table: 6.0.1 Voltage profile at Malbase substation

400/220/	66/11kV Ma	lbase Substa	ation						
		400kV B	us Voltage	Operation S	tate (%)	220kV B	us Voltage	Operation S	tate (%)
Sl. No	Months	Normal	Alert	Emergenc		Normal	Alert	Emergenc	Blackout/
1	Jan	0.00	0.00	0.00	Other 0.00	0.00	0.00	0.00	Other 0.00
2	Feb	89.78	0.54	0.00		90.05	0.00	0.27	9.68
3	Mar	98.39	1.61	0.00	0.00	100.00	0.00	0.00	0.00
4	Apr	96.10	0.27	0.00	3.63	92.07	4.44	0.00	3.49
5	May	100.00	0.00	0.00	0.00	99.87	0.13	0.00	0.00
6	Jun	96.77	0.00	0.00	3.23	96.51	0.27	0.00	3.23
7	Jul	98.12	1.61	0.27	0.00	100.00	0.00	0.00	0.00
8	Aug	0.00	0.00	0.00	0.00	100.00	0.00	0.00	0.00
9	Sep	96.77	0.00	0.00	3.23	96.77	0.00	0.00	3.23
10	Oct	100.00	0.00	0.00	0.00	100.00	0.00	0.00	0.00
11	Nov	70.97	14.52	0.27	14.25	96.77	0.00	0.00	3.23
12	Dec	93.95	0.00	0.00	0.06	100.00	0.00	0.00	0.00
-	on State for	78.41%	1.55%	0.04%	2.84%	89.34%	0.40%	0.02%	1.90%
y	ear								


Graph: 6.0.1 Voltage profile at Malbase substation at 400kV bus




Voltage profile at Nangkhor substation Table: 6.0.2

		132kV B	us Voltage	Operation S	tate (%)
Sl. No	Months	Normal	Alert	Emergenc	Blackout/
		Normai	Alert	y	Other
1	Jan	100.00	0.00	0.00	0.00
2	Feb	90.32	0.00	0.00	9.68
3	Mar	99.33	0.00	0.00	0.67
4	Apr	94.89	4.97	0.00	0.13
5	May	97.18	2.82	0.00	0.00
6	Jun	96.77	0.00	0.00	3.23
7	Jul	100.00	0.00	0.00	0.00
8	Aug	0.00	0.00	0.00	0.67
9	Sep	92.74	0.13	0.00	7.12
10	Oct	99.87	0.00	0.00	0.13
11	Nov	96.77	0.00	0.00	3.23
12	12 Dec	0.00	0.00	0.00	0.00
•	Operation State for vear		0.66%	0.00%	2.07%

Graph: 6.0.2Voltage profile at Malbase substation at 220kV bus



Graph: 6.0.3 Voltage profile at Nangkhor substation



#### 7.0 MAJOR GENERATING AND TRANSMISSION OUTAGE

The summary of the major transmission outages for the eastern grid and western grid are attached as Annexure- I and Annexure- II respectively.

The outages of transmission line or transformer or any power system equipment below 66kV, tripping/outage of less than 30minutes and planned shutdown which do not cause supply interruption to the customers are not reflected.

#### 8.0 TRANSMISSION CONSTRAINTS

There are no instant of transmission constraints during normal condition in Bhutan Power System.

9.0 INSTANCES OF PERSISTENT OR SIGNIFICANT NON-COMPLIANCE WITHIN THE GIRD CODE REGULATION The instance of non-compliance with the Grid Code Regulation 2008 for the year 2019 was not recorded.

## Annexure- I

# **Eastern Grid Outages** January 2021

Tripping	Report for the	of month Ja	nuary, 2021 unde	er SMD Deo	thang Subst	ation, TD,E	BPC						
SI, No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	MU Lost during outages	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Remarks
	3/11kV Kilikhar	Substation			10 400000 1	- 11 Str - 1 St			6			I sossowean	
132kV I	Feeder								210 000	20010			
1	3/11kV Kanglin	- Outomator							NO TRI	PPING			
	Feeder(No Tripp												
	3/11kV Deothar												
	2kV Feeder												
1	25.01.2021	8:30	25.01.2021	17:20	8	11.916		132kV Motonga	Motanga Line	NA	Nil	DR fdr between Deothang- Matonga	As per Approved order REF/MSG No.10A/BPC/BPSO/PSOD/Vol- 1/2021/09, dated 21/01.2021. Code No 0050 by Madham Tshering Yangzom, BPSO. Thimphu dated 25.01.2021. (Breaker, both isolator open and Earth switch closed done). Charge the fdr with closing code:1189(Tshering Yangzom BPSO) and found normal. As per Approved order REF/MSG No.10A/BPC/BPSO/PSOD/Vol-
2	26.01.2021	8:30	26.01.2021	14:43	6	9.11		132kV Motonga	Motanga Line	NA	Nil	DR fdr between Deothang- Matonga	1/2021/09, dated 21/01.2021. Code No 0054 by Miss Tshering Choden, BPSO, Thimphu dated 26.01.2021. (Breaker, both isolator open and Earth switch closed done). Charge the fdr with closing code:1191(Karma BPSO) and found normal.
3	27.01.2021	8:10	27.01.2021	15:19	7	6.948		132kV Motonga	Motanga Line	NA	Nil	DR fdr between Deothang- Matonga	As per Approved order REF/MSG No.10A/BPC/BPSO/PSOD/Vol. 1/2021/09, dated 21/01.2021. Code No.0059 by Miss Tshering Choden, BPSO, Thimphu dated 27.01.2021. Breaker, both isolator open and Earth switch closed done). Fdr charged with closing code 1198. Yshering Choden BPSO, frd found normal
	3/11kV Nangkh	or substation	l,	().	11	2	30 /	W .	S	98	107 13	N.	
132	2kV Feeder 16.01.2021	07:19hrs	16.01.2021	07:23hrs	0	0.35		5MVA Trf- II,132/33kV	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A,51A,50C,51C & tripping relay 86 operated.	Nangkor Substation	Tripped while test charging 33kV Wamrong Feeder.
2	26.01.2021	14:10 hrs	26.01.2021	16:02 hrs	1	2.34		Nangkor-Nganglam	Nangkor-Nganglam line	NA	\$ <del>9</del>	Nganglam Sunstation	Y phase Disc Insulator decapped/punctured at Nganglam Substation. Closed the CB with closing code-1193 from BPSO, Thimphu.
	7						7						
5. 132/3	33/11kV Ngangl	am substatio	n										
	3								NO TRIPPI	NG	-	ī	
1	26.01.2021	14:14	26.01.2021	16:03	1	-2.15		Nangkhor-Nganglam	Nangkhor-Nganglam	Suspension Inulator for Y-Phase got Punctured and Jumper got Touch with Structure		Substation	Y-Phase Suspension Insulator got Punctured and Jumper has touched with tower Structure is Emergency CB hand trip was done to avoid any other demages to Line-lequipments and informed to BPSO regarding the matter. Supply was restored after replacing of broken Insulator with Switch ON code# 1193 issued by Miss Thsering Yangzom, BPSO
1	21.12.2020	14:39	21.12.2020	15:14	0	-7.2		Gel-Sal	non	Temporary fault	ip,YB-Ph,Zone -1,di	Salakati line	
											1		

# February 2021

Trippin	ng Report for th	e of month Feb	ruary, 2021 und	ler SMD Deo	thang, TD,I	вРС						
Sl. No.	Date of Tripping	Time of outages	Date of Normalizatio n	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Remarks
	33/11kV Kangle Fooder(No Trip		W 8		S			2	#	2	;	V
1	07.02.2021	16:02	07.02.2021	18 10	2:00	2,232	Phuotshothang	Phuntshothang	Breaker failler	Distanc realey oppt.	Kanglung ss	Testcharge done once but tripping with same fault due to braker problem.but supply was feeded through transfer bucCharging code 1267.Again min breaker charging code 1268.Transfer bus oppening code 0117.
	33/11kV Nangki 2kV Foodor	hor substation										
1	03.02.2021	15:08 hrs	03.02.2021	16:44 hrs	1	0.44	132/33kV, 5MVA Trf-1	132/33kV, 5MVA Trf-I	NA		Nangkor Substation	Emergency slut down taken by Substation incharge to attend oil leakage. No supple was interrupted.
2	25.02.2021	13:20 hrs	25.02.2021	13:41 hrs	0	0.45	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	Tripped on fault	Non directional IDMT O/C-50A,51A, 50C, 51C & tripping relay 86 operated	Nangkor Substation	Tripped due to fault on 33kV Yurung feeder.
3	25.02.2021	13:20 hrs	25.02.2021	13:41 hrs	0	0.27	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	Tripped on fault	Non directional IDMT O/C-50A,51A, 51C, & tripping relay 86 operated	Nangkor Substation	Tripped due to fault on 33kV Yurung feeder.
	/33/11kV Ngang											
	Feeder Feeder	dam substation										
1		19:19	28 02 2021	19:21	0	1.66	SMVA Transformer	3MVA Transformer	Over Current Earth Fault	O/C & E.F 86opted	33kV Dechenling feeder	Tripped due to 33kV Dechenling feeder fault
6.	132kV Morang	a substation				4/				· · · · · · · · · · · · · · · · · · ·		
1	2/1/2021	14:23 hrs	2/1/2021	14:26 hrs	0.5	0.05	15MVA xmer-I	3	Tripped on Fault	86A optd	Motanga ss	CB tripped while charging of transformer at Azista end informed BPSO and charged transformer at 14:26 hrs from our end.
2	2/7/2021	16:00 hrs	2/7/2021	16:10hrs		-8.5	Deothang fdr incomer	_	Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	Informed BPSO, with code no.1260 CB classed at 16:10hrs from our end.
3	2/7/2021	16:00 hrs	2/7/2021	16:26hrs	6¥3	-15.39	Motanga-Rangia fdr	9	Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	Informed BPSO,with code no.NLDC Bht.1262,NLDC India 702,NERLDC 7644 C8 . closed at 16:26hrs from our end.
4	2/7/2021	16:00 hrs	2/7/2021	17:12hrs	1	-1.68	Motanga-Phuntshothang fdr		Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	informed BPSO, with code no. 1265 CB closed at 17:12hrm from our end.
1. 400/ Sl. No.	Tripping	Time of Outages/ Time of Time of Tripping	Date of Normalizatio	Time of Fault was Cleared	Duration of Outages (Hrs)	MW before Outage (MW)	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Remarks
1) 400%		T			_				100	Main-1 = R.Y&Bph -Ground Pickup and		
1	08.02.2021	14:37lus	08.02.2021	14:46hrs	0	101.08	MHPA line 2	Alipurduar SS	Line-Earth Fault		Main 1 - 82.8km Main 2 - 82.3km	
2	14.02.2021	11:19 hrs	14.02.2021	12:56 hrs	- 1		Alipur CKT1	Alipurduar SS	Line-Earth Fault	RYB phase pick up, DTT Tripped		
3	20.02.2021	14:06 hrs	20.02.2021	14:24 hrs	0	93.96	MHPA line 3	Alipurduar SS	Line-Earth Fault	Main-1 - Rph pickup, DTT trip, Main- 2 - Rph pick up	Main 1 = 78.8km Main 2 = 77.8km	
ff) 220	ky and 132 kV											
1	28.02,2021	5:09:03hrs	28.02.2021	5:32:18hrs	0	9.79	Tsirang-Jigmeling	Dhajay and Jigmeling substation	phase to phase fault	Main-I Rph=2.021KA, Yph=2.032KA, Bph=0.04KA, and Main-II Rph=2053.86ph, Yph=2032.70KA, Bph=36.27KA, FOR BOTH ZONE-I(Z1) OPTD.	Main-I=4.1KM, Main- II=3.41KM	breaker at our end is closed first then only breaker at jigmeling end is closed.

. No.	Date of Tripping	Time of outages	Date of Normalizatio n	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Remarks
	3/11kV Deotini kV Fooder	ng Substation				(a						
1	1.03.2020	15:01	1.03.2020	15:33	.0	17.28	132kV Deothang- Nangkhor	Deothang-Nangkhor line	NA	Nil	Nangkor s/s	Incomer triped with opening code 0229 & breaker closed closing code 1272 by Tshering Choki
2	6.03.2021	12:58	06.03.2021	13:11	0	8.028	132kV Deothang- Nangkhor	Deothang-Nangkhor	NA	Nil	Unknown	Grid fail, at our end all breaker are in normal condition ,at 13:1 supply resumed from Motonga SS. Deothang breaker kept opened at Deothang substation.
3	6.03.2021	12:58	06.03.2021	13:11	0	8.028	132kV Deothang-Motanga	Deothang-Motanga	NA	Nil	Unknown	Grid fail, at our end all breaker are in normal condition at 13:1 supply resumed from Motonga SS.
4	06.03.2021	12:58	06.03.2021	16:24	3	-9.252	132kV Deothang- Nangkhor	Deothang-Nangkhor	33/11kV 2.5MVA Transformer blast	NA	Nangkor s/s	Emergency shut down taken by Nangkor S/S since both 33/11kV 2.5MVA Transformer got blast. Availed through phot by BPSO and Nangkor substation Head.
5	30.03.2021	20:22	30.03.2021	20:25	0	26.49	132 kV Doethang-Motonga	Deothang-Motonga	NA	Nill		Emergency shut down by BPSO Tshering Yangzom openong code 0334 due to low Voltage system in estren grid. Cahrged v closing code 1901 BPSO Jangchub
	3/11kV Naugkh kV Feeder	or substation										
1	05.03.2021	18:43 hrs	05.03.2021	19:09 hrs	0	1.13	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A/50C & tripping relay 86 operated	Nangkor Substation	Tripped while test charging 33kV Nanung feeder
2	05.03.2021	18:43 hrs	05.03.2021	18:48 hrs	0	0.85	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A/50C & tripping relay 86 operated	Nangkor Substation	Tripped while test charging 33kV Nanung feeder
3	06.03.2021	12:56 hrs	06.03.2021	16:25 hrs	3	-7.89	Nangkor-Nganglam	Nangkor-Nganglam line	NA	-	Nangkor Substation	Emergency hand trip requested from our end and same was informed to BPSO, Thimphu. Due to 2.5MVA Transformer fi incident
4	06.03.2021	12:57 hrs	06.03.2021	16:36 hrs	3	-4.89	Kurichu-Nangkor	Kurichu-Nangkor line	NA		Nangkor Substation	Emergency hand trip requested from our end and same was informed to BPSO, Thimphu. Due to 2.5MVA Transformer fi incident
5	06.03.2021	12:58 hrs	06.03.2021	16:24 hrs	3	11.94	Nangkor-Deothang	Nangkor-Deothang line	NA	-	Nangkor Substation	Emergency hand trip requested from our end and same was informed to BPSO, Thimphu. Due to 2.5MVA Transformer for incident
6	06.03.2021	12:50 hrs	08.03,2021	16:23 hrs	51	0.21	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	NA		Nangkor Substation	Due to 2.5MVA Transformer fire incident
7	06.03.2021	12:50 hrs	08.03.2021	14:35 hrs	49	0.85	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	NA		Nangkor Substation	Due to 2.5MVA Transformer fire incident
. 132/	33/11kV Ngangl	lam substation			-		-		en e	Sa. 2		-
1 1	02.03.2021	14:30	02.03.2021	14-35	0	0.58	3MVA transformer-II	3MVA transformer-II	Over current	O/C 86cpted	Dechenling Feeder	Trip due to 33kV Decheling feeder fault.
2	05.03.2021	16:42	05.03.2021	16.45	0	0.856	3MVA transformer-II	3MVA transformer-II	Over current	O.C 86opted	Dechenling Feeder	Trip due to 33kV Decheling feeder fault.
3	05.03,2021	12:52	06.03.2021	16:25	3	11.19	Nengkhor-Ngnaglam	Nangkhor-Ngnaglarn	Earth Fault	E/F opted, 86 optd	Nangkhor-Nganglam	Fault Value, IA= 180.0A IB= 191.1A IC= 885.9 IN= 529.8A, VAN=65.28kV VBN=65.38kV VCN=19.26kV. The feeder was normalised as per the Switch ON code# 1592 convey by Miss Tshering Vangarm, BPSO Thimpha.
ky F	eeder	substation										
1	3/6/2021	12:58 hrs	3/6/2021	13:10 hrs		-13.83	Deothang fdr incomer		Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	Informed BPSO, as per there instruction CB closed at 13:10hrs from our end.
2	3/15/2021	05:43 hrs	3/15/2021	05:48hrs	2	0.05	15MVA Xmer	<u> </u>	Tripped on Fault	O/C at our end	Motanga ss	CB closed at 5:48hrs from our end.
3 4	3/15/2021	14:49 hrs 23:36hrs	3/15/2021	15:28hrs 23:59hrs	-	8.81	33kV Azista Motanga-Rangia fdr	*	Hand tripped Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss Motanga ss	Taken shutdown by DCSD for maintenance work at Azista end. Informed BPSO, as per there instruction CB closed at 23:59hrs with code NLDC is
-	20/132/33kV Ji	0.717.000.001.00		1 (majore to 10 mc				-			(0.000-0.000)	1906,NLDC India-2137 and NERLDC-11175 from our end.
. No.	Date of Tripping	Time of Outages/ Time of Tripping	Date of Normalizatio n	Time of Fault was Cleared	Duration of Outages (Hrs)	MW before Outage (MW)	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Remarks
1	44276	12:12 hrs	44276	12:22 hrs	0 hrs	138.17 MW	MHPA Line 4	Alipurdwar substation	DTT trip while opening line Alipur Ckt 2 at their end	DTT trip		
	3/11kV Tintibi S and Above	Substation										
	44261.00	0.51	44261.00	0.55	0.00	23.76	132kV Tingtibi-Nanglam	132kV Tingtibi-Nanglam	Tempoary fault	Distance Protection Relay:Trip phase ABC,Fault Loaction: 119.4kM,Fault Zone-3.	132kV Tingtibi-	

il. No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
132/33 32kV F	11kV Kilikbar	Substation											
	eeder 30.04.2021	16-50	30.04.2021	17:06		-13.75	132kv kurichu	All feeders	NA	Nill	kurichu end	trip	Line tripped from kurichu end, all unit are trip due to under voltage.
-1	30.04.2021	10.07	30.04.2021	17.00		-13.70	132KV KUI ICHU	All leeders	1 00	I INIII	Kut lend end	usp	Time tripped from kuricus end, an unit are trip one to succe vottage,
. 132/33	7/11kV Kanglun	g Substation	ĥ										
32kV F	eeder	3											2
1	01.04.2021	14:30	1.4.2021	14:34	0:04	-7.182	Corlung	Kanglung	E/F	E/F	Corlung Line	Tripped on fault	Line Tripped due to Lightening
2	07.04.2021	21:14	07.04.2021	21:17	0:00	-12.168	Corlung	kanglung	O/c	ole	Corlung Line	Tripped on fault	line tripped due to over current at our end ,due to heavy rainfall with thunderin &lightinning
3	28.04.2021	17:03	28.04.2021	17:13	0:00	-11.412	Corlung	kanglung	O/C & E/F	O/C & E/F relay operated Ir-27.56A, Iy-801.8A, Ib- 720.2A. Distance relay operated with Zone 1, at 17.88KM	Corlung Line	Tripped on fault	fdr normalised after getting clearence from ms. Karma, (engg), BPSO, At 17:1 hrs.
4	28.04.2022	17:03	28.04.2021	17:14	0:00	9.756	Phuntshothang	Kanglung	NA	snce relay zone 1 ope	Phuntshothang line	Tripped on fault	fdr normalised after getting clearence from ms. Karma, (engg). BPSO. At 17:14hrs.
5	28.04.2021	17:43	28.04.2021	17:45	0:00	-11.412	Corlung	kanglung	O/C & E/F	O/C & E/F relay operated Ir-570.8A, Iy-57.85A, Ib- 621A. Distance relay operated with Zone 2, at 25.71KM		Tripped on fault	fdr normalised after getting clearence from ms. Karma, (engg). BPSO. At 17:45 hrs.
6	28.04.2021	17:43	28.04.2021	19:56	2:00	9,756	Phuntshothang	Kanglung	NA	unce relay zone 1 ope	Phuntshothang line	Tripped on fault	fdr normalised after getting clearence from ms. Karma, (engg). BPSO with charging code 2050
7	30.04.2021	16:55	30.04.2021	17:16	0:00	-10.872	Corlung	kanglung	0/C & E/F	O/C & E/F relay operated IA- 32.78A, IB-72.53A, IC-797.6A. VAB- 134.1kV,VBC- 81.7kV,VCA- 77.9kV. Distance relay operated with Zone 1, at5.586KM,IA- 32.71A,IB- 72.2A,IC- 822.3A,VAN- 78.66kV,VBN- 5.706kV	Corlung Line	Tripped on fault	Feeder normalised after getting clearence from BPSO.
8	30.04.2021	16:55	30.04.2021	17:16	0:00	9.486	Phuntshothang	Kanglung	NA	NA	Phuntshothang line	Tripped on fault	Feeder normalised after getting clearence from BPSO.

	3/11kV Nangkh	or substation											
132	kV Feeder					175	N 80			V	yr.		
1	04.04.2021	18:43 hrs	04.04.2021	19:57 hrs	0	0.84	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Tsebar feeder
2	04.04.2021	18:43 hrs	04.04.2021	18:47 hrs	0	0.61	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Tsebar feeder
3	04.04.2021	19:33 hrs	04.04.2021	19:37 hrs	0	0.46	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Tsebar feeder
4	04.04.2021	20:50 hrs	04.04.2021	21:03 hrs	0	11.7	Nangkor-Deothang	Nangkor-Deothang line	Tripped on fault	Non directional E/F,O/C relay & tripping relay 86 operated	Nangkor-Deothang line	Tripped on fault	Start Ø CN, Trip Ø N. O/C start I>1, E/F start IN1>12, trip IN1>2. IA-60.16A IB-52.54A,IC-404.0A, IN measured-353.5A. Informed to BPSO, and charged the feeder with instruction from BPSO.
5	10.04.2021	20:53 hrs	10.04.2021	21:06 hrs	0	35.7	Nangkor-Deothang	Nangkor-Deothang line	Tripped on fault	Non directional E/F,O/C relay & tripping relay 86 operated	Nangkor-Deothang line	Tripped on fault	Sturt Ø CN, Trip Ø N, O/C start I>1, E/F start INI>12, trip INI>2, IA-102.4A IB-100.9A,IC-447.5A, IN measured-361.4A. Informed to BPSO, and charged the feeder with instruction from BPSO.
6	14.04.2021	04:32 hrs	14.04.2021	14:50 hrs	0	0.39	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	NA	Non directional IDMT O/C Relay- 50A,50C & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Due to fault on 33kV Tsebar feeder.
7	16.04.2021	15:58 hrs	16.04.2021	16:03 hrs	0	0.42	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A,50C & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Yurung feeder
8	16.04.2021	15:58 hrs	16.04.2021	16:03 hrs	0	0.24	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A,50C & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Yurung feeder
9	22.04.2021	02:26 hrs	22.04.2021	02:40 hrs	0	0.38	132/33kV, 5MVA Trf-I	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A,50C & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Namung feeder & Namung Feeder
10	22.04.2021	02:26 hrs	22.04.2021	02:40 hrs	0	0.43	132/33kV, 5MVA Trf-II	All 33kV & 11kV feeders	Transient fault	Non directional IDMT O/C Relay- 50A,50C & tripping relay 86 operated	Nangkor Substation	Tripped on fault	Tripped due to fault on 33kV Nanung feeder & Nanung Feeder
11	28.04.2021	00:03 hrs	28.04.2021	00:26 hrs	0	24.1	Nangkor-Deothang	Nangkor-Deothang line	Tripped on fault	Non directional O/C.E/F Relay & tripping relay 86 operated	Nangkor-Deothang line	Tripped on fault	Start Ø CN, Trip Ø N. O/C start I>1, E/F start INI>12, trip INI>2. IA-100.2A IB-96.92A,IC-467.9A, IN measured-391.2A. Informed to BPSO, and charged the feeder with instruction from BPSO.
12	28.04.2021	08:23 hrs	28.04.2021	09:58 hrs	1	0.24	132/33kV, 5MVA Trf-II	132/33kV, 5MVA Trf-II	Tripped on fault	Aux-Relay Diff/ref 87x,64x, 30CWDG temp. Alarm, 30D Buch. Alarm & tripping relay 86 operated	Nangkor Substation	Tripped on fault	No supply interrupted. Tripped due to Shake of Earth Quake, Charged the Xm after inspection.
13	30.04.2021	16:03 hrs	30.04.2021	16:15 hrs	0	28.6	Nangkor-Nganglam	Nangkor-Nganglam line	Tripped on fault	Directional O/C,E/F & tripping relay 86 operated	Nangkor-Nganglam line	Tripped on fault	Directional O/C & E/F & trip relay 86 operated at our end: Start phase BN, trip phase N, O/C start I>1, E/F start E/F INI>12, trip INI>2, IA-78.17A, IB-670. IC-141.2A, VAB-109.8kV, VBC-107.3kV, VCA-130.5kV, VAN-72.7kV, VBS 53.08kV, VCN-74.15kV, VN-0.00, 49.98Hz,IN measured-456.0A, IN derieve 455.8A. Informed to BPSO & charged the feeder as per their instruction.
14	30.04.2021	16:57 hrs	30.04.2021	17:04 hrs	0	28.6	Main Grid	All 33kV & 11kV feeders	37		Motonga Substation & Tintibi Substation	Tripped on fault	Supply failed from Motonga Substation and Tintibi Substation and received from Motonga Substation.

6	132kV Motanga	whstation					_						
1	4/4/2021	20:53 hrs	4/4/2021	20:58 hrs		-10.5	Deothang fdr income		Tripped on Fault	86A & 86B OPTD,OC/EF at	Motanga ss		Informed BPSO,as per there instruction by Karma Yangzom without clossing
2	4/8/2021	10:15 hrs	4/8/2021	13:52hrs	3	0.1	15MVA Xmer	-	Careensess	oue end	0.07.500000000000	(	code CB closed at 20:58hrs from our end as emergency.  Informed BPSO and CB closed at 13:52hrs from our end.
- 2	4/8/2021	10:15 mrs	4/8/2021	13:52hrs	3	0.1	15MVA Amer	-	Hand tripped	86A & 86B	Motanga ss	=	Informed BPSO and CB closed at 13;52hrs from our end.
3	4/10/2021	20:52 hrs	4/10/2021	21:01hrs	E2.	-34.5	Deothang fdr Income	=	Tripped on Fault	OPTD,OC/EF at oue end	Motanga ss	==	Taken shutdown by DCSD for maintenance work at Azista end.
4	4/11/2021	08:02hrs	4/11/2021	08:40hrs	<u> </u>	0.02	33kV POP Factory	2	Hand tripped	2	Motanga ss	121	Shutdown taken by DCSD S/Jongkhar to replace Fuse at there end.
5	28/04/201	08.25hrs	28/04/201	09.22hrs		-22.47	Deothang fdr Income	5	Hand tripped	=	Motanga ss	=	Informed BPSO, Thimphu as instructed to closed CB with code no. 2046 CB closed form our end at 09:22hrs.Due to heavy earthquake all isolators alignment was slightly gone out and Rangia main isolator and line isolator and Phuntshothang line isolator got burnt. So firstly control the fire at isolators by hand tripping CB for Deothang,Rangia and Phuntshothang feeders and than we the staffs physically check all the structures and alignment for all bays.manually closed all isolators to confriend fully closed and inform BPSO to charge the line.
6	28/04/201	08.25hrs	28/04/201	13.07hrs	4 hrs	6.11	Motanga-Rangia line		Hand tripped	<u> -</u>	Motanga ss	-	Informed to BPSO, Thimphu as instructed to closed CB with code no.NLDC Bht-2047,NLDC India-1349,NERLDC -1875 CB closed from our end at 13:07hrs.Due to earthquake main isolator and line isolator alignment gone out and got burnt .informed maintenance team at Deothang and done all alignment works both for Rangia and Phuntshothang isolators and both line charged from our end.
7	28/04/201	08.25hrs	28/04/201	13.26hrs	5 hrs	-8.97	tanga-Phuntshothang	line	Hand tripped	9	Motanga ss	-2-	Informed BPSO, Thimphu as instructed to closed CB with code 2048 from our end at 13:26hrs. Due to earthquake isolator s got burnt and informed maintenance team and after completing alignment works only line charged from our end.
8	28/04/201	17.04hrs	28/04/201	17.16hrs		-8.96	tanga-Phuntshothang	line	Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	-	Informed BPSO and closed the CB from our end at 17:16hrs from our end.
9	28/04/201	17.39hrs	28/04/201	17.45hrs		-8.96	tanga-Phuntshothang	line	Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss		Informed BPSO and closed the CB from our end at 17:45hrs from our end.
10	30/04/201	16.55hrs	30/04/201	17.04hrs		-26.9	Aotanga-Deothang lin	ne	Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	-	Informed BPSO and closed the CB from our end at 17:04hrs from our end.
11	30/04/201	16.55hrs	30/04/201	17,05hrs		-6.47	tanga-Phuntshothang	line	Tripped on Fault	86A & 86B OPTD,OC/EF at oue end	Motanga ss	181	Informed BPSO and closed the CB from our end at 17:05hrs from our end.
	2/33 kV Corlung	substation				100	10			N SAME SHOWS			
1 1 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	30.04.2021	16:58 hrs	30.04.2021	17:04 hrs	0	9.57	132 Khilihar- Corlung line and 132 kV Corlung- Kanglung Line	132 Khilihar- Corlung line and 132 kV Corlung- Kanglung Line, 132kv Corlung Substation and 33 kV T/Yantse Fedeer	Incoming supply fail	NA	Kurichhu Supply fail	Grid fail	At 14:58 hrs Incomming supply from khilikar substation fail and Corlung substation was blekout but no breaker tripping has occoured at Corlung substation.
7, 132 132kV I	2/33 kV Phuntsh Feeder	othang subst	ation										
1	1/04/2021	14:20	4/1/2021	14:47		7.02	Kanglung Line	Kanglung line	Zone one Distance Relay Trip for Kanglung s/s	86A and 86B	Kanglung Line	Trip	Kanglung s/s zone one distance relay trip
2	7/04/2021	21:09	4/7/2021	21:17		10.50	V incomer Kanglung	Kanglung Line	10PTD (R,Y,B Phas	89A and 89B	Kanglung Line	Trip	Zone-1 OPTD R,Y,B Phase trip
3	28/04/2021	17:03	4/28/2021	17:24		9.39	KANGLUNG LINE	Kanglung Line	Zone one Distance Relay Trip for Kanglung s/s	86A and 86B	Kanglung Line	TRIP	Kanglung s/s zone one distance relay trip
4	28/04/2021	17:42	4/28/2021	19:59	2	9.39	KANGLUNG LINE	Kanglung Line	10PTD (R,Y,B Phas	89A and 89B	Kanglung Line	TRIP	Zone-1 OPTD R,B Phase trip
5	30-04-21	16:55	4/30/2021	17:15		11.03	KANGLUNG LINE	Kanglung Line	zone -1OPTD(B Phase trip) and over voltage	89A and 89B	Kanglung Line	TRIP	Zone-1 OPTD B Phase trip(grid fail)

400k	7					-			T				
1	22.04.2021	12:44 hrs			0	64.1MW	MHPA Line-2	Jigmeling	DTT trip. RYB			Transient Fault (Lightening and	
	22.04.2021	12:44 108			0	04.11/1W	MITIPA LIBE-2	Substation	phase Tripped.			(Lightening and thundering)	
									2020000000000000			Transient Fault	
2	30.04.2021	02:50 hrs	30,04.2021	14:57 hrs			Shunt Reactor-1		Rphase- Ground			(Lightening and	
===	0-000/19/7/10/83	5000550000	Contribution (C.	cotto-sate (c					neult			thundering)	
_												1	
	v and 132 kV	10.301	10012021	10.425		1000 1 20 st	dos des comes e a			FORT FART T. C.	1		
1	10.04.2021	19:28hrs	10.04.2021	19:42hrs		ICI-1 30.41	80MVA ICT1 & 2	Jigmeling s/s		50N/51N Trip, (In=0.53kA,Ib=0kA			
									10100000000000000000000000000000000000	Ic-0 kA for ICT 1).		Transient (lightning	
									LV SEF optd	50N/51N Trip,		and thundering	Both ICT1&2 Trip at the sametime.
										(In=0.54kA,Ib=0kA		110000000000000000000000000000000000000	
										Ic=0 kA for ICT 2)			
2	22.04.2020	12:02hrs	22.04.2021	01:45hrs	- 0	12.99MW	Tsirang Feeder	Jigmeling s/s		50N/51N pick up,		2577420000000000000	
									Earthfault(12-E)	L2E phase tripped, main 1 operated.	dist. 23.4km	Transient (lightning and thundering	
										dist. 23.4km		and tousdering	
3	22.04.2021	12:23hrs	22.04.2021	12:23hrs		1.13MW	Dagapela Feeder	Jigmeling s/s		Y&Bphase tripped,			
									Line Fault	zone 1 optd. Dist.	Dist. 21.68km	Transient (lightning	
										21.68km		and thundering	
4	30.04.2021	15:26hrs	30.04.2021	15:34hrs	0	29.33		Jigmeling &		main 1 = Relay			
							Gelephu Line	Tingtibi	Ground fault	General Trip and R	Distance -65.9km	Transient	
										& Y phase with			
				_						ground fault trip.			
220/6	6/33kV Dhajay	Substation											
66kV	and above												
- 1	22.04.2021	00:01:50hrs	22.04.2021	1:46:30hrs	- 1	13.3	Jigmeling feeder	Dhajay SS	main I-Ia-0.47KA,	, ∏86.1 &2, Distance r	e Main I–16.8km, Ma	ii Tripped	whole Tsirang is black out as line couldnot extand from Jigmeling since the
								111111111111111111111111111111111111111					VIPORTAGE AND TO THE PROPERTY OF THE STATE O
132/6	6/33/11kV Gele	phu Substati	Dill :					-					
	and above							ge ve					
1	04.04.2021	17.22hrs	04.04.2021	18.24hrs		6.6	132kv Sal-Gel	132kv Sal-Gel	bed weather	_B=1606.46A,C=1.3	Salakati line		Charging Code; NLDC BTN=1927, NLDC IND=191 & NERLDC=23
2	04.04.2021	17.22hrs	05.04.2021	13.00hrs	19	2	132kv Gel-Jig	132lev Gel-Jig	bed weather	no relay opperated	132kv Gel-Jig		Charging Code; BPSO=1929
2017	200000000000000000000000000000000000000	Tax reserve		September		.10	10/20/00/20/00/20	South Caroline III. El.	10/10/2004 (20/2004)	at our end	000000000000000000000000000000000000000		
										Dist protection, REL			
										670,General			
3	08.04.2021	03.48hrs	08.04.2021	04.18hrs		3.4	132kv Sal-Gel	132kv Sal-Gel	bed weather	trip,RB-phase,Zone	Salakati line		Charging Code; NLDC BTN=1942, NLDC IND=423 & NERLDC=471.
										LDist.41.92km			
										towards Salakati ss.			
									1	1			
132/3	3/11kV Tintibi S	ubstation											
6 kV	and Above						6			2 5			
									Temponry fault	Distance Protection		Tempoary	
			9722223	10000		200000	132kV Tingtibi-	132kV Tingtibj-		Relay:Trip phase	Nanglam		
90	44300.00	0.10	44300.00	0.11	0.00	13.84	Nanglam	Nanglam		ABC,Foult Loaction:37.25kM,			
										Fault Zone-1.			
									Tempoary fault	Distance Protection	132kV Tingtibi-	Tempoary	
							4 0 04 04 00715 7	Contactor, and	12 SEC	Relay:Trip phase	Jigmeling	25 15	
00	44316.00	0.64	44316.00	0.65	0.00	-29.74	132kV Tingtibi-			ABC,Foult	1.5.5 M(2.5.7.7.5.7.50		
							Jigmeling	Jigmeling		Loaction:3.217kM,			
									-	Fault Zone-1.			
									Tempoary fault	Distance Protection		Тетровту	
00	44316.00	0.67	44316.00	0.00	0.00	21.12	132kV Tingtibi-	132kV Tingtibi-		Relay:Trip phase ABC,Fault	Nanglam		
<i>9</i> 0:	94210.00	0.67	44516.00	0.68	0.00	21.13	Nanglam	Nanglam		ABC,Fault Loaction:1.495kM,			
										Fault Zone-1.			
									Tempoary fault	Distance Protection	132kV Tingtibi-	Tempoary	
							****	100131001	100040000	Relay:Trip phase	Nanglam.		
00	44316.00	0.68	44316.00	0.70	0.00	4.10	132kV Tingtibi- Yurmoo	132kV Tingtibi- Yurmoo		ABC,Fault	HOUSE THE STATE OF		
							1 ucmoo	I WILLIAM		Loaction:2.756kM,			
	****	4014044000							1	Fault Zone-1.			
	3kV Yurmoo Su & Above	DSTAIION											
	30.04.2021	0.684028	30.04.2021	0.696528	0	. 4	132kV, Tingtibi Lin	e Yumoo Ss	ov	Distance relay tripp	e Nill	Temporary	
					-			ALCOHOLD CONTROL	***************************************	and a supply			
1		Janes de la constant											
20/3	3kV Dagapela S & Above	Substation											

# May 2021

Divi	iston:	5MD-DEOTHANG	1													
Sub	station:	132/33/110V KRR1	har Substation													
Mo	nth:	May-21	MATERIAL MATERIAL PROPERTY AND ADDRESS OF THE PARTY AND ADDRESS OF THE													
	Name of Feeder	Voltago Level	Type of Ontage (Shandown/Tripping)	Shutdown	Tripping me	Normaliz	stice Time	53	Duration of Outage	MW before Outago (MW)		Tripping Details	Type-Couse of Fault	Rosson for Shat Sown	Weather Condition Suring the	Researks
			(Santowas Lippan)	Date	Time	Date	Time	(Hrs)	(Min)		Protecton Relay Optd	Fault Details (As recorded by relay)			Outage	
V Feed	lers		10		in .			100			NC 9		4			
	Kurichu	132Kv	Tripped	5/27/2021	0:25 km	5/27/2021	0:35 les:		10	21.41	- 12	8	(2)	Tripped	Rosting	Grid fail from Naughan and Tingtibe due to o/current along with grid fail fro Rangia
Divi	Islan:	SMD-DEOTHANG	9													
Sub	istation:	132/33/116V Kang	lung Substation													
Mo	nth:	May-21														

St. No.	Name of Feeder	Voltage Level	Type of Outage (Shutdown/Tripping)	Shutdown Tin		Normaliza	tion Time	=	Duration of Outage	MW before Outage (MW)		Tripping Details	Type Course of Fault	Reason for Shaidown	Weather Condition during the	Remarks
		11	(onesoure trapping)	Date	Time	Date	Time	(Hrs)	(Min)		Protecton Relay Opts	Fault Details (As recorded by relay)			Outage	
1	certain langtum feeder	132AV	tripping	01-05-2021	12.60	01.05.2021	12:01	0	4	-10.896	Distance protection salay Miscon 8442	Tripped on ABCN, Zone-1, Fish Curren: 14 - 763.34, IB - 791.64, IC - 762.24, Fash Looning, 15.84ps.	Transcorr,Throo plane Fault	SA.	windy	protocol in consultation with SPSO
+	Sorghug-Phursholming feeler	15287	tripping	00.01.2021	12:40	01.05.2021	1241	. 0	(4)	9.455	Distance protection relay ESE 640	Import on ABCN, Zono 1, Fault Current: IA -717A, IB - 752A, IC -745A, Fault Location: 17 11im	Transier, Thron phase Funds	NA NA	windy	printeed in considering with 2000
1	istagling Phansholizing Neder	13200	httpping	01.05.2021	15:12	62.05.2021	2010	ж	ü	SAM	Distance protection tells/ RELATO and EFOC solar	Tripped on AN, Zone 1, Frait Current, IA 624A, IB 36A, IC -53A, Finit London, 20,59cm, OC-SF IA 607A, IB-42A, IC-52A		NA	const	Test charged the feeder twice after informed to EPSO at 15-14 Mrs and 15-44 Mrs but on not write and the Seder Dest charged the line as informed by BPSO with charging coil 2007 at 20.07 lins. This feeder was charged to a transier by an 47.04 with closing on 2008 at 2007 by the third polytopid again charge or de 2004.
18	Cober	135 NV	NA NA	27.65.2021	0.16	27.05.2021	0.34	10	18	-22 176	NA NA	NA NA	SA	SA.	Hyperring & Thundering Baixway	Daggie full dan to Gold full it was Kush but not no operation take place or Kunghang Salestanian.
19	Humiolog	13269	List Birty	27 65 2021	0.34	27.05.2021	0.47	0	13	21.6	NA NA	NA.	36A	NA	Harristop & Threatering Raissang	Chlarged the feeder often contact to BP90.

Division:	SMD-DEOTHANG
Substation:	132/33/31kV Naugher Substitute
Month:	May-21

MONTHLY OUTAGE REPORT FOR THE MONTH OF MAY UNDER SMD DEOTHANG, TD, BPC.

П			Type of Ontage	Shutdown	Tripping	Normaliz	ation Time	E	Paration of Outage	4		Tripping Details			Weather Condition	
10.	Name of Feeder	Voltage Level	(Shatdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	MW before Outage (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	during the Outage	Remarks
d	enders		(1)					100		V/I	(A					
I	32/33kV, SMVA Tif-1	132kV	Tripping	5/1/2021	13:58 hrs	5/1/2021	14:13 km	6	14	0.48	Non directional IDMT PROTN Relay operated	O/C Relay-50A, 50C & tripping relay 86 operated	fivalt	12	Clear	Tripped the to fault on 33kV Namun feeder
I	32/33kV, 5MVA Tif-II	132kV	Tripping	5/1/2021	13:58 hrs	5/1/2021	14:06 hrs	0		0.3	Non directional IDMT PROTN Relay operated	O/C Relay-50A, 50C & tripping relay 86 operated.	Tripped due to feeder finalt	*	Clear	Tripped due to feult on 33kV Natura feeder
2	Norghor-Devtheng Line	11260	Unipping	5/1/2021	15:19 hm	5/1/2021	15:27 les	۰	,	2)	MiCOM PIADIB	Switz C.X., O'C. Sam D. I., E.P. I. det C. N. N. I. S. I. det C. 192-2-VAR-18-38-V. C. 192-2-VAR-18-38-V. C. 192-2-VAR-18-38-V. C. 192-2-V. C. 192-2-V	Tripped on imit	8	Thuder &	Informed to 1878O, and charged the feeder with instruction from 1878O.
	132/33kV, 5MVA THFI	13.2kV	Tripping	5/1/2021	16:30 hrs	5/1/2021	16:35 hrs	0	5	0.3	Non directional IDMT PROTN Relay operated	O/C Relay-50A & tripping relay 86 operated	Tripped the to feeder fault	8	Thinder &	Tripped the to fault on 33kV Wanning feeder
1	132/33kV, 5MVA TiGI	132kV	Tripping	5/6/2021	11:00 hrs	5/9/2021	11:05 les	.0	3	0.43	Mon dispersonal EDATE	O/C Relay-50A & tripping relay 85 operated	Transient	(3)	Clear	•
I	132/33EV, 3MVA TIC4	132kV	Tripping	5/7/2021	32:24 hrs	5/7/2021	22:29 hrs	- 6	3	0.53	Non directional IDMT PROTN Relay operated	G/C Relay-50A & tripping relay 86 operated	Tripped due to feeder findt	9	Clear	Tripped this to fault on 33kV Wanning feeder
	132/33kV, 5MVA Tif-I	1326V	Tripping	5/8/2021	05:31 hrs	5/8/2021	09:40 ires	0	9	0.5	Non directional IDMT PROTN Relay operated	O/C Relay-50A & tripping relay 86 operated	Tripped on finit	j#i	Cloudy	No sapply interrupted

56	ongåor-Dredung Line	13288	Tripping	\$/91/2021	05:42 his	5/31/2021	09:49 hrs	0	,	37,63	MICCON P14DB	Directional—OC & EFF Refor Tripped O  N. Sent O AN, CO Start D L. EFF Sant NI-SEL AND SPLENKY SEC. 21, 349 DNI-SLAMB SPLENKY SEC. 21, 444 VANN-S SIMV VINS- 12, 344 VANN-S SIM	faral#	2	Rainfell	hifurned to RPSO, and charged the feeder with instruction from RPSO.
13	32/33kV, SMVA Tef-II	132kV	Tripping	5/27/2021	00:43 hrs	5/27/2021	01:19 hrs	0	36	0.17	Non directional IDMT PROTN Relay operated	O/C Relay-50C & tripping relay 86 openited	Tripped due to fooder took	22	Heavy rainfall	Tripped the to fault on 33kV Nannag & Wannong feeder
13	32/33NV, 5MVA TIGH	132kV	Tripping	5/27/2021	00:16 hrs	5/27/2021	00:42 hrs	0	26	0.31	Non directional IDMI PROTN Relay operated	O/C Relay-50C & tripping relay its operated	Tripped on Sult	(*)	Heavy rainfall with thander & lightning	Tripped at the instant of Grid failure
1 30	lergker-Dwedeng Line	1326V	Tripping	5/27/2021	00:16 hrs	5/27/2021	60:32 les	0	26	31	MSCOM P442	Distance Relay - Start O ADCN, Tripped O ABC Shart distance element, TOC start. distance rip Z1, system frequency 40,09Hz, AB Lockour cheef-goalt curration-125 cms, Relay vity time - 00,02ms, Fanh Secritic XV- B-155hm towards Douffung, IA-465.5A, TB 121.0A, IC-353.1A, VAN-16.5d(V, VBN- 17.71) V, VCN-18 948V, Fault resistance XV-2.801C, Fank in Z1. And vipping relay 86 operated at our care.	Tripped on Soilt	œ	Heavy rainfall with thurder & lightning	Informed to DPSO. Thimpho & closed the CO on per their instruction Both Gri- fulled and Subsket Grid received at 00.34 lm.
13	SZ/SSKV, 5MVA THFE	132kV	Tripping	5/18/2021	03:45 hrs	5/18/2021	03:45 les	0	3	0.40	Not directional EDMI PROTN Rulay operated	O/C Relay-50AA: tripping relay 86 operated	Tripped due to feeder final!		Raisfell	Tripped due to fault on 33kV Wannung freeler
13	52/33kV, 5MVA Tef-B	132kV	Tripping	5/11/2021	23:55 hrs	5/11/2021	23:57 les	0	2	0,64	Non directional IDMT PROTN Relay operated	O/C Rolay-SOA& tripping relay \$6 operated	Tripped due to feeder fault	<b>(iii)</b>	Heavy rainfall	Tripped due to fault on JSKV Naming feeder
13	32/33kV, 5MVA Tif-1	132kV	Tripping	5/11/2021	21:37 las	5/11/2021	21:51 hrs	0	14	0.53	Non directional EDMT PROTN Relay operated.	O/C Relay-50C & tripping relay \$5 operated	Tripped due to feeder fault		Heavy raisfulf.	Tripped the to fault on 33kV Tsebur Seeder
13	DAYRIKV, SMVA Trif-II	132kV	Imppira	5/11/2021	21:37 hrs	5/11/2021	21:01 ks	0	34	0,35	Non directional IDMT PROTN Relay operated	O/C Relay-50C & tripping relay 85 operated	Tripped due to feeder Scale	3	Heavy rainfall	Tripped due to fault en J3KV Toobar feeder
13	32/33kV, 5MVA Trf-I	132kV	Tripping	5/11/2021	11:09 hrs	5/11/2021	11:15 hrs	0	6	0.43	Non directional IDMT PROTN Relay operated.	O/C Relay-50A & tripping relay 85 operated	Tripped due to feeder first	*	Clear	Tripped while test changing 33LV Wassrong feeder

Division:	SMD-DEOTHANG
Substation:	132/33/11kV Deothang Substation

	***********	Voltage Level	Type of Outage	Shutdown	Tripping	Normaliza	tion Time		Duration of Outage	MW before Outago (MW)		Tripping Details	Type Couse of Fault	Rosson for Shutdown	Wester.	Remarks
St. 70.	Name of Feeder	Voctage Level	(Shutdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	MW below Ontago (MW)	Protecton Relay Optd	Fault Details (As recorded by rolay)	Type-Cause of Famil	Reason for Sharmown	Condition	Remarks
5			0000		314					20022		UV W. 165	The second second	72		South contain him backets may be tell
1	112kV Doothasy-Nagiday Lian	19265	Trigging	01-05-2021	15.20	61.05.2021	15:29	.0		-21.43	384	NB.	Orid fail	NA.	Clear	Original from both the end and at our end all breaker was in assemble condition.
25	1521V Deshay - Nagkar ke	332EV	Transping	27892021	0.23	21:05:2023	0.44	. 6	25	-56.66	Distance relay	Zone J Opt, Fault Dist 18 90km. LA 1 055kA, IB-214 4A,IC-1.146kA,	Preticuries I on E. (a B Plan	NA.	Earning & Gooding	Dorthaug benårn vig at för same tinn grid fall. Dorthaug breaker elsepf av 24 19km. After flat charge from Nungtor at 34 40km from commit
26	ESSET Deviluag Nargico ine	13260	Tripping	31.65.2021	9:45	38.05.2023	9:50	0	1	27.22	Sit	Sil	Transcept fault	NA.	Raining A Throdony	Cold that there both the read and an Nangither shorring CVCNERF. At natural breslow, with all bensions, or or as montreal consistion.

Division:	SMD-DEOTHANG	
Substation:	132/33/11kV Nganghua Solistation	
Month:	May-21	

SL No.	Name of Feeder		Type of Ostage	Shutdown Tie		Normaliza	ction Time		Duration of Outage			Tripping Details		Reason for Shutdown	Weather Condition	Remarks
SL 70.	Name of Feeder	Voltage Level	(Shardown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	MW before Outage (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	during the Outage	Scenarics
				_	_	_		-		13	kV	R .	Name of the Owner, which we have			
a .	132/336V SMVATnusdomer 1	19289	Trepting	97/05/2021	11:55	07:08:2023	11:57	0	1	0.594	O/C & B/FROMT	Earth Fest	Tripped due to +NeV Debroiling freder		Clour	
1	Ngogian-Topthi Lise	132kV	Tripping	15052021	13:57	13.05.2023	14.08	0	11	-846	Distance relay Micana P442	Tripped on ARCN, Fault Current IA -426-6A, IR - 57-26A, IC -61-74A IN - 888-5A	Transient Early fault	0	Clear	
1	132/336V 5MVAUrandomer 4	13265	Tripping	20.04.2021	01:00	20.08.2021	01:01	0	4	0.603	OC & DTEMT	Lath Early	Tripped due to 3 Sey Debesting feeder		Light Mainy	
4	Namedons Tietarbi Line	1828V	Tripping	27/05/2021	00:03	27.05.2023	09:34		31	19.98	Distance rolay Micom P442	Fedi Veles IA- 1.305KA IB- 1.365KA IO- 1.311KA, VAN 10.69EV, VBN- 11.66KV, VCN- 10.10KV	Over Current		Hony Rainfall	
	Ngangiami Tingtibi Lina	13280	Transing	27 65 2021	00:17	21.08.2021	00:34	- 0	-17	16.98	Distance riday Miscom P444	Grid full	Grid fell		Henry Ramfell	Supply fail from Rango end.
*	DOSEN SMVADualbraer I	132kV	Tripping	27.05.2021	06:49	21.08.2021	06:54	.0		9.7E	O/C & EVEDMI	Early Facil	Tripped dar to 5 SeV Debrailing feeder		Clear	

	livision:	SMD-DEOTHANG														
3	ubstation:	132/33kV Matanga	Substation													
-	louth:	May-21			1											
20	duranti sababatan	Transfer and T	Type of Ontage	Shutdown	Tripolog	Normaliz	ation Time		Duratica of Outage	1		Tripping Details	40.1100.1100.000.000		Womer	
No.	Name of Feeder	Voltage Level	(Shutdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Mle)	MW before Outago (MW)	Protecton Relay Oped	Fault Details (As recorded by relay)	Type:Cause of Fault	Rosson for Shutdown	Condition	Remarks
					***************************************			- Baranter and American	747000							
1 2	lotases-Pleatshofkany lier:	13250	Trianing	51/2021	15.12	5/1/2021	15.16	0	4	-8.68	BACKUP PROTN SELAY		OCT		Normal	Informed BPSO and CB closed from our end at 15.16km
-	2017-0001-0001-0001	08000	10.00000000	5-2-5-555	500007		9202254	- 625		1 25000	BAY CONTROL UNIT		1,188.583		10000000	TALL STATE OF THE
2 2	lotunga Deorhung line	1326	Tripping	1/1/2023	15:15	5/1/2021	15:29		11	-21.9	RBC670	MA & 14B OPTD		~	Norrasi	Informed RPSO and storged line at 15 29 km
1 2	loteaga Deothang line	13287	Tripping	5/1/2021	15:31	5/1/2021	15:53		22	-21.9	MAIN DISTANCE PROTY. RELAY RELASO	28	ov	9	Normal	Litse Voltage shootspito 1.15 SEV and CB auto tripped from our end informed HPSO of except at 15 SBI's.
4 2	Ctango-Rorgia line	33287	Tribbing	\$112821	15:12	3/1/2021	16:08		50	100	BAY CONTROL UNIT	SEA & SOR OPTO	-2-2		Normal	Informed BPSO and with charging code BHT-2065 NLDC India-15 and NERLDC-20
7	confrantian	(0.040)	1156776	1150000	95000	- Transact	2000	_	2000		BACKUP PROTE RELAY	2000,000,000			, manual .	closed at 16.08lps from our end.
. 2	lotsage Doothang ime	13260	Trapping	5/27/2021	0:16	\$127/2025	0.52		37	-55	REPOS SELECT	±1	OCALT	3	Zorate	informed BPSO and line extend at 00:53 has from our end.
6 3	emga-Ragia lie	1928V	Tripping	5/27/2021	0.16	5/27/2025	136	- 1	tt.	53.17	BACKUP PROTN RELAY		OC#EF	8	Raising	Informal RPSO and with code on NLDC BRT 238 NLDC India 643 & NERLDC 3460 CB closed
		200000								11-7-8-11	REPAIS MADY DISTANCE PROTIS		ONAY			and at 130 less
† 5	warge-Plumikohong Line	DOW	Trigging	5/27/2021	1901	9/17/2021	1111		- 1	-0127	RELEV RELEG		OVUY	141	Kinke	3 flowed SPSC and charged the for at 1.3 ftm from our med.
9 1	stongs Deathing lies	132KV	Tripping	5/31/2021	39362	5/3 E/2021	9.50		(4)	-15.51	MAIN DISTANCE PROTN. RELAY REL650	ZONE LOPID & RIPH TREF	OC & E3	9	Raising	inflammed RPSO, an incorporated to closed the CRI or 95 Mart Years our well
to s	Angs Bargis Sec	1326V	Tripping	5/31/2021	9.42	501/2021	10:00		- 18	26.13	BACKUP PROTN RELAY		ocarr		Raining	Informed BFSO <sub>2</sub> m instructed to closed the CB with code NLDC BBT 1600,NLDC halo 697 & N 1502 CB closed in 1600/st from our end
	louth:	May-21														
	0100000		Type of Outage	Shutdown	Tripping	Normaliza	ation Time		Duraties of Outage			Tripping Details			wagmer	-
	Name of Feeder	Voltago Laval	Type of Outage (Skatdown/Tripping)	Shutdown	Tripping	Normaliz- Date	ation Time	(Hrs)	Duration of Outage (Min)	MW before Outage (MW)	Protecton Relay Opid	Tripping Details Finit Details (As recorded by relay)	Type Course of Fault	Remon for Shutdown	Condition	Remarks
No.	Name of Feeder	Voltago Levol	(Shatdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	-22.00	Protecton Relay Optid			Reason for Shutdown	Condition	At 10 16 her Incoming supply from Whillian substation (bill and Coring substation was
No.	Name of Feeder	Voltage Level			Time	Date		(Hrs)			1 100		Type Cause of Fault Ord ful	Rosson for Shatdown		
No.	Name of Feeder	Voltago Levol	(Shatdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	-22.00	1 100			Reason for Shatdown	Condition	At 10 16 her Incoming supply from Whillian substation (bill and Coring substation was
No.	Name of Feeder	Voltago Levol	(Shatdown/Tripping) Oral fel	Date	Time	Date	Time	(Hrs)	(Min)	-22.00	1 100			Rosson for Shardown	Condition	At 10 16 her Incoming supply from Whillian substation (bill and Coring substation was
No.	Name of Feedor 12 kV Shithart.es 12 kV Smithart.es	Voltago Level 1924V 1924V	(Shatdoven/Tripping) Oral fel	Date	Time	Date	Time	(Hrs)	(Min)	-22.00	1 100			Reason for Shathown	Condition	At 10 16 her Incomming supply from hit liker substation fall and Coriney substation wa
No.	Name of Feeder 12 av 83035ar 1. ra 12 av 83035ar 1. ra 12 av 83055ar 1. ra Wiston:	Voltago Levol 11289 11289 SMD-DEOTHANG	(Shatdoven/Tripping) Oral fel	Date	Time	Date	Time	(Hrs)	(Min)	-22.00	1 100			Rosson for Shatdown	Condition	At 10 16 her Incomming supply from hit liker substation fall and Coriney substation wa
No.	Name of Feeder 12 tV 83083ar1.re 13 tV Emphre 1.re 184830m; ubstation;	Voltago Levol  132 sV  132 sV  SMD-DEOTHANG  132/33kV Photoche	(Shatdown/Tripping)  Oral ful  interpretation	Date 27-65-2021	Time 60 16 km	Date 21.05.2021	10.33 km	(Hrs)	(Min) 17	-22.00	1 100	Fault Details (As recorded by relay)		Rossen for Shathoon	Condition	At 10 16 her Incoming supply from khillion substation (bill and Corbug substation was
No.	Name of Feeder 12 tV 83083ar1.re 13 tV Emphre 1.re 184830m; ubstation;	Voltago Levol  132 sV  132 sV  SMD-DEOTHANG  132/33kV Photoche	(Shatdown Tripping) Oral felt  Grant felt	Date 27-64 2021	Time 60 16 km	Date 27.06.2021 Normaliz	Time 00.33 km	0	(Min) 17  Deratics of Outago	-22.00	Na Na	Fault Details (As recorded by relay) N3 Tripping Details	Oriel fail)	Resson for Shardown  Resson for Shardown	Condition	At 10 16 her Incoming supply from khillion substation (bill and Corbug substation was
co.	Name of Feeder 27 W Shikher Lee 27 W Shikher Lee 27 W Emphre Lee 28 Wision: obstation: fonth:	Voltago Lavol  1324V 1324V 1324V SMD-DEOTHANG 132/334V Pinnetha May 21	(Shatdown/Tripping)  Oral ful  interpretation	Date 27-65-2021	Time 60 16 km	Date 21.05.2021	10.33 km	0	(Min) 17	-12336 22336	1 100	Fault Details (As recorded by relay) N3 Tripping Details			Clear	Al 30 I films Decreming supply from Stillion velocities full and Corkey substellers are later breaker migrage has occound at Corkey polytocos.
No.	Name of Feeder 27 W Shikher Lee 27 W Shikher Lee 27 W Emphre Lee 28 Wision: obstation: fonth:	Voltago Lavol  1324V 1324V 1324V SMD-DEOTHANG 132/334V Pinnetha May 21	(Shatdown Tripping) Oral felt  Grant felt	Date 27-64 2021	Time 60 16 km	Date 27.06.2021 Normaliz	Time 00.33 km	0	(Min) 17  Deratics of Outago	-12336 22336	Na Na	Fault DataBs (As recorded by relay) 13  Topping Details  Fault Details (As recorded by relay)	Oriel fail)		Clear	Al 30 16 first Deceasing supply times follow velocities full and Circles; substetion and large substetion are librarie tradpring his occount of Circles; solution.
No.	Name of Feeder 12 V 83084m Lee 12 V Knighter Lee 13 V Knighter Lee 14 Ston: 16 Ston: 16 Ston: 16 Ston: 17 Name of Feeder 18 Name of Feeder	Voltage Level  132 av 132 av 132 av 132 av 132/334V Pinurche May-21  Voltage Level	(Shatdown Tripping)  Oral for  inchang Substation  Typo of Ontage (Shatdown Tripping)	Date 27 (4 2021 Shutdorn Date	Time 60-16 hrs Tripping Tripping	Date 21.06.2021 Normalize Date	Time 00.33 km	0	(Min) 17  Deratics of Outago	-11339 -12330	Protecton Relay Opté	Fault Details (As recorded by relay) NI  Tripping Details  Fault Details (As recorded by relay)  JOHN OFTO AND PLAN Physical Part Fault  JOHN OFTO AND PLAN Physical Part Fault	Orabiai  Type-Cause of Fault		Coultins Cou	At 20 1 film the consider agely broad tillibe velocities that and Coring substation as factor broken shipping his eccentral of Coring solutions.  Remarks
No.	Name of Feeder 27 W Shikher Lee 27 W Shikher Lee 27 W Emphre Lee 28 Wision: obstation: fonth:	Voltago Lavol  1324V 1324V 1324V SMD-DEOTHANG 132/334V Pinnetha May 21	(Shatdown Tripping) Oral felt  Grant felt	Date 27-64 2021	Time 60 16 km	Date 27.06.2021 Normaliz	Time 20.33 km ation Time Time	0	(Min)  17  Deratics of Outage (Min)	-12336 22336	Na Na	Fault DataBs (As recorded by relay) 13  Topping Details  Fault Details (As recorded by relay)	Oriel fail)	Rossen for Sharkown	Clear	Al 30 16 first Deceasing supply times follow velocities full and Circles substetion as flut are breaker migrage has occounted at Circles; solvetices.
No.	Name of Feeder 12 V X108Mer Lee 13 W Kemphers Lee 13 W Kemphers Lee 13 W Kemphers Lee 14 W Kemphers Lee 15 W Kemphers Lee 16 W Kemphers Lee 16 W Kemphers Lee 16 W Kemphers Lee 17 W Kemphers Lee 17 W Kemphers Lee 18 W Kemphers Le	Voltage Level 13.24V 13.24V SMIP-DEOTHANG 132.334V Plustriks May 21 Voltage Level	(Shatdown Tripping) Oral for thing Substation  Type of Ontage (Shatdown Tripping)  transier, rest	Date   27/04/2021   Shutdortt   Date   5/2/2021	Time to 16 km	Date 27.05.2021   Normaliz   Date   1/3/2021	Time 00.33 km atton Time Time	(line)	(Min) 17  Deratics of Outage (Min)	-22 2300 22 2300 MW before Outage (MW)	Protecton Relay Op 16	Fault Details (As recorded by relay) N2  Tripping Details  Fault Details (As recorded by relay)  ZONA (STO ASSON PLANTAMENT) archivations on State and Conference (Asson Plantament) and Conference (Asson Plantam	Oral fail  Type-Cause of Fault  R.v. and II phase trip.	Reseas for Shardown  The available	Contition Clear Pressurer Condition Surry	Al 30 16 hts Decreasing supply from Millior solution in fill and Corkeg substein non-later integral his coccount of Corkeg reletation.  Remarks  Test charged and five with starst.  The charge but could not stand line with starst.
No.	Name of Feeder 12 V 83084m Lee 12 V Knighter Lee 13 V Knighter Lee 14 Ston: 16 Ston: 16 Ston: 16 Ston: 17 Name of Feeder 18 Name of Feeder	Voltage Level  132 av 132 av 132 av 132 av 132/334V Pinurche May-21  Voltage Level	(Shatdown Tripping)  Oral for  inchang Substation  Typo of Ontage (Shatdown Tripping)	Date 27 (4 2021 Shutdorn Date	Time 60-16 hrs Tripping Tripping	Date 21.06.2021 Normalize Date	Time 20.33 km ation Time Time	0	(Min)  17  Deratics of Outage (Min)	-11339 -12330	Protecton Relay Opté	Finite Details (As recorded by relay) \$13  Tripping Details  Finite Details (As recorded by relay) \$2,000,1001 Indian (As recorded by relay)	Orabiai  Type-Cause of Fault	Rossen for Sharkown	Coultins Cou	At D116 him housesting supply brook billion with state in the and Carkey substetion with better brighted his occount of Crobay relection.  Remarks  Test charged and from with states.  The charge but nouth not tool like at Naughing and the ZONEL OPTLD, it mig and rolay addicating OVULN 3 food brittens: 28.222 line, like no circuit.
No.	Name of Feeder 12 V X108Mer Lee 13 W Kemphers Lee 13 W Kemphers Lee 13 W Kemphers Lee 14 W Kemphers Lee 15 W Kemphers Lee 16 W Kemphers Lee 16 W Kemphers Lee 16 W Kemphers Lee 17 W Kemphers Lee 17 W Kemphers Lee 18 W Kemphers Le	Voltage Level  1324V  SMD-DEOTHANG 132/33AV Plearche May 21  Voltage Level  13200	(Shatdown Tripping) Oral for thing Substation  Type of Ontage (Shatdown Tripping)  transier, rest	Date   27/04/2021   Shutdortt   Date   5/2/2021	Time to 16 km	Date 21:06:3021  Normaliz: Date 5/3/2021	Time 00.33 km 00.33 km ellon Time Time 12.44	(line)	(Min) 17  Deraties of Outage (Min) 4	-22 239 22 239 MW Infate Outage (MW) 9.22 9.20	Protecton Relay Optid  Bon & Bon  Sen. 86 OPTD	Fault Details (As recorded by relay) N3  Irapins Details  Fault Details (As recorded by relay)  2003.1 GFI DAMP #, 1879-warty set Fault Details (As recorded by relay)  2003.1 GFI DAMP #, 1879-warty set Fault DAMP #, 1879-warty set Fault Fault Content value (1144), 1879  Fault C	Oral fail  Type-Cause of Fault  R.v. and II phase trip.	Remain for Shardown  not available  Not available	Continue  Closs  Weather Continue  Surry  Conty	Al 30 16 feet becoming supply three Strikes whitelities full and Cocking substitute in the substitute
ia.	Name of Feeder 12 V X108Mer Lee 13 W Kemphers Lee 13 W Kemphers Lee 13 W Kemphers Lee 14 W Kemphers Lee 15 W Kemphers Lee 16 W Kemphers Lee 16 W Kemphers Lee 16 W Kemphers Lee 17 W Kemphers Lee 17 W Kemphers Lee 18 W Kemphers Le	Voltage Level 13.24V 13.24V SMIP-DEOTHANG 132.334V Plustriks May 21 Voltage Level	(Shatdown Tripping) Oral for thing Substation  Type of Ontage (Shatdown Tripping)  transier, rest	Date   27/04/2021   Shutdortt   Date   5/2/2021	Time to 16 km	Date 27.05.2021   Normaliz   Date   1/3/2021	Time 00.33 km atton Time Time	(line)	(Min) 17  Deratics of Outage (Min)	-22 2300 22 2300 MW before Outage (MW)	Protecton Relay Op 16	Finite Details (As recorded by relay) \$13  Tripping Details  Finite Details (As recorded by relay)  2004; UPIG AND PLAY STATE FOR THE AND TO STATE FOR THE AND PLAY STATE FOR THE FOR THE AND PLAY STATE FOR THE PLAY STATE FOR THE FOR THE PLAY STATE FOR THE	Oral fail  Type-Cause of Fault  R.v. and II phase trip.	Reseas for Shardown  The available	Continue  Closs  Weather Continue  Surry  Conty	Al 30 I films Decreasing agely trees littless velocities that and Coring substeins as flutter brader staying his occound at Coring substation.  Remarks  Test charge but could not stand line at Knagling end due 2008 i GPID. R imp and rolly and cotted (Test). The charge but could not stand line at Knagling end due 2008 i GPID, R imp and rolly addicatege (TVV). I also Destinee; 28.3.22 for the mercall 2,004,025021 also rescues are strating code 2008 for BIPSO.
No.	Name of Feeder  12 O Middle Lee 13 O Angles Lee 13 O Angles Lee 14 O Angles Lee 15 O Angles Le	Voltage Level  1324V  SMD-DEOTHANG 132/33AV Plearche May 21  Voltage Level  13200	Chardove Tripping)  Oral fee  I thing Substation  Typo of Ontogo (Shatdove Tripping)  Transier: trust  Tripped on fault	Date   2745 2021	Time 40-16 km Tripping Time 12-90 15-12	Date 21:06:3021  Normaliz: Date 5/3/2021	Time 00.33 km 00.33 km ellon Time Time 12.44	(line)	(Min) 17  Deraties of Outage (Min) 4	-22 239 22 239 MW Infate Outage (MW) 9.22 9.20	Protecton Relay Optid  Bon & Bon  Sen. 86 COTED	Fault Details (As recorded by relay) N3  Irapins Details  Fault Details (As recorded by relay)  2003.1 GFI DAMP #, 1879-warty set Fault Details (As recorded by relay)  2003.1 GFI DAMP #, 1879-warty set Fault DAMP #, 1879-warty set Fault Fault Content value (1144), 1879  Fault C	Ord fail  Type Cross of Fact  13.7 and 8 phase trip  Rand Nyhase trip	Remain for Shardown  not available  Not available	Continue  Closs  Weather Continue  Surry  Conty	Al 30 1 films Decreasing supply trans littles walsottien full and Carkery substrates we have a brader shipping his occount of Corking relection.  Remarks  Test charges but could not stand line at Kasaginag and the ZONE1 OPTO , it may aim relay advantage of the Market Corking of the Corker Corking of the Corker Corke
No.	Name of Feeder  12 O Middle Lee 13 O Angles Lee 13 O Angles Lee 14 O Angles Lee 15 O Angles Le	Voltage Level  1324V  SMD-DEOTHANG 132/33AV Plearche May 21  Voltage Level  13200	Chardove Tripping)  Oral fee  I thing Substation  Typo of Ontogo (Shatdove Tripping)  Transier: trust  Tripped on fault	Date   2745 2021	Time 40-16 km Tripping Time 12-90 15-12	Date 21:06:3021  Normaliz: Date 5/3/2021	Time 00.33 km 00.33 km ellon Time Time 12.44	(line)	(Min) 17  Deraties of Outage (Min) 4	-22 239 22 239 MW Infate Outage (MW) 9.22 9.20	Protecton Relay Optid  Bon & Bon  Sen. 86 COTED	Fault Details (As recorded by relay) N3  Irapines Details  Fault Details (As recorded by relay)  2003.1 GFI DAMS # 3,5 Phone trip set Fault  2003.1 GFI DAMS # 3,5 Phone trip set Fault  2003.1 GFI DAMS # 3,5 Phone trip set Fault  2003.1 GFI DAMS # 3,5 Phone trip set Fault  2004.0 GFI DAMS # 3,5 Phone trip set Fault  Fault correct value-1144, 7,6 Ph. 15 SA,  RE2PA £ 0,0 N1 GFI DAMS # 3,5 Phone  2015.1 GFI DAMS # 2,5 Phon	Ord fail  Type Cross of Fact  13.7 and 8 phase trip  Rand Nyhase trip	Remain for Shardown  not available  Not available	Continue  Closs  Weather Continue  Surry  Conty	At 10 1 films Recreating supply branchitillar subsistion that and Carkey substein non-like the brader shiping his occount of Circlesy rebottons.  Remarks  Remarks  Test charge but could not stand line with stand.  The charge but could not stand line with stand.  The charge but could not stand line with stand.  The charge but could not stand line with stand.  The charge but could not stand line with standing or due ZOORE CPTED, it mig not relay addicating (OVUN). Fault Distance: 28-2323 last line normalis.  JOHAN 2005-21 after recovered contributing code 2006 from BPIO.  John the standard of the standard and Mottang cond breaker was spending in the standard standard conditions and standard standar
No.	Name of Feeder 2: 20 Abbitot tee 2: 20 Abbitot tee 2: 20 Abbitot tee 2: 20 Abbitot tee 2: 20 Abbitot	Valtage Level  132 W  132 W  132 W  SMB-DEOTHANG  132/33W Plearthe  May 21:  Voltage Level  11500  11500	Chardowe Tripping) Oral for Linning Substation.  Typo of Outage (Shandowe Tripping)  Translers rout  Tripped on fault  Tripped on fault	Date   2744 2021	Time 60.16 km  Tripping Time  12.40  15.12	Date 21:05:3021  Necus Aliz  Date  5/1/2021  5/1/2021	Time 00.33 km 00.33 km 100 Time 1100 Time 12.44 12.64 15.56	(line)	(Mis) 17  Deraties of Outage (Mis) 4	-21339 22336  MW before Outage (MW)  1.11  8.70  8.37	Protecton Relay Option  DOA & NOR  SOL SE COTD  SOL SE COTD	Finish Details (As recorded by relay) 183  Topping Details  Finish Details (As recorded by relay)  2004; URL ORL AS recorded by relay)  2004; URL ORL AS recorded by relay)  2004; URL AS READ TO SENSE THE SENSE TO SENSE TO SENSE THE SENSE TO SENSE THE SENSE TO SENSE THE SENSE	Type Course of Fault  It, and It phase trip.  Rand It phase trip  Over voltaget	Resear for Shardown  For ovaluable  Nor available  Out ovaluable  Out of the shardown of the s	Country Country Country Country Country Country Rainy & wardy	Al 30 1 films Decreasing supply trans littles walsottien full and Carkery substrates we have a brader shipping his occount of Corking relection.  Remarks  Test charges but could not stand line at Kasaginag and the ZONE1 OPTO , it may aim relay advantage of the Market Corking of the Corker Corking of the Corker Corke
No.	Name of Feeder 2: 20 Abbitot tee 2: 20 Abbitot tee 2: 20 Abbitot tee 2: 20 Abbitot tee 2: 20 Abbitot	Valtage Level  132 W  132 W  132 W  SMB-DEOTHANG  132/33W Plearthe  May 21:  Voltage Level  11500  11500	Chardowe Tripping) Oral for Linning Substation.  Typo of Outage (Shandowe Tripping)  Translers rout  Tripped on fault  Tripped on fault	Date   2744 2021	Time   60.16 km   12.40   15:42   15:31   0:33	Date 21:05:3021  Necus Aliz  Date  5/1/2021  5/1/2021	Time 00.33 km 00.33 km 100 Time 1100 Time 12.44 12.64 15.56	(line)	(Mis) 17  Deraties of Outage (Mis) 4	-21339 22336  MW before Outage (MW)  1.11  8.70  8.37	Protecton Relay Option  DOA & NOR  SOL SE COTD  SOL SE COTD	Finish Details (As recorded by reliay) 513  Tripping Details  Finish Details (As recorded by reliay) Finish Details (As recorded by relay) Finish Details (As recorded by relay) Finish Control (As Primer injured Laute distance on AMMAP and 10 other 1-1177-1894/2- Finish Control (As Primer injured Laute finish (As Primer injured Laute) Finish Control (As Primer inj	Type Course of Fault  It, and It phase trip.  Rand It phase trip  Over voltaget	Resear for Shardown  For ovaluable  Nor available  Out ovaluable  Out of the shardown of the s	Country Country Country Country Country Country Rainy & wardy	At 10 1 films the consulty supply three shifting substition in the and Corleage abstraction on factor from the shifting has eccessed of Corleage reletation.  Remarks.  Remarks.  Test charge-but could not stand like at Kangling and the ZONEL OPTD., it is part ratally indicating (OVAIN). Fact Distinctive 28-22 feet little moments 20-04-0205523 that received switchings code 2066 from 10FOO. Our and thereafter was normal and Meetings and incides was poperly.  Finds current value (1-0-224, 1.0-146, 1.0-066, 180, 111.0, 111.0, Religional controllers are supplied to the controllers of the controllers and the controllers are supplied to the controllers and the controllers are supplied to the controllers of the controllers and the controllers are supplied to the controllers are supplied to the controllers and the controllers are supplied to the controllers and the controllers are supplied to the controllers are supplied to the controllers and the controllers are supplied to the controllers and the controllers are supplied to the controllers are supplied t

šl. No.	Date of Tripping	Time of Outages/ Time of Tripping	Date of Normalization	Time of Fault was Cleared	Duration of Outages (Hrs)	MW before Outage (MW)	Name of feeder	Name of the Substati on/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Type of outages	Remarks
) 66kV /	Above												
1	05.05.2021	12:21hrs	05.05.2021	12:36hrs		-12.990	220kV Jigmeling - Tsirong feeder	Jigmeling SS	Ground failt	Main 1(B ph pick up, zone 1 trip ) Main 2(B ph pick up, zone 1 trip )	14.9km		heavy rainfall, thunder and lightnin
2	05.05.2021	12:22hrs	05.05.2021	12:38hrs		1.29	220kV Jigmeling - Dagapeela feeder	Dagapela S	Ground failt	Main 1(B ph pick up, 20ne 1 trip ) Main 2(B ph pick up, 20ne 1 trip )	main 1 - 15.9km main 2- 13.96km		heavy rainfall, thunder and lightning
3	05.05.2021	12:40hrs	05.05.2021	15:08hrs	2	-11.250	220kV Jigmeling - Tsirang feeder	Jigmoling SS	Ground failt	Main 1 ((R &B ph pick up, zl trip ) Main 2((R &B ph pick up, zl trip )	main 1 - 4km main 2- 3.17km		heavy rainfall, thunder and lightnin
4	05.05.2021	13:59hrs	05.05.2021	14:53hrs	0	1.33	220kV Jigmeling - Dagspeela feeder	Dagapela Si	s	relay general trip			heavy rainfall, thunder and lightuin
5	29.05.2021	09:06 hrs	29.05.2021	09:12 hrs	0	19.44	Jigmeling-	Tingtibi SS	Earthfault	Yphase pick up			No DR and relay tripped not

1	2:40hen	05 05 2021	15-06-56hm	2	17.02	Tierralina for	Dhain: S	Smain Line 1 77K A The COLVA	26 1 82 Dictores relay Main ISH	Main I=22 2km Main II=2	Trinnad	whole Tsirang is bl
	2,40115	00.00.2021	15.00.50ш3		1,7,000	Jigmenng ico	(Dilajay 3	main Pla 1.77 R.A., 10 - 0.01 R.A.	30.1 6c2, Distance Tellay Main 16cil	Main I - 32 Sam, Main II - 3	2 Tripped	whole I shang is o
5.2021	2:50hrs	12,05,2021	17.57hrs	14	0.104	Dagapela-I		Ia-4.105A, Ib-452.8A, Ic-450.2A, In=1.371A	MICOMP122	Line segument	Tripped	Feeder restored aft O&M head ,ESD Dagapela confirme line clerance.
15.2021	11:20hrs	14.05.2021	12:40hrs	1	0.079	Rangthanglin g		Ia=2.25A, Ib=3A, Ic=37.12A, In=34.92A	MICOMP122	Line segument	Tripped	Feeder restored after O&M head ,ESD Tsirang confirmed line clerance.
Substation		<u> </u>										
1/2021	16:00	5/3/2021	16:05	0	16.2700	cv Tingtibi-Nang	Tingtibi-N	Tempoary fault	Distance Protection Relay:Trip phase ABC,Fault Loaction:32.90kM,Fault Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
5/2021	13:57	5/5/2021	14:01	0	12.1000	ev Tingtibi-Nanı	Tingtibi-N	Tempoary fault	Distance Protection Relay: Trip phase ABC, Fault Loaction: 34.7kM, Fault Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
			14:07	0	4.5700	eV Tingtibi-Nan	Tingtibi-N	Tempoary fault	Distance Protection Relay: Trip phase ABC, Fault Loaction: 19.9kM, Fault Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
3/2021	13:57	5/13/2021	14.07									
	15.2021 15.2021 15.2021 15.2021 15.2021 15.2021	Substation 16:00	5.2021 2:50hrs 12,05.2021  5.2021 11:20hrs 14,05.2021  Substation  12,05.2021 15,0021	5.2021 2:50hrs 12.05.2021 17.57hrs  15.2021 11:20hrs 14.05.2021 12:40hrs  Substation  12.05.2021 16:00 5/3/2021 16:05	5.2021 2:50hrs 12.05.2021 17.57hrs 14  5.2021 11:20hrs 14.05.2021 12:40hrs 1  Substation  92021 16:00 5/3/2021 16:05 0	5.2021 2:50hrs 12.05.2021 17.57hrs 14 0.104  5.2021 11:20hrs 14.05.2021 12:40hrs 1 0.079  Substation  92021 16:00 5/3/2021 16:05 0 16.2700			12.05.2021   17.57hrs   14   0.104   Dagapela-I   Dhajay Subsation   Ia-4.105A; Ib-452.8A, Ic-450.2A, In-1.371A   19.2021   11:20hrs   14.05.2021   12:40hrs   1   0.079   Rangthanglin g   Dhajay Subsation   Ia-2.25A, Ib-3A, Ic-37.12A, In-34.92A   In-34.92A	12.05.2021   12.05.2021   17.57hrs   14   0.104   Dagapela-U Substation   12.05.2021   12.40hrs   1   0.079   Rangthanglin   Substation   12.250, In=1.371A   MICOMP122	12.05.2021   12.05.2021   17.57hrs   14   0.104   Dagapela-I   Dagay Subsatio   Ia-4.105A, Ib-452.8A, Ic-450.2A, In-1.371A   MICOMP122   Line segmment	12.05.2021   17.57hrs   14   0.104   Dagapela-I   Dhajay Subsatio   14.05.2021   17.57hrs   14   0.104   Dagapela-I   Dhajay Subsatio   14.05.2021   12:40hrs   1   0.079   Rangthanglin   Dhajay Subsatio   1   12:20hrs   14.05.2021   12:40hrs   1   0.079   Rangthanglin   Dhajay Subsatio   1   12:20hrs   14.05.2021   12:40hrs   1   0.079   Rangthanglin   Dhajay Subsatio   1   12:25A, Ib=3A, Ic=37.12A, Ib=

# June 2021

The	rision	SMD-DEOTHANG		151	N.											
Sui		132/33/118V Kangi	eng Sabstation													
Ma	noth:	Jun 21														
	No.		Type of Oatage	Shutdown	Tripping	Normaliza	tion Time		Duraties of Outage	I I I I I I I I I I I I I I I I I I I	1	Tripping Details	Type/Cause of Fault	Rosson for Shatdown	Weather	Remarky
o.	Name of Feeder	Voltage Level	(Shutdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	MW before Outago (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	Lype-Cause of Fami	Rosson for Shatdown	Condition	Remarks
	33KV Clenery Feeder	32.37	Tripped	16.06.2021	5:22	16.96.2021	6:20	0	55	0.173	Over current	1A-729.2A.IB-714A.IC-15.8LA	Tripped on dailt	Over current	Raining	Feeder tripped owing to o'c cert charge done once but trippint with an fault, informed to Chenery control room.
13	32/33kv Transformer -I (33kv side)	135.51	Tripped	22,06,2021	12:25	22.06.2021	16:31	4	6	9.471	50%	50%	NA	B phase disc insulator puterine	Clear	shudown token by somm Took) offg. substraint incharge inorder to che puncture dies insulator and LA of SMVA tr2 with permit to 1413
	132 kV Phontsbothang	130,52	Tripped	25.06.2021	20158	25.06.2021	20:52	0	14	15.174	NA.	NA NA	NA	NA.	Cloudy	charged the feeder after informed by RPSO
Div	rision	SMB-DEOTHANG	TE .													
Sal	bstation:	132/33/11kV Naugh	or Substation													
310	eeth:	Jun-23			l)											
	Name of Feeder	Voitage Level	Type of Ontage	Shordown	Tripping	Normaliza	tion Time		Duration of Outage	MW before Outago (MW)		Tripping Details	Type Course of Fault	Reason for Shutshown	wommer	200
	Name of Feeder	Vottage Level	(Shutdown/Tripping)	Date	Time	Date	Time	(Hrx)	(Min)	MW before Outago (MW)	Protecton Relay Optd	Fault Details (As recorded by rolay)	Type-Couse of Paul	Reason for Shutflown	Condition	Remarks

2020	40000440000	TARREST TO STATE OF	Type of Ontage	Shordown	Tripping	Normaliz	ation Time		Duration of Outage	(VALUE OF COMPANY AND ASSAULT		Tripping Details	alternation regions	230000000000000000000000000000000000000	ta channel.	2000
L No.	Name of Feeder	Voltage Level	(Shutdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	MW before Outago (MW)	Protecton Relay Optd		Type Couse of Fault	Reason for Shutslown	Condition	Remorks
	Nangkor-Deething Line	132kV	Iripping	6/8/2021	02:21 hrs	6/8/2021	02:33 hrs	0	12	0,43	MICOM P442	Dissurce Relay -Start Ø ABCN, Trip Ø ABC, Start distance element, TOC start, distance element, TOC start, distance element, TOC start, distance element, Pol. Start, Ender, system frequency 40,874 ft, find drarder, 70,15m, Relay trip fine-10,18m, Famil Residon, 6,633 hm towards Deciding LA-681-78, IP-981 AB, US-914-64, VAN-14-831-79 NY-83-840-V, VCN-5-9889, V, Famil reoferance, 1567-520, 18mil 27, 18 remote relay 66	Tripped on forit	×	Heavy minfall with Thunder 8 lightning	
	Narghov-Deothorg Lise	13244	Isiqqirg	6/11/2021	16:20 lua	6/11/2021	16.26 las	0	6	-9.25	MICOM P442	Directional O'C. & EF Reless Tripped O N.  Directional O'C. & EF Reless Tripped O N.  Shari O AN, O'C. start P. I, EF1 start NN-12, sip NN-2-VAB-165.25V, NNC-121.25V, VAS-165.25V, NNC-121.25V, VAS-165.25V, NNC-121.25V, NNC-161.25V, NNC-161	Tripped on finit	s.	Cloudy	lethermed to 809 O. A. charged the finaler after receiving instruction from 809 O. Thirapha.
3.	152/39kV, 9MVA Tif-1	132NV	Tripping	6/13/2021	10:57 hrs	6/13/2021	10:58 les		3	0.58	Non-directional IDMT PROTN relay operated	Fault in Z3.  O/C relay-50C & tripping relay 86 operated	Tripped due to feeder fault	3:	Cloudy	Tripped due to fault on 3.5 kV Wanning Feeder.
4	132/33kV, 5MVA Tv61	132kV	Trippira	6/13/2021	11:27 hrs	6/13/2021	11:28 hrs	0	1	0.43	Non-directional IDMT PROTN relay operated	O/C relay-50C & tripping relay 86 operated	Tripped due to feeder fealt	2	Cloudy	Tripped due to fault on 33kV Wanning Feeder.
5	132/93EV, SMVA THEE	132EV	Tripping	6/18/2021	15:02 bys	6/14/2021	15:50 lex	0		0.37	Non-directional IDMI PROTN relay operated	O.C reby-50A & tripping relay \$6 operated	Tripped due to feeder finalt	8	Clear	Tripped due to fault on JSEV Yarang Feeder.
6	Main grid (Rangio Grid)	132kV	Tripping	6/25/2021	20:10 hm	6/25/2021	20:33 hrs	0	23	55.8	24		OCT blast at Rangia Substitution	(4)	Clear	At 20:53 hrs supply received from Nganglan Substation.

	Division: Salistation: Month:	SMD-DEOTHANG 132/33/11kV Ngang Jun-21	Ann Sekstation													
ía.	Name of Feeder	Voltago Level	Type of Outage (Shatdown/Tripping)	Shutdown Date	Tripping	Normalize Date	ation Time	(Hrs)	Duration of Outage (Min)	MW before Outage (MW)		Tripping Details Fault Details (As recorded by relay)	Type-Cause of Fault	Rosson for Shardown	Condition	Remarks
Т			10000000	1 20000	T	-		-			Micom & IDMT E/F &	The second secon				
	132/33kV 5MVATesasfirmer -1	132kV	Tripping	01.06.2021	19:04	01.06.2021	19:05	0	2	1,335	O/C relay	Earth Foult	Transient/Earth fault		Clear	
	132/33kV 5MVATmusfenner -1	132kV	Tripping	02.06.2021	05:47	02.06.2021	05:54	.0	3	0,975	Micora & IDMT E/F & O/C relay	Earth Fault	33kV Druk GYP freder fault		Clear	Test charged and withstood successfully.
t	182/33EU SMVATransformer -II	13.2kV	120004000	02.06.2021	95:47	02.96.2021	05:55				Micom & IDMT E/F &	Earth Fault	NCT operated for		Clear	
1	182/33EV SSIVATEMISTORINET -II	13260	Tripping	07.06.7021	99:47	92.96.2021	05:55	0			O/C relay	EATE FROM	33kV side		Clear	
ŀ	132/33kV 3MVATransformer -II	132kV	Tripping	03.06.2021	17:32	03.06.2021	17.38	0	- 6	0.861	Micorn de IDMT E/F & O/C relay	Over Carrent	Tripped due to 33kV Panbang Feeder	0.0	Raniny & Thursdersh	on
T	152/33kV 5MVATmusformer -1	132kV	Tripping	08.06.2021	01:37	08.06.2021	01:40	0	3	0,381	Micom & IDMT E/F &	Earli Foult	Tripped due to 33kV		Clear	
+		7 2000			10000	100000000	1000000	-0		(2000)	O'C relay Distance relay Micom		Dechesling Feeder		100000	Namajam-Tinatibi CB operated at Tingtibi end and Namakhor-Deorhana CS
1	Nganghan-Tingtibi	132kV	Tripping	68.06.2021	02:21	08.06.2021	02:27	.0	16	-15.12	P442	Grid Fail	Grid Fail			eperated at Nangidsor end respectively.
	Nganglan-Tunghbi	132kV	Tripping	08.06.2021	92:45	08,08,2021	02:53	0	*	-15.12	Distance relay Micous P443	AR Lockout Tripped Phase ABC Zenel Frequency 49 52th Fasht Duration Fa. Limill Oftens Relay Trip Time 40 1 Smilli olum Fasht Resistance 45.98e/ms Fasht Iceation 40.94m IA - 1.026KA IB - 121.6A IC- 1.09KA VAN- 1.5.52kV VBN- 81.6GkV VCN- 11.59kV	i		Close	500 STATE OF THE S
Т	Ngonglam-Tingtihi	112kV	Tripping	05.06.2021	02:58	08.86.2021	03:01	.0	3	-15.12	Distance relay Micom P444		Orid Fail			Namalam-Imptibi CB operaterated at Tangtibi and & Nangkhor- Deofteng
1	1970700000000000	100000		00.04.3033	10.00	00 05 303 i	20.12	- 6		0.00	Micon & IDMT E/F &	Frank Frank	33kV Decheding		Thunderstrom Clear	operated at Deotlang cud.
-1	132/33kV 3MVATematonner -1	132kV	Tripping	08.06.2021	10:06	08.06.2021	10:13	- 0	13	0.69	O/C relay	Earth Fault	feeder fault		Clear	
	Ngonglom-Tingtihi	132kV	Tripping	08.06.2021	28:29	09.06.2011	08:25	9	50	-20.56	Distance relay Micom P444					
1	Ngunglum-Tingtibi	DW	tripping	11.06.2021	16:19km	11,06,2021	16:50hrs	.0	я	-12.59	Distance relay Miccen 7444	Earth Fanh	Fault lox-66-97km Fault lox-66-97km Fault duration 203-km; Frequency-40-96kg.V AN=0.55kV NDN-7-72kV NCN-76-75k 77.47-10.02kV 183-78 77.48-76-75kV NDN-79-72kV VCN-76-75-72kV VCN-76-75-72kV VCN-76-72kV		Clear	Feeder sharged after condustion with Trighth and NLDC with closing code 1087 covery by medica Kerna Chedra
	182/33kV SMVATesesformer -1	13 2KV	Tripping	14.06.2021	11:49	14.06.2021	11:50	0	1	0.612	Micom & IDMT E/F & O'C relay	Earth Fault	Due to 33kV Decloraling Fooder fradt		Clear	
	132/33kV 3MVATransfumer -1	132kV	Tripping	15.06 2021	02:57	15.06.2021	02:59	- 0.	2	0.453	Micom & IDMT EF & O/C relay	Earth Fault	Duc to 33&V Dechesling Feeder field		Reimy	
	ECP	13.2kV	Tripping	16.06.2021	10:29	16.06.2021	16:30	o	1	12.54		NA.			Clear	Due to the continuous recessor of eith the rain water has average inside the CB cause the CB position sufficience lamp to abnormall not glowing; while see the above problem coordination with SMD maintenance Engs. Incidently C tripped at our end.
	Ngangkao-Tingtihi	1328V	Tripping	18.06.2022	17:09	18,05,2022	19:37	2	40)	30,25	Distance relay Misom P444	Fault Value; 85 opt IA =724.9A   IB =169.8A IC =85.87A   IN =665.7A VAN =45.14kV VBN=77.88kV VCN =75.62kV Fault Zone 3 Fault location 142km	Disc got pinetured at Tragfibi end.		Clear	Supply resorted after completing the Disc changing work at Hingtible and un coordination to IPSO.
	132/33kV 3MVA Franciomer -1	13 2kV	Tripping	18.06.2021	21:22	18.05.2021	21:24	.0	9	1.017	IDMT Earth fault & Over current relay	Over Current	33kV Dechenling feeder fault	Hec	rvy Rainy & Thurste	estroes
1	132/33kV 3MVATmmfomer -1	132kV	hand triped	36.06.2021	18:26	30.06.2021	18:25	0	5	6.807	Micorn & IDMT E/F &		Absertial sound from		Clear	
10	Division: Salistation:	SMD-DEOTHANG 132/53kV Motanga Jun-21	Substation				780000	- 25		4007	O/C relay	INA.	HkV penal		Wester	
4	Name of Fooder	Voltage Level	Type of Outage (Shutdown/Tripping)	Date	Time	Normalize Date	Time	(Hrs)	Duration of Outage (Min)	MW before Outago (MW)	Protection Relay Optid	Tripping Details Fault Details (As recorded by relay)	Type/Course of Fault	Rosson for Shatdown	Condition	Remrks
,	132/33kV Transformer	1326V	Tripping	6/2/2021	9:48	6/2/2021	9:54	0	6	0.13	BACKUP PROTN. RELAY REF615	86A OPTD	OC & EF	_	Normal	Informed BPSO and CB closed from our end at 99:54hrs.
5	Notanga-Deothang line	132kV	Tripping	6/16/2021	2:20	6/16/2021	2:28			-58.84	BACKUP PROTN.	86A & 86B OPTD, K-PH IRIPS	OC & EF		Raining, Threader	Informed BPSO and line extende at 2:28 hrs from our end.
t	ACCUSATION CONTRACTOR		To the the year of			2000000000	2007			20000000	RELAY REF615 BACKUP PROTN	86A & 86B OPTD, ZONE+1 OPTD R-PH		-	and lightening Raining, Thursday	Informed BPSO and with code to NLDC BHT-1119,NLDC India-869 & N
a	Motarga Rangia line	132kV	Tripping	6/16/2021	2:20	6/16/2021	2:45		25	54.59	RELAY REF615	TRIPS	OC & EF	-	and lightening	6376 CB closed from our end at 2:45hrs.
5	Moranga-Deodiang line	112kV	Tripping	6/25/2021	20:38	6/25/2021	20:41		3	+24.5	BACKUP PROTN. RELAY REF615	86A & 86B OPTD	OC & EF	9	Nonnal	Informed BPSO and line extened at 20:01 lins from our end.
H	Motorga-Plaintshothang Line	132kV	Tripping	6/25/2021	20:38	6/25/2021	20:46			-9.06	BACKUP PROTN.	86A & 86B OFID	OC & EF		Nomal	infromed 8PSO and charged the line at 20:46hrs from our ead:
ŕ					2,000						RELAY REPORT MAIN DISTANCE					Informed BPSQ, as instructed to closed the CB with code NLOC BHT-11:
3	Motonga-Rangio line	13 2 kV	Tripping	6/25/2021	20:38	6/23/2021	11:48	3	10	9.35	MAIN DISTANCE. PROTN. RELAY REL650	86A & 868 OFID	OV/UV	E	Nomal	India-1461 & NERLDC-4907 CB closed at 11:48hrs from our en-
3	Motonga-Rongio line	13 2 kV	Tripping	6/26/2021	120	6/26/2021	2:27	i	1	9.35	Hand tripped	÷	(3)	55	Nomal	As per the SPSO instruction CB hand tripped and kept under shardown do problem at Rangia and, BPSO instruct to close CB with code no. NLDC 1160 NLDC India-1465 and NERLDC-4913 CB closed at 2:27hrs from a

	Division:	SMD-DEOTHANG	1													
	Sabstation:	122/33kV Curbing	Salistation		1											
	Months	Jun-21	Distriction .	_	1											
No.	Name of Feeder	Voltage Level	Type of Outage	Shutdown	Tripping	Normaliza	tion Time	D	teration of Outage	MW before Outage (MW)		Tripping Details	Type/Cause of Fault	Rosson for Shatdown	Condition	Remarks
c. 10.	Value of Access.	v seeinge Level	(Shutdown/Tripping)	Date	Time	Date	Time	(Hrs)	(Min)	saw betore Outago (sew)	Protecton Roby Opid	Fault Details (As recorded by riday)	Section removes comme	ACOMOR TO PSERCHOWN	Antenth	Remires
1	152 kV Khilikhar-Corbung Line	132 EV	Incomming supply fail	25.06.2021	20:08 hrs	25.06.2021	20:38 hrs	0	20	21.160	Nil	There was no incomming supply due to grid fail	Grid fail		Clear	At 20.05 hrs Incomming supply from thillian substation fall and Corling substation was bickout but no bresier tripping has occoured at Corling substation
		SMD-DEOTHANG														
		132/33kV Phontshi Jun-21	thang Salestation				-								Womber	
	Saintations	132/33kV Phoetsho		Shutdown Date	Tripping Time	Normaliza Date	tion Time		turation of Outage (Min)	MW before Outago (MW)	Protection Relay Opid	Tripping Details  Fault Details (As recorded by relay)	Type-Cause of Fault	Rosson for Shutdown	Condition	Remarks
	Salistations Month:	132/33kV Phontshi Jun-21	thing Salistation  Type of Outage							MW before Outingo (MW)	Protecton Relay Opid	Fault Details (As recorded by relay)	Type-Cause of Fault	Reason for Shatdown	Condition	Remarks
	Salistations Month:	132/33kV Phontshi Jun-21	thing Salistation  Type of Outage		Time					MW before Outage (MW)	Protecton Relay Optol  UV/OV Trip		Type Cause of Fault	Resson for Shutdown  Not available	Condition	Remarks  Hes charged silve after called escrive from RPSO

. No.	220/132/33kV Jigmeling Subs  Date of Tripping	Time of Outages/ Time of Tripping	Date of Normalization	Time of Fault was Cleared	Duration of Outages (Hrs)	MW before Outage (MW)	Name of feeder	Name of the Substati on/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Type of outages	Remarks
6kV	Above									/-			
	2-Jun-21	21:16 hrs	2-Jun-21	21:39 hrs	0	-205.00	400kV MJ 2			Distance Relay: SIPROTECT 78A52 & SIPROTECT 78A611	Main-1: Tripped on RYB, Zone-1, Fault Location: 15.03km Main-2: Tripped on RYB, Fault Location: 16km	Transient	
	3-Jun-21	15:34hrs	3-Jun-21	15:44hrs	:0	196.34	400kV MJ 2			Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA611	Fault loop L2L3, Zone 1 trip. Fault distant (25.0km)	Transient	
	15-Jun-21	01:46 hrs	15-Jon-21	02:41 hrs	0	303.24	400kV Interior to Alipurduar ckt-1	1		Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA611	Main-1; YBph pick up and Z1 & Z1B trip. Fault distance 130 7km. Main-2; YBph pick up and Z1 & Z1B trip. Fault distance 128 9km.	Phase-Phase fault, Main-1; Ia=0.43kA, Ib=1.31kA, Ic=1.07kA. Main-2; Ia=0.44kA, Ib=1.3kA, Ic=1.08kA	
	15-Jun-21	01:46 lus	15-Jun-21	05:21 hrs	3	303:24	400kV Interior to Alipurduar ekt-2			Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA611	Main-1; YBph pick up and Z1 & Z1B trip, Fault distance 130 lkm. Main-2; YBph pick up and Z1 & Z1B trip. Fault distance 130 0km.	Phase-Phase fault, Main-1; Ia=0.43kA, Ib=1.31kA, Ic=1.07kA. Main-2; Ia=0.44kA, Ib=1.3kA, Ic=1.08kA	
	15-Jun-21	02:41 hrs	15-Jun-21	03:52 hrs	1		400kV MJ 1 & MJ3			Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA612	ov		
	19-Jun-21	16:42 hrs	19-Jun-21	17:13hrs	0	-292.33	400kV MI3			Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA611	Fault dist(8.4km)	Fault Loop(L1-G)	
	28-Jun-21	15:50 hrs	28-Jun-21	15:50 hrs	0	204.25	400kV Quad moose Alipurduar Line-2			Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA611	Main-1; Rph pick up and Z1 & Z1B trip. Fault distance 70.1km. Main-2; YBph pick up and Z1 trip. Fault distance 74.5km.	Ia-1.86kA	

29	9-Jun-21	06:23 hrs	29-Jun-21	07:36 hrs	1	-21.81	500MVA ICT			7SJ8031-5EB90-IFC0/DD, SIPROTECT 7UT61	67/67N trip		
25	9-Jun-21	15:56 hrs	29-Jun-21	15:56 hrs	0	204.25	400kV Quad moose Alipurduar Line-2			Distance Relay: SIPROTECT 7SA52 & SIPROTECT 7SA611	Main-1; Yph pick . Fault distance 63.9km. Main-2; Yph pick. Fault distance 63.1km.		
6-	Jun-21	11:53 hrs	7-Jua-21	12:17 hrs	0	0.94	220kV Dagapela Feeder			Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; YBph pick up and Z1 trip. Fault distance 7.7km. Main-2; YBph pick up and Z1 trip. Fault distance 7.07km.	Fault Loop (1.2 & 1.3), 1a=0.02kA, 1b=2.53kA & Ie=2.53kA	<u>.</u>
7-	Jun-21	00:43 hrs	7-Jun-21	00:54 hrs	0	0.94	220kV Dugapela Feeder			Distance Relay: SIPROTECT 7SA52 & REL670	Main-1: Tripped on RYN, Zone-1, Fault Location: 7.7km Main-2: Tripped on RYN, Zone-1 & 2 Fault Location: 7.07km	Fault Loop (L1 & L2), 1a=2.46kA, lb=2.45kA & Ic=0.02kA	
7-	Jun-21	08:27 hrs	7-Jun-21	08:41 hrs	0	1.31	220kV Dagapela Feeder			Distance Relay: SIPROTECT 78A52 & REL670	Main 1 = Tripped on RYN, Zone 1, Distance. Distance Main-1=7,7km, Main- 2=7,11 km	Ia-2.5KA, Ib-2.5kA, Ic-0.02kA	
7-	-Jun-21	09:31 hrs	8-Jun-21	13:35 hrs	28	1.31	220kV Dagspela Feeder			Distance Relay: SIPROTECT 78A52 & REL670	Main 1 = Tripped on RYN, Zone 1. Main-1=7.7km, Main-2=7.4 km	In-2.5KA, Ib-2.5kA, Ic-0.02kA	
12	2-Jun-21	08:34 hrs	12-Jun-21	10:16 hrs			Bus-coupler				50/51N		
10	2-Jun-21	10:04 hrs	12-Jun-21	10:16 hrs	0	-133.14	80 MVA ICT- 1			7SJ8022-5EB90-1FA0/CC & 7SJ8041-5EB90-1FC0/CC	50/51N, WTI LV tripped	Over load	
- 2	2-Jun-21	10:59 hrs	12-Jun-21	11:13 hrs			Bus-coupler				50/51N		
12	2-Jun-21	11:47 hrs	12-Jun-21	12:21 hrs			Bus-coupler				50/51N		
15	8-Jun-21	17:00 hrs	18-Jun-21	17/23 hrs	0	51.89	80MVA ICT 1 & 2			78J8022-5EB90-1FA0/CC & 78J8041-5EB90-1FC0/CC	LV SEF trip, 50N-1 trip		
19	9-Jun-21	16:42 hrs	19-Jun-21	16:48 hrs	:0	ICT-1: -35.5, ICT-2: -35.6	80MVA ICT 1 & 2			7SJ8022-5EB90-1FA0/CC & 7SJ8041-5EB90-1FC0/CC	Relay Gen.trip. LV SEF trip.		
25	9-Jun-21	05:35 hrs	29-Jun-21	05:52 hrs	0	1.1	220kV Dugapela Feeder			Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; Y,Bph and Z1 trip. Fault distance 7.4km. Main-2; Y,Bph and Z1 trip. Fault distance 7.12km.	Fault loop (L2L3)	
25	9-Jun-21	06:25 hrs	29-Jun-21	06:37 hrs	0	1.76	220kV Dagapela Feeder			Distance Relay: SIPROTECT 7SA52 & REL670	Main-2 optd; YBph pick up and Z1 trip. Fault distance 7.08km. Main-1 optd YBph pick up and Z1 trip. Fault distance 7.5km.	Fault loop (L2L3)	
3.	-Jun-21	18:39 hrs	3-Jun-21	18:44 hrs	0	13.76	132kV Gelephu Feeder			Distance Relay SIPROTECT 7SA52 & REL 670	Fault loop 1.11.21.3, Zone 1 wip.	Transient	
14	5-Jun-21	02:41 hrs	15-Jun-21	02:53 hrs	0	0	132kV Tingribi			Distance Relay SIPROTECT 75A52 & REL 670	Fault dirtant (20.3lan)  Main-1; RYBph pick up		
-	8-Jun-21	17.09 hrs	18-Jun-21	19.35 hrs	2	40.67	Feeder 132kV Tingritis Feeder				Main-1; Rph pick up Falt Dist(75.9km)	Fault Loop(L1-E) Fault current L1-1.3kA.	
	6/33kV Dhajay Substation	S-110 - 110	255 (1771) (1770)				p				2000(12.78M)	ace a recomposition to the statute of AMORA	
	and above	02:05hrs	14 06 2021	03-16hm		0 67	Namelia C.	Marian m		rates that and a state to		The state of the s	and of the Parkers of the
	5.06.2021	02:05hrs 8:41:07HRS	15.06.2021	02:16hrs 8:54:37hrs		94.36	Jigmeling fees I Dagachu feed I			9.2586.1 &2, relay Main II 9K' 86.1 &2, relay Main II		Tripped Tripped	whole Tsirang is I whole Tsirang is I
32/66	i/33/11kV Gelephu Substatio		19.00.2021	0.24,37118		5-4.30	radigacian reeds 1	onajay S	South 11- 10-0, 1004, 141.	70, 00.1 0.2, Italy Main ii		Апррия	whole I shang is o
6kV a	and above	1				_				1			T 4 4 4 4 7 5
	03.06.2021	18.40hrs	03.06.2021	19:27		12	el-Salakati & b	lackout f	bed weather	No CB & relay operatted at our end	Salakati line	Temporary	Auto reclosed fro Jigmeling ss at 18.43hrs
3	04.06.2021	11.32hrs	04.06.2021	18.23hrs	6	5.4	132kv Gel-Jel	non	Shutdown by Salakati as	non	Salakati line	Temporary	Charging code NL BTN=1035,NLDC IND=215,NERLD 3194

) 66 kV an	ol Aboro						1			1		100	
1	6/8/2021	2:20	6/8/2021	8:18	5	16.6600	cV Tingtibi-Nan	Tingtibi-N	Tempoary fault	Distance Protection Relay:Trip phase ABC,Fault Looction:64.49kM,Fault Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
2	6/11/2021	16:20	6/11/2021	16:40	0	17.5700	cv Tingtibi-Nan	Tingtibi-N	Temposity fault	Distance Protection Relay: Start Phase: N, Trip phase ABC, Fault Loaction: 20.14kM, Fault Zone- 1.	132kV Tingtibi-Nanglam	Tempoary	
3	6/15/2021	1:46	6/15/2021	2:02	0	42.2600	eV Tingtibi-Nan	Tingtibi-N	Tempoary fault	Distance Protection Relay: Start Phase: ABC, Trip phase ABC, Fault Loaction: 2.013kM, Fault Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
4	6/15/2021	1:46	6/15/2021	2:38	0	-44.5700	cV Tingtibl-Jigm	(Tingtibi-Jij	t Tempoary fault	Distance Protection Relay: Start Phase: ABC, Trip phase ABC, Fault Loaction: 8. 792kM, Fault Zone-1.	132kV Tingtibi-Jigmeling	Tempoary	
5	6/18/2021	17:15	6/18/2021	19:36	2	-34.1300	d Tingtibi-Jigm	Tingtibi-Ji	32kV Main Bus R phase insulator fai	Distance Protection Relay: Start Phase: AN, Fault Loaction: -403.2M, Fault Zone- 4	132kV Tingtibi-Jigmeling	Insulator Fail	
6	6/18/2021	17:15	6/18/2021	19:37	2	31.3200	cv Tingtibi-Nan	Tingtibi-N	32kV Main Bus R phase insulator fail	Distance Protection Relay:Trip phase AN,Fault Loaction: 769.7M,Fault Zone-4.	132kV Tingtibi-Nanglam	Insulator Fail	
	V Yurmoo Substation												
) 66kV &	06.2021	0.512000000	10.06.2021	0.05215222	9.	0.0	***************************************	r v	T. 1	V-0	T1 (1.10		D
	V Dagapela Substation	0.713888889	18.06.2021	0.85347222	3	3.2	132kV Tingti	t Yurmoo:	Insulator puncture at Tingtibi Ss	Nill	Tingtibi Ss		Restored after comple
66kV &													
	.06.2021	0.086805556	15.06.2021	0.09722222	0	-0.64	220KV Dagag	Disagneli	over voltage	86 A, 86B,V>1		Transient Fault	feeder tripped on ove

# July 2021

							N	IONTHLY OUTAG	E REPORT FOR T	HE MONTH OF JULY UNDER SM	ID DEOTHANG, TD, BPC.		
	Division:	SMD-DEOTHANG 132/33/11kV Nangkor Substation											
1	Substation:												
	Month:	Jul-21											
	10 mg	500000	Type of	Shutdow	n/Tripping	pping Normalization Time		Daration of	1	Fripping Details			
Sl. No	Name of Feeder	Voltage Level	(Shutdown (Tripping)	Date	Time	Date	Time	(Hrs)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
132kV	Feeders												
1	132/33kV, 5MVA Trf-I	132kV	Tripping	7/2/2021	00:19 hrs	7/2/2021	00:23 hrs	0	Non directional IDMT PROTN Relay operated	O/C relay-50A & tripping relay 86 operated	Tripped due to feeder fault		Tripped due to to fault on 33kV Tsebar feeder
2	132/33kV, 5MVA Trf-II	132kV	Tripping	7/2/2021	00:19 hrs	7/2/2021	00:24 hrs	0	Non directional IDMT PROTN Relay operated	O/C relay-50A & tripping relay 86 operated	Tripped due to feeder fault	is a	Tripped due to fault on 33kV Tsebar feeder
3	132/33kV, 5MVA Trf-I	132kV	Tripping	7/2/2021	00:45 hrs	7/2/2021	09:35 hrs	8	Non-directional IDMT PROTN relay operated	O/C relay-50C & tripping relay 86 operated	Tripped while test charging of 33kV Tsebar feeder	N.F	Kept under shut down due to spark observation from LV side Isolator.
4	132/33kV, 5MVA Trf-II	132kV	Tripping	7/2/2021	00:45 hrs	7/2/2021	01:50 hrs	1	Non-directional IDMT PROTN relay operated	O/C relay-50C & tripping relay 86 operated	Tripped while test charging of 33kV Tsebar feeder		Delayed in charging due to rainfall.
5	132/33kV, SMVA Trf-I	132kV	Tripping	7/5/2021	09:39 hrs	7/5/2021	09:44 hrs	0	Non-directional IDMT PROTN relay operated	O/C relay-50A & tripping relay 86 operated	Tripped due to feeder fault		Tripped due to fault on 33kV Tsebar feeder
6	132/33kV, 5MVA Trf-II	132kV	Tripping	7/13/2021	14:22 hrs	7/13/2021	14:27 hrs	0	Non-directional IDMT PROTN relay operated	O/C relay-50A & tripping relay 86 operated	Tripped due to feeder fault	ii.	Tripped due to fault on 33kV Yurung feeder
7	132/33kV, 5MVA Trf-II	132kV	Tripping	7/13/2021	15:14 hrs	7/13/2021	15:19 hrs	0	Non-directional IDMT PROTN relay operated	O/C relay-50A & tripping relay 86 operated	Tripped due to feeder fault	Æ	Tripped due to fault on 33kV Yurung feeder

	Division:		D-DEOTHA											
2	Substation: Month:	132/33/11k	V Nganglan Jul-21	Substation										
	, vacuum.		341.71											
9779420	Name of	Voltage	Outage	Shutdown	/Tripping	Norm	alization Time	Duration of		Tripping Details		27 27 1 M - 1 - 28 27 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2000000000	
L No.	Feeder	Level	(Shutdown	Date	Time	Date	Time	(Hrs)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks	-
32kV									1000000				T	
1	Nganglam-Tingtibi	132kV	Tripping	07.07.2021	10:27	11.07.2021	12:34	97	Micom relayP442	Fault Value IA= 382.4A IB=88.96A IC=101.2A IN=481.2A	Earth Fault (R-PH to Ground)		Test charged vide closing code# 1300 from both end but tripped on same fault. Fault was located towards TN#124- TN#125 where decapping of Disc insulator has caused	
2	Nganglam-Tingtibi	132kV	Tripping	21.07.2021	12:00	21.67.2021	12:12	р	Micom relayP442	(O'C trip, & 86epted, Fault location- 135 0km, Zone-3, Fault resistance- 1750 oms, System frequency-50.0Hz, Frult duration-79.94ms )LA=58.67A, IB=858.4A IC=945.6A, VAN 118.9kV, VBN=51.84kV, VCN= 110.4kV	Over Current		Supply restored after coordination to BPSO and Tingtibi end with vide Switch ON code# 1322 issued by Mr. Sungay BPSO/Ihmghu	
80	Division:		D-DEOTHA		l,									
3	Substation:	132/33kV	Motanga S	abstation										
	Month:		Jul-21	-										
		Lorenza march	rype or	Shutdown	Tripping	Norm	alization Time	Duration of		Cripping Details	1		-	
L No.	Name of Feeder	Voltage Level	Outage (Shutdown	Date	Time	***	(Hrs)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks		
						1			Viii (8)		t :: :::::::::::::::::::::::::::::::::			
£	132/33kV Trans	132kV	Tripping	7/8/2021	9:42	7/8/2021	9:50	0	BACKUP PROTN. RELAY REF615	86A OPTD	OC & EF	8.	CB closed at 09:50 hrs from our end.	
6	132/33kV Trans	132kV	Tripping	7/15/2021	6:12	7/15/2021	6:18		BACKUP PROTN. RELAY REF615	86A OPTD,Protection tripped	OC & EF	91	CB closed at 6:18hrs from our end.	
9	132kV Rangia fe	132kV	Tripping	7/20/2021	12:36	7/20/2021	12:55		PROTECTION RELAY	86A &86B OPTD	OC & EF	-	CB closed at 12:55hrs from our end.	
11	132/33kV Trans	132kV	Tripping	7/27/2021	12:59	7/27/2021	13:02		BACKUP PROTN. RELAY REF615	86A OPTO	OC & EF	2	CB closed at 13:02hrs from our end.	
400/2	20/132/33kV Jig	manage Superior	station								1			
L No.	Date of Tripping	Time of Outages/ Time of Tripping	Date of Normaliza tion	Time of Fault was Cleared	Duration of Outages (Hrs)	Outages (Min)	MW before Outage (MW)	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Type of outages	Remarks
100k	V													
1	2-Jul-21	00:14 hrs	2-Jul-21	00:41 hrs	0	27	-78.01	500MVA ICT	-78.01	67/67 TOC A Pickup, 67/67 TOC B Pickup	7SJS031-5EB90-IFC0/DD, SIPROTECT 7UT61			ICT tripped along with tripping of 220kV Dagapela Line
2	2-Jul-21	01:34 hrs	2-Jul-21	07:40 hrs	6	14	-21.81	500MVA ICT	-21.81	67/67 TOC A Pickup, 67/67 TOC B Pickup, 50Ns - 1/2 trip	7SJ8031-5EB90-IFC0/DD, SIPROTECT 7UT61			ICT tripped along with tripping of 220kV Dagapela Line and ICT kept shutdown as per BPSO instruction
4	10-Jul-21	12;49 hrs	10-Jul-21	13:46 hrs	0	57	-78.33	500MVA ICT	-78.33	67/67N HV	7SJ8031-5EB90-IFC0/DD, SIPROTECT 7UT61			
5	10-Jul-21	12;49 hrs	10-Jul-21	12:49 hrs	0	0	MJ1-290.15 & MJ3- 290.88	MHPA Line 1 & 3	MJ1-290.15 & MJ3- 290.88	MJ1; Bph pick up. Fault distance 7.7km. MJ2; Bph pick up and Z1 trip.	SIPROTECT 7SA52, SIPROTECT 7SA611			Line auto reclosed at 1,396s

20 k	7													
1	2-Jul-21	00:14 hrs	2-Jul-21	00:22 hrs	00:14 hrs	0	0.91	220kV Dagapela Feeder		Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; RYph pick up and Z1/Z1B trip. Fault distance 7.4km. Main-2; RYph pick up and Z1 trip. Fault distance 7.2km.		Fault Loop (L1 & L2), Ia=7.23kA, Ib=7.21kA & Ie=0.02kA	
25	2-Jul-21	00:30 hrs	2-Jul-21	00:37 hrs	00:30 hrs	0	0.91	220kV Dagspela Feeder		Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; R.Yph pick up and Z1/Z1B trip. Fault distance 7.6km. Main-2; R.Yph pick up and Z1 trip. Fault distance 6.98km.		Fault Loop (L1 & L2), L=2.7kA, lb=2.68kA & le=0.02kA	
3	2-Jul-21	01:10 hrs	2-Jul-21	01:20 hrs	01:10 hrs	0	0.87	220kV Dagspela Feeder		Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; R.Yph pick up and Z1/Z1B trip. Foult distance 7.5km. Main-2; R.Yph pick up and Z1 trip. Fault distance 7.20km.		Fault Loop (L1 & L2), Is=7.25kA, Ib=4.24kA & Ic=0.02kA	
4	2-Jul-21	01:34 hrs	3-Jul-21	14:18 hrs	01:34 hrs	35	0.87	220kV Dagspela Feeder		Distance Relay: SIPROTECT 7SA52 & REL676	Main-1; RYph pick up and Z1/Z1B trip. Foult distance 7.6km. Main-2; RYph pick up and Z1 trip. Fault distance 7.02km.		Fault Loop (L1 & L2), Is=2.69kA, Ib=2.68kA & Ic=0.02kA	Line decleared faulty
5	20-Jul-21	04:31 hrs	20-Jul-21	04:42 hrs	04:31 hrs	o.	0.87	220kV Dagapela Feeder		Distance Relay: \$IPROTECT 7\$A\$2 & REL670	Main-1; Y&Bph pick up and Zltrip. Fault		Fault Loop (L1 & L2), Ia=0.02kA, Ib=7.39kA & Ie=7.39kA	
6	28-Jul-21	16:59 hrs	28-Jul-21	17:23 hrs	16:59 hrs	0	-99.52	220kV Tsirang Feeder		Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; R&Bph pick up and Zltrip. Fault		Fault Loop (L1 & L3), In=3.89kA, Ib=0.30kA & Ie=4.26kA	Line charged as per BPSO coe 1374 , Phub Zum
7	28-Jul-21	16:59 hrs	28-Jul-21	17:25 hrs	16:59 hrs	0	0.92	220kV Dagapela Feeder		Distance Relay: SIPROTECT 7SA52 & REL670	Main-1; Bph pick up and Z1trip. Fault		Fault Current Ia=3.62kA, Ib=0.01kA & Ic=3.70kA	Line charged as per BPSO coo 1375 , Phub Zam
	6/33/11kV Gel	phu Substat	ion								Tourseller Transfer		-10	
66kV	and above							4			p		4	
1	22.07.2021	13.50hrs	22.07.202 1	14.22hrs		32	30	kv Gelephu-Jigmelin	100	Emergency s/d by Salakati ss	No CB opperated at our end	Jigmeling line	Temporary	No CB opperated at our er
2	23.07.2021	11.27hrs	23.07.202	13.06hrs		39	22.6	tkv Gelephu-Salakati	19001	bamboo cutting		Salakati line	Temporary	Charging code NLDC BTN=1344, NLDC IND=1204,NERLDC=617
3	31.07.2021	06.15hrs	31.07.202 1	15.38hrs	9	23	19.4	kv Gelephu-Salakati	Non	Y-Ph conductor snaped from main bus at Salakati Substation.	General trip,fuse failZone I,Y- phase,Dist.43.23km,Differencial relay,RY- ph. Fault current=R=320.4A,Y=1496.54A,B=242.6 5A,IN=934.57A.	Salakati line	Temporary	Charging code NLDC BTN=1398, NLDC IND=1629,NERLDC=649
	3/11kV Tintibi S	Substation												
66 K	and Above										Distance Protection Relay:Trip phase			
1	7/7/2021	10:27	7/11/2021	12:40	98	13	13.6100	132kV Tingtibi-Nanglan	132kV Tingtibi-Nanglam	Insulator failed	ABC, Start phase : AN, Fault Loaction: 19.98kM, Fault Zone-1.	132kV Tingtibl-Nanglam	Line fault	
2	7/21/2021	11:59	7/21/2021	12:13	0	14	38,4500	132kV Tingtibi-Nanglan	132kV Tingtibi-Nangjarr	Tempoary Fault	Distance Protection Relay:Trip phase ABC,Start phase :BC,Fault Loaction:7.605kM,Fault Zone-1.	132kV Tingtibi-Nanglam	Lirie fault	
	3kV Dagapela	Substation												
561-V	& Above													
UUL	15.06.2021	0.086806				15	-0.64		Dagapela Substation		86 A. 86B.V>1 -		Transient Fault	feeder tripped on or

# August 2021

0.00	Division:		D-DEOTH/	DAILURA .	Š.									
Sı	A STATE OF THE PARTY OF THE PAR	132/33/111	V Kanglung	Substation										
	Month:		Aug-21	-	9									
			Type of	Shutdown	Tripping	Normal	ization Time	Duration	of Outage	Trippin	g Details			
il. No.	Name of Feeder	Voltage Level	Outage (Shutdown	Date	Time	Date	Time	(Hrs)	(Min)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
32kV	Feeders		Transmiss allow	/IX	la .	Te. 11	- 17		Ti.		å .	(/		
1	132kvCoriun	132kv	triped on faul	7.08.2021	12:39	7.08.2021	12:57	0	18	relay 86 operated	NA	Trop on fault	Faulty	132kV breaker trip due to outgoing feeder faulty.
	Division:	SM	D-DEOTH/	ANG		V						5		9
St		132/33/111	V Deothan	g Substation										
	Month:		Aug-21											
-			Type of	Shutdown	/Tripping	Normal	ization Time	Duration	of Outage	Trinnin	g Details			
sl. No.	Name of Feeder	Voltage Level	Outage (Shutdown		Time	Date	Time	(Hrs)	(Min)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
120			A 600 H 50 D 60 - 2 1 A 5 V	•	2	1.0			7.	- th		2.		
1	XMER 2	132/33KV	Trip	18.08.2022	11:20	18.08.2022	11:30	0	10	5000	Nill			Trip due to low air pressure & card loose.
2	XMER 2 Division:	132/33KV	Trip D-DEOTH/	18.08.2023	12:17	18.08.2023	12:22	0	5	86				Trip by S/J feeder.Charged & found normal
S.		000000	V Nganglan											
	Month:	10200111	Aug-21	a Jungtation										
man make i	Name of	Voltage	Outage	Shutdown	/Tripping	Normal	ization Time	Duration	of Outage		g Details			1.0000000000000000000000000000000000000
SL No.	Feeder	Level	(Shutdown	Date	Time	Date	Time	(Hrs)	(Min)	Protecton Relay	Fault Details (As	Type/Cause of Fault	Reason for Shutdown	Remarks
			(Talantas)	A SHEE	Time	Date	X IIII C	(1113)	(ivalia)	Optd	recorded by relay)			
32kV			(Televise)	Jane 1	Time	Date	Time	(iii s)	Creaty	Optd	recorded by relay)			
	gkhor-Nganş	132kV	Tripping	06.08.2021	12:39	06.08.2021	12:44	0	5	Optd  Micom relayP442	recorded by relay)	Due to seepage of Rain water inside the CB box that might have caused/lend to tripping of CB.		CB operated at our end only. Supply was restored after coordination to BPSO & Tingtibi end.
	gkhor-Ngang anglam-Ting		70.05						# W W W W W W W W W W W W W W W W W W W			inside the CB box that might have		CB operated at our end only. Supply was restored afte coordination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored afte coordination to BPSO & Tingtibi end.
1		132kV	10.00	06.08.2021	12:39	06.08.2021	12:44	0	35	Micom relayP442	NA	inside the CB box that might have caused/lead to tripping of CB.  Due to seepage of Rain water inside the CB box that might have		coodination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored after
2	anglam-Ting	132kV	Tripping	06.08.2021 11.08.2021	12:39 02:58	06.08.2021	12:44	0	5	Micom relayP442 Micom relayP442	NA NA	inside the CB box that might have caused/lead to tripping of CB.  Due to seepage of Rain water inside the CB box that might have		coodination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored afte coodination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored afte coodination to BPSO & Tingtibi end.
2	anglam-Ting	132kV 132kV 132kV	Tripping Tripping Tripping	06.08.2021 11.08.2021 17.08.2021	12:39 02:58 04:00	06.08.2021 11.08.2021 17.08.2021	12:44 02:59 04:05	0 0	5	Micom relayP442 Micom relayP442 Micom relayP442	NA NA NA	inside the CB box that might have caused/lead to tripping of CB.  Due to seepage of Rain water inside the CB box that might have caused/lead to tripping of CB.  Due to seepage of Rain water		coodination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored afte coodination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored afte coodination to BPSO & Tingtibi end.  CB operated at our end only. Supply was restored afte

Sı	Division:		Motanga S											
	Month:		Aug-21	and the same of th										
			type or	Shutdown	/Tripping	Norm	alization Time	Duration	of Outage	Trionin	g Details			J.,
l. No.	Name of Feeder	Voltage Level	Outage (Shutdown	200	Time	Date	Time	(Hrs)	(Min)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
1	132kV Rang	132kV	Tripping	8/5/2021	12:06	8/5/2021	13:16	1	10	MAIN DISTANCE PROTN, RELAY- REL650	86A & 86B OPTD	OV&UV OPTD	-	Infromed BPSO, as instructed to closed CB with code NLDC BHT-1408,NLDC India-208 and NERLDC-6689 13:16 hrs from our end.
2	132kV DMI	132kV	Tripping	8/6/2021	15:40	8/6/2021	16:04		24	MAIN DISTANCE PROTN. RELAY- REL650	86A OPTD,Protection tripped	OV&UV OPTD. R&Y&B TRIP	=	CB closed at 16:04hrs from our end.
3	33kV POP I	33kV	Shutdown	8/8/2021	9:33	8/8/2021	10:06		33	HAND TRIPED	2	<u>=</u>	To replace fuse	Shutdown taken by ESD to replace fues at their end an line charge at 10:06hrs from our end
4	132kV Deo	132kV	Tripping	8/12/2021	5:23	8/12/2021	5:46		23	MAIN DISTANCE PROTN. RELAY- REL650	86A & 86B OPTD	OV & UV OPTD	-	Tripped due to voltage shooting to 141.08kV informed BPSO and line charged at 5:46hrs from our end.
5	132kV Rang	132kV	Tripping	8/12/2021	5:23	8/12/2021	5:50		27	MAIN DISTANCE PROTN, RELAY- REL650	86A & 86B OPTD	OV & UV OPTD	9	Tripped due to voltage shootup to 141.08kV informed BPSO and line charged at 5:50hrs from our end with cov NLDC BHT-1449,NLDC India-572 and NERLDC-6962
6	132kV DMI	132 <b>k</b> V	Tripping	8/12/2021	5:23	8/12/2021	6:24	1	1	MAIN DISTANCE PROTN. RELAY- REL650	86A & 86B OPTD	OV & UV OPTD	=	Tripped due to voltage shootup to 141.08kV informed BPSO and line charged at 6:24hrs from our end.
7	132kV Phur	132kV	Tripping	8/12/2021	5:23	8/12/2021	6:27	1	4	MAIN DISTANCE PROTN, RELAY- REL650	86A & 86B OPTD	OV & UV OPTD	ā	Tripped due to voltage shootup to 141.08kV informed BPSO and line charged at 6:27hrs from our end.
8	33kV Azista	33kV	Shutdown	8/16/2021	16:11	8/16/2021	16:34		23	HAND TRIPED	2		To remove jumpering at their end.	CB closed at 16:34hrs from our end.
9	15MVA Tra	132/33kV	Tripping	8/26/2021	10:03	8/26/2021	10:04		1	Differential Realy RET 650 Operated	SEF protn optd.	-	-	CB closed at 10:04hr from our end.
10	Rangia Fee	132kV	Tripping	29:08/2021	14:06	29:08/2021	14:50		44	MAIN DISTANCE PROTN, RELAY- REL650	86A & 86B OPTD	OV/UV	9	Informed BPSO, as instructed to closed CB with code NLDC BHT-1535,NLDC India-1797 and NERLDC-7627 14:50hrs from our end.
11	Rangia Fee	132 <b>k</b> V	Tripping	29:08/2021	15:37	29:08/2021	16:51	1	14	MAIN DISTANCE PROTN. RELAY- REL650	86A & 86B OPTD	ov/uv	F	Informed BPSO, as instructed to closed CB with code NLDC BHT-1536,NLDC India-1812 and NERLDC-7633 16:51hrs from our end.
l. No.	Date of Tripping	Time of Outages/ Time of Tripping	Date of Normaliza tion	Time of Fault was Cleared	Duration of Outages (Hrs)	Duration of Outages (Min)	MW before Outage (MW)	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Type of outages	Remarks
66kV										7SJ8031-5EB90-				
1	500MVA IC	400/220kV	Tripping	0:00	07:49 hrs	44420	07:55 hrs	6	-41.72	1FC0/DD, SIPROTECT 7UT61	No relay indication			
2	500MVA IC	400/220kV	Tripping	24-Aug-21	20:58 hrs	44432	21:04 hrs	6	-23.34	7SJ8031-5EB90- 1FC0/DD, SIPROTECT 7UT61	50Ns 1/2 tripped			
3	500MVA IC	400/220kV	Tripping	0:00	22:45 hrs	44432	23:39 hrs	54		7SJ8031-5EB90- 1FC0/DD, SIPROTECT 7UT61	50Ns 1/2 tripped			
4	500MVA IC	400/220kV	Tripping	0:00	23:54 hrs	44432	12:47 hrs			7SJ8031-5EB90- 1FC0/DD, SIPROTECT 7UT62	50Ns 1/2 tripped			
5	400kV Quad	400kV	Tripping	0:00	01:58 hrs	44434	01:58 hrs	0	306.9	SIPROTECT 7SA52, SIPROTECT 7SA611	Main-1; Rph to ground pick . Main-2; Rph to ground pick .	Fault distance 155.9km		
	220kV Tsira: 80 MVA ICT	220kV 220kV	Tripping Tripping	0:00	15:47 hrs	44415	16:37 hrs	50	-74.19 -23.98	Distance Relay: SIPROTECT 7SAS2 & REL670 86.1/86.2 operated	Main 1: Fault Loop Bph to Ground, Z1/z1B Trip. Fault dist; 21.04km. Main 2: Fault Loop Bph to Ground and Z1 & Z2 Trip. LV SEF	urrent: Ia; 0.36kA, Ib; 0.14kA & Ie;	4.21kA	

2.														
i) 66k\	V and above													
	1 11.08.2021	01:39 hrs	11.08.2021 02:00	hrs	0	21	76.42 Jigmeling feeder	Dhajay SS	Main II Ia=15	.4 86.1 &2, relay Main II		Tripped	bus coulper also tripped at a same time.	
	2 11,08.2021	01:39 hrs	11.08.2021 2:12hr	rs 0	33	-83.06	Dagachu	Dhajay SS	Main II Ia=15	.4 86.1 &2, relay Main II		Tripped	bus coulper also tripped at a same time.	
. 132/	66/33/11kV	Gelephu St	ibstation											
) 66kV	V and above													
1	11.08.202	01.36hrs	11.08.202 02.03	3hrs	00;	00 1	6.8 kv Gelephu-Salak	ti 25MVA(HV & LV)	bed weather	ial relay,B-ph,	Salakati line	Temporary	Charging code NLDC BTN=1442, IND=508,NERLDC=6932	NLDO

#### September 2021

	Division: Substation: Month:		D-DEOTH: V Kaughung #REF!												
		Voltage	Type or	Shutdown	/Tripping	Normal	ization Time	Duration	of Outage	MW before		Tripping Details		Reason for	- Account
l. No.	Name of Feeder	Level	Outage	Date	Time	Date	Time	(Hrs)	(Min)	Outage (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Shutdown	Remarks
		132kV									The state of the s				- 1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
ı	Corlung-Kanglung Incomer	132kV	Tripping	02 09 2021	5:58	02.09.2021	6:13	0	15	-18.792	relay P14DB16A6C0540A operated,	IA=411.3, IB=80.34, IC=465.6	Earth fault	Tripped	Corlong-Kanglung incomer Breaker tripped indicating earth fault, test charge done at 6:03 but did not withstand, later agai charged at 6:13.
2	Corlung-Kanglung Incomer	132kV	Tripping	10.09,2021	17:10	10.09.2021	17:12	0	2	-21.204	relay P14DB16A6C0540A operated and P442(Distance Relay)	IA=658.6, IB=704.4, IC=697.3 and Fault Location = 35.64KM	Over current	Tripped	Corlong-Kanglung incomer Breaker tripped indicating Over current and test charge done and line withstand.
3	Phonoshoring	132KV	Tripping	10.09.2021	17:10	10.09.2021	17:30	0	20	20.124	REF615	IA=1.154 x IN, IB=1.261 x IN, IC=1.236 x IN	Over current	Tripped	132kV Phintshothang line tripped on Over current and test charge done and line withstand.
4	Corlung-Kanglung Incomer	132kV	Tripping	10.09.2021	17;39	10.09.2021	17:41	0	2	-21.204	relay P14DB16A6C0540A operated and P442(Distance Relay)	IA=774.1, IB=839, IC=786.9 and Fault Location = 16.15KM	Over current	Tripped	Corlong-Kanglung incomer Breaker tripped indicating Over current and test charge done and line withstand.
5	Plumtshotheng	132KV	Tripping	10.09.2021	17:39	11.09.2021	12:43	19	.40	20.124	REF615	IA=1.508 x IN, IB=1.515 x IN, IC=1.644 x IN	Over current	Tripped	132kV Phuntshothang line tripped on Over current and test charge done and line did not withstand. Line undr faulty.Charg- the feeder on dated 11.09.2021 Closing Code 1582 by Tsherir Choden (BPSO Thimphu.)
6	Phontshothang	132	Line Faulty	29.09.2021	14:05	29.09.2021	14:15	0	10	18.954	Dist. Pret.	NA NA	Dist.	Line Faulty	Triped & indicates Distance Protection relay.
7	Phontshotheng	132	Shutdown	29.09.2021	16:12					freder still under sl	nut down		Shutdown	Voltage checking at p/Thang ss	Opening code:0343, issued by BPSO. Tshering Chodon, Duty personal
8	Corlung-Kanglung Incomer	132	Line Faulty	29.09.2021	17:27	29.09.2021	18:06	0	39	-1.512	E/F	IA-109.6A.IB-753.8A.IC-96.93A.	Earth fault	Line Faulty	Triped &earth fault relay.
	Division: Substation: Month:	132/33/11	D-DEOTH: kV Nangkor #REF!	Substation											li .
l. No.	Name of Feeder	Voltage Level	Outage	Date	/Tripping	Normal Date	ization Time Time	Duration (Hrs)	of Outage (Min)	MW before Outage (MW)	Protecton Relay Optd	Tripping Details Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
32kV 1	Fooders	Deve	loca ad	Date	Amore	Date	Time	(insy	1 (1110)	Outling (Strift)	Tratectou Ketaly Optu	Tami Details (As recorded by relay)		Summore	
1	132/33kV, 5MVA Trf- II	132kV	Tripping	9/1/2021	18:53 hrs	9/1/2021	18:57 hrs	0	4	0.39	Trip relay operated	Tripping relay 86 operated	Tripped due to feeder fault	-	Tripped due to fault on 33kV Tsebar feeder.
ı	Nangkor-Deothang line	132kV	Tripping	9/28/2021	02:18 hrs	9/28/2021	02:34 hrs	0	16	44.7	MiCOM P442	Directional -O/C & E/F Relay: Tripped O/CN: Start O N, O/C start I > 1, E/F 1 start RN  -12, rrip IND-2/VABI-15,6E/Y, VBC=125,6E/Y,VCA=102,0E/Y,VAN=75,08E/Y,VEN -78,02E/Y,VCN=57-3,6E/Y,IA=185,7A,IB=198,2A,I C=754,7A, INDerived=615,0A, IN measured=614,6A & tripping relay 86 operated at our end.	Tripped on fault	*	Information to BPSO & charged the feeder with the instruction from BPSO.

- 1	Division:	SM	D-DEOTH.	ING											
- 1	Substation:	132/33/111	V Deothan	Substation											
	Month:	ri .	#REF!												
_			туреог				ization Time							D 4	
l. No.	Name of Feeder	Voltage Level	Outage	Date	Time	Date	Time	(Hrs)	of Outage (Min)	MW before Outage (MW)	Protecton Relay Optil	Tripping Details Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
		Letel	CC4 + 4	Date	THING	Date	Time	(mrs)	(sim)	Catage (at ii)	Protecton Kerny Opto	Frank Details (As recorded by relay)	THE CONTRACTOR OF THE PARTY OF	Sautown	
	132/33kV 5MVA Transformer I&II	132/33kV	Tripped	02.09.2021	5:17	02.09.2021	5:20	0	3	0.67 & 0.65	NA	Nil	NA		Both the Trabsformer got tripped due to fault at samdrupjongkhar line. Test cargedwas done and got stand.
	32/33kV 5MVA Fransformer [&II	132/33kV	Triped	03.09.2021	9:19	03:09:2021		0		0.08 & 0.077	NA	Nil	NA		Both the Transformer got tripped due to over current& earth fault of Bangter line. Test charge was done and got stand.fdr found ok.
	32/33kV 5MVA Transformer I&II	132/33kV	Triped	03.09.2021	18:34	03.09.2021	18:39	0	5	.96 and .95	86 opt.	NA NA	By Bangtar fdr	NA	Transformer was charged with isolating bangtar line and four normal. Burnt the closing coil of Tr.2 LV side we kept Idle charge.
4	Nangkor-Deothang line	132kV	Tripped	28.09.2021	2:20	28.09.2021	2:31	0	11	-50.22	NA	Nil	NA	NA	Supply tripped at both end (Nangkor and Motanga). No beak operated at Deothang end. At 2;31 hrs supply charged from Motanga and at 2;34 hrs supply synchronized from Nangkor
_									le:						substation.
	Distribute	CAU	D-BEOTH	NC.					(C)						substation.
	Division:		D-DEOTH												substation.
				ANG n Substation											substation.
	Substation: Month:	132/33/11k	V Nganglas #REF!	o Substation		Normal	ization Time	Duration	of Outage	MW before		Tripping Details		Reason for	
l No.	Substation:		V Nganglar	o Substation	. Tripping	Normal Date	ization Time	Duration (Hrs)	of Outage (Min)	MW before Outage (MW)	Protecton Relay Optid	Tripping Details Fault Details (As recorded by relay)	- Type/Cause of Fault	Reason for Shutdown	substation.  Remarks
L No.	Substation: Month:	132/33/11k Voltage	V Nganglas #REF!	Shutdown	n/Tripping		THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW				Protecton Relay Optd		Type/Cause of Fault		
	Substation: Month:	132/33/11k Voltage	V Nganglar #REF! Type or Outage	Shutdown	n/Tripping Time		THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN TW						Type/Cause of Fault Transient Fault		
1	Substation: Month:  Name of Feeder	Voltage Level	V Nganglas #REF! Type of Outage Tripping	Shutdown Date	Time	Date	Time	(Hrs)	(Min)	Outage (MW)	132kV	Fault Details (As recorded by relay)			Remarks  CB operated at Tingtibi end only.  Supply restored after coordination to BPSO and Tingtibi en
1 2	Substation: Month:  Name of Feeder  Naganglam-Tingtibi	Voltage Level	V Nganglas #REF:  Type or Outage  Tripping  Tripping	Shutdown Date 01.09.2021	Time  14:55  11:33	Date 01.09.2021	Time 15:39	(Hrs)	(Min) 44	Outage (MW)	132kV Micom relayP442	Fault Details (As recorded by relay)  NA  IA= 387.8A IB= 151.0A IC= 164.9A IN= 500.4A  VAN= 113.3kV VBN= 133.4kV VCN= 128.4kV	Transient Fault		Remarks  CB operated at Tingtibi end only.  Supply restored after coodination to BPSO and Tingtibi en with vide Switch DN codel 370, Issued by Madam Karu
3	Substation: Month:  Name of Feeder  Naganglam-Tingtib: Naganglam-Tingtib:	132/33/11k  Voltage Level  132kV  132kV	V Nganglas #REF! Type of Outage Tripping Tripping Tripping	Shutdown Date 01.09.2021 09.09.2021	14:55 11:33	Date 01.09.2021 09.09.2021	Time 15:39 11:42	(Hrs) 0	(Min) 44 9	Outage (MW) -18.31 30.7	Micom relayP442 Micom relayP443	NA IA= 387.8A IB= 151.0A IC= 164.9A IN= 500.4A VAN= 113.3kV VBN= 133.4kV VCN= 128.4kV A/R lockout 86operated	Transient Fault  Earth Fault/Transient Fault  Tripped cause due to 33kV  Panhung feeder where		Remarks  CB operated at Tingtibl end only.  Supply restored after coodination to BPSO and Tingtibl en with vide Switch ON code# 1570, Issued by Madam Karm Choden. BPSO

	Substation: Month:	132/3383	Motanga S	abstation											
ā	Towns and the second	Voltage	type or	Shutdown	Tripping	Norms	alization Time	Duration	of Outage	MW before		Tripping Details		Reason for	******
Sl. No.	Name of Feeder	Level	Outage	Date	Time	Date	Time	(Hrs)	(Min)	Outage (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Shutdown	Remarks
1	132kV Deothong Feeds	132kV	Tripping	9/2/2021	5:58	9/2/2021	6:07		9	-37.9	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV&UV OPTD	-	Infromed BPSO, as instructed to closed CB at 06:07 hrs from our end.
2	132kV Plantshothaug F	132kV	Tripping	9/2/2021	5:58	9/2/2021	6:13		15	-16.6	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV&UV OPTD	-	Infromed BPSO, as instructed to closed CB at 06:13 hrs from our end.
3	132kV Rangin feeder	132kV	Tripping	9/2/2021	5:58	9/2/2021	6:18		20	38.38	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV&UV OPTD	8	Informed BPSO, as instructed to closed CB with code NLDC BHT-1547,NLDC India-44 and NERLDC-7757 charged at 6:18hrs from our end.
4	132kV Rangia fooder	132kV	Tripping	9/6/2021	4:16	9/6/2021	5:42	1	26	49.37	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV & UV OPTD	×	Informed BPSO, as instructed to closed CB with code NLDC BHT-1559,NLDC India-202 and NERLDC-7961 line charged a 5:42hrs from our end.
5	132kV Deothang Feede	132kV	Tripping	9/7/2021	5:20	9/7/2021	5:26		6	-33.77	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV & UV OPTO	2	Informed BPSO, as instructed to closed CB with code no. NLDC Bht-1563 charged at 5:26brs from our end.
6	132kV DML feeder	132kV	Tripping	9/7/2021	5:20	9/7/2021	5:38		18	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV & UV OPTD	=	Informed BPSO, as instructed to closed CB with code no. NLDC Bht-1564 charged at 5:38hrs from our end.
7	132kV Rangia feeder	132kV	Tripping	9/7/2021	5:20	9/7/2021	5:55		35	26.71	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV & UV OPTD	U	Informed BPSO, as instructed to closed CB with code NLDC BHT-1565,NLDC India-259 and NERLDC-8010 charged at 5:55hrs from our end.
8	132kV Deothang Feeds	132kV	Tripping	9/16/2021	3:58	9/16/2021	4:08		10	-30.12	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV & UV OPTD		Informed BPSO, as instructed to closed CB at 4:08hrs from our end.
9	132kV DML feeder	132kV	Tripping	9/16/2021	3:58	9/16/2021	4:11		13	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV & UV OPTD,R,Y,B phase OPTD	8	Informed BPSO, as instructed to closed CB at 4:11hrs from our end.
10	15MVA Transformer	132/33kV	Tripping	9/17/2021	8:35	9/17/2021	8:39		4	0.09	DIFFERENTIAL PROTN. RELAY-RET650	86A OPTD	OC & EF	-	CB closed at 8:39hrs from our end.
11	15MVA Transformer	132/33kV	Tripping	9/21/2021	16:07	9/21/2021	16:37		30	0.12	DIFFERENTIAL PROTN. RELAY-RET650	86A OPTD	EF	=	CB closed at 16:37hrs from our end.
12	15MVA Transformer	132/33kV	Tripping	9/22/2021	5:56	9/22/2021	5:58		2	0.07	DIFFERENTIAL PROTN. RELAY-RET650	86A OPTD, SEF PROTN OPTD.	OC & EF		CB closed at 5:58hrs from our end.
13	15MVA Transformer	132/33kV	Tripping	9/22/2021	14:52	9/22/2021	14:54		2	0.06	DIFFERENTIAL PROTN. RELAY-RET650	86A OPTD,SEF PROTN OPTD.	EF	=	CB closed at 14:54hrs from our end.
14	15MVA Transformer	132/33kV	Tripping	9/24/2021	1:07	9/24/2021	1:09		2	0.08	DIFFERENTIAL PROTN. RELAY-RET650	86A OPTD, SEF PROTN OPTD.	OC & EF	2	CB closed at 1:09hrs from our end.
15	132kV Deothang Feeds	132kV	Tripping	9/24/2021	5:57	9/24/2021	6:07		10	-49.23	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	2	Informed BPSO, as instructed to closed CB with code no. NLDC BHT-1637 at 6:07 hrs. line extend from our end.
16	132kV DML feeder	132kV	Tripping	9/24/2021	5:57	9/24/2021	6:07		10	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD,R,Y,B Trip.	OV/UV Trip	-	Informed BPSO, as instructed to closed CB with code no. NLDO BHT-1638 at 6:07 hrs. line extend from our end.
17	132kV Deothang Feede	132kV	Tripping	9/28/2021	2:18	9/28/2021	2:29		п	+43.01	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OC & EF	-	Informed BPSO, as instructed to closed CB at 2:29hrs from our end.
18	132kV Rangia feeder	132kV	Tripping	9/28/2021	2:18	9/28/2021	3:12		54	33.08	MAIN DISTANCE PROTN: RELAY-REL650	86A & 86B OPTD	OC & EF	9	Informed BPSO, as instructed to closed CB with code no.NLDC BHT-1650,NLDC India-1654,NERLDC-8988 at 3:12hrs line charge from our end.
19	132kV Deothang Feede	132kV	Tripping	9/28/2021	2:56	9/28/2021	3:08		12	-43.01	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	2	Informed BPSO, as instructed to closed CB at 3:08hrs from our end.
20	132kV DML feeder	132kV	Tripping	9/28/2021	2:56	9/28/2021	3:10		14	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD,R,Y,B Trip.	OV/UV Trip	-	Informed BPSO, as instructed to closed CB at 3:10 hrs from our end.
21	132kV DML feeder	132kV	Tripping	9/28/2021	5:08	9/28/2021	11;14	6	6	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD,R,Y,B Trip.	OV/UV Trip	==	Informed BPSO, as instructed to closed CB with code no.NLDC BHT-1654 at 11:14hrs line extend from our end.
22	132kV Deothong Feede	132kV	Tripping	9/28/2021	5:12	9/28/2021	6:40	1	28	-38.87	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	-	Informed BPSO, as instructed to closed CB with code no.NLDC BHT-1652 at 06:40hrs CB closed from our end.
23	132kV Plumtshothang E	132kV	Tripping	9/29/2021	14:05	9/29/2021	14:11		6	-19.4	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPID	Zone-1 OPTD,R and Y phase Trip.	-	Informed BPSO as instructed to closed CB and CB closed at 14:11 hrs from our end.
24	132kV Deothang Feede	132kV	Tripping	9/29/2021	14:15	9/29/2021	14:21		6	-47.73	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip		Informed BPSO, as instructed to closed CB and CB closed at 14:21 hrs from our end.
25	132kV Deothang Feede	132kV	Tripping	9/29/2021	14:23	9/29/2021	14:43		20	+47.73	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	-	Informed BPSO, as instructed to closed CB and CB closed at 14:43 hrs from our end.
26	132kV Phontshothang F	132kV	Tripping	9/29/2021	14:15	9/29/2021	14:47		32	-19.04	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	-	Informed BPSO, as instructed to closed CB and CB closed at 14:47hrs from our end.
27	132kV Rangia feeder	132kV	Tripping	9/29/2021	14:15	9/29/2021	14:55		40	51.21	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	- 5	Informed BPSO, as instructed to closed CB with code no.NLDC BHT-1661,NLDC India-1756,NERLDC-9083 at 14:55hrs line charge from our end.
28	132kV Deothang Feeds	132kV	Tripping	9/29/2021	17:57	9/29/2021	18:01		4	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip		Informed BPSO, as instructed to closed CB and CB closed at 18:01hrs from our end.
29	132kV Plumtshothang F	132kV	Tripping	9/29/2021	17:57	9/29/2021	18:04		7	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	-	Informed BPSO, as instructed to closed CB and CB closed at 18:04hrs from our end.
30	132kV Rangia feeder	132kV	Tripping	9/29/2021	17:57	9/29/2021	18:25		28	0	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	=	Informed BPSO, as instructed to closed CB with code no.NLDC BHT-1665.NLDC India-1767,NERLDC-9109 at 18:25hrs line charge from our end.
31	132kV Deothang Feede	132kV	Tripping	9/30/2021	10:58	9/30/2021	11:01		3	54.44	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	2	Informed BPSO,as instructed to closed CB and CB closed at 11:01hrs from our end.
32	132kV Rangia feeder	132kV	Tripping	9/30/2021	10:58	9/30/2021	11:27		29	42.73	MAIN DISTANCE PROTN. RELAY-REL650	86A & 86B OPTD	OV/UV Trip	_	Informed BPSO, as instructed to closed CB with code no.NLDC BHT-1667,NLDC India-1819,NERLDC-931 at 11:27hrs line charge from our end.

Division: SMD-DEOTHANG

	Division: Substation: Month:		AD-DEOTE kV Corlung #REF!	Substation											
10000	744500000000000000000000000000000000000	Voltage	rype or	Shutdow	n/Tripping	Norma	lization Time	Duration	of Outage	MW before		Tripping Details		Reason for	No. Alabama
I. No.	Name of Feeder	Level	Outage	Date	Time	Date	Time	(Hrs)	(Min)	Outage (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Fault	Shutdown	Remarks
1	132 kV Khilikhar line	132 kV	No supply from Khilikhar substation		12:27 hrs	05.09.2021	12:34 hes	0	7	2.380	Nil	Nil	There was no 132 kV supply from Khilikhar substation		
2	132 kV Khilikhar line	132 kV	No suppl from Khilikha substatio	29.09.2021	17:29 hrs	29.09.2021	17:35 hrs	0	6	2,430	Nil	Nii	There was no 132 kV supply from Khilikhar substation		132 EV Khilikhar-Corlung Line was triped at Khulikhar Substation.
3	132 kV Kanglung Line	132 kV	No suppl from Khilikha substatio	29.09.2021	17:29 hrs	29.09.2021	18:06 hrs	0	37	1.320	Relay 86A and 86B	VT fuse fail	There was no 132 kV supply from Khilikhar substation		132 kV Kanglung Line Triped at 17:35 hrs when Khilikhar- Corlung Line was charged from Khilikhar end.
	Division:	SM	4D-DEOTE	IANG											
					1										
	Substation:	32/33kV I	Phuntshoth	ing Substatio	<b>&gt;</b>										
	Substation: Month:	32/33kV I	Phontshoth #REF?	ing Substatio	<b>)</b>										
W. W.	Month:	Voltage	#REF:		n/Tripping	Norma	lization Time	Duration	of Outage	MW before		Tripping Details	To Constitution	Reason for	Powerhi
l. No.		0	#REF:			Norma Date	lization Time	Duration (Hrs)	of Outage (Min)	MW before Outage (MW)	Protecton Relay Optd	Tripping Details  Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
. No.	Month:	Voltage	#REF?	Shutdow	n/Tripping						Protecton Relay Optd  REL650 Zone1		Type/Cause of Fault  Earth fault	Shutdown	132kV incomer fedder trip at both end ,test charged from
1. No.	Month:  Name of Feeder  Plantshothang-	Voltage Level	#REF! Lype of Outage	Shutdow	n/Tripping Time	Date	Time		(Min)	Outage (MW)	av .	Fault Details (As recorded by relay)  (DEFLPDEF1) Trip value: L1: 489.71A, L2: 93.87A, L3: 513.09A, Ln: 597.68A.  ZONE1 0PTD AND R. V.B. Plase trip and fault (Increase 3) 23.374 Senil;		Shutdown	132kV incomer fedder trip at both end, test charged from Kanglung end and did not withstand. Charged from Motanga e
î	Month:  Name of Feeder  Plantshothang- Motanga	Voltage Level	#REF: Lype of Outage ransient F	Shutdow Date	n/Tripping Time  5.58	9/2/2021	Time 6:15		(Min)	Outage (MW)	REL650 Zone1	Fault Details (As recorded by relay)	Earth fault  R,Y and B phase trip.	Not available	132kV incomer fedder trip at both end ,test charged from Kanghung end and tild not withstand. Charged from Motanga e and Normalized.  Test charged and line with stand.  Triped again after 7 minutes of test charging and BPSO has instructed for line partoling. him charged after TMD cleared t
ï	Month:  Name of Feeder  Plantshothang- Motanga  Kanglung	Voltage Level 132kV 132kV	ransient F	Shutdow Date 9/2/2021 au 9/10/2021	5-58 17:11 17:40	9/2/2021 9/10/2021	6:15 17:33	(Hrs)	(Min) 17 32	Outage (MW)  16.62  20.15	REL650 Zone1  ONE 1 OPTD AND R, Y, B TR	Fault Details (As recorded by relay)	Earth fault  R,Y and B phase trip.	Not available  Not available	132kV incomer fedder trip at both end ,test charged from Kanghung end and did not withstand. Charged from Motanga e and Normalized.  Test charged and line with stand.  Triped again after 7 minutes of test charging and BPSO has instructed for line partoling line charged after TMD cleared frault with the switch DN code in 1822 issued by mrs. Tabering that with the Section 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the switch DN code in 1822 issued by mrs. Tabering the 1822 issued by mrs.

1, 400/2	220/132/33kV Jigmelin	g Substatio	n										
81. No.	Date of Tripping	Time of Outages/ Time of Tripping	Date of Normaliza tion	Time of Fault was Cleared	Duration of Outages (Hrs)	MW before Outage (MW)	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Type of outages	Remarks
) 66kV	Above												
1	2-Sep-21	04:06 hrs	2-Sep-21	04:18 hrs	0	-385.42	400kV MJ3	400kV	Tripping	SIPROTECT 7SA52 & SIPROTECT 7SA611	R,Y&B Pickup, Ground Pickup, Zone 1 optd.	Line-Ground fault	
2	7-Sep-21	07:00 hrs	7-Sep-21	07:04 hrs	0	-58.06	500MVA ICT	400/22 <b>0k</b> V	Tripping	7SJ8031-5EB90- IFC0/DD, SIPROTECT 7UT61	No relay indication		
3	7-Sep-21	07:06 hrs	7-Sep-21	12:22 hrs	5	-58.06	500MVA ICT	400/220kV	Tripping	7SJ8031-5EB90- 1FC0/DD, SIPROTECT 7UT62	50Ns 1/2 tripped		
4	16-Sep-21	16:13 hrs	16-Sep-21	16:23 hrs	o	-385.42	400kV MJ3	400kV	Tripping	SIPROTECT 7SA52 & SIPROTECT 7SA611	Main 1 optd, fault loop L2-3-G, Fault Dist. 41.3km, Main 2 optd, L2-3-G, Fault Dist.41.2km	L2-3-Ground fault, (Main-1 Fault curren Ia=0.07kA, Ib=6.56kA, Ic=6.34kA.) (Main-2 Fault current Ia=0.07kA, Ib=6.53kA, Ic=6.30kA.)	Line charged as per BPSO instruction
5	8-Sep-21	11.25hrs	8-Sep-21	11:38hrs	0	96.94	220kV Tsirang feeder	220kV	Tripping	50/51N	3ph to Ground, Z1/z1B Trip. Faul	Line-Ground fault	Western Grid fail
6	13-Sep-21	14:19hrs	13-Sep-21	14:23hrs	o	-81.25	220kV Tsirang feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL670	М	Line-Ground fault	Western Grid fail
7	13-Scp-21	14:20hrs	13-Sep-21	14:26hrs	0	1.1	220kV Dagapela feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL670	Main 1 optd, Fault Loop(B to Ground) Fault dist(2km), Zone 1 optd. Main 2 optd. Fault Loop(B to Ground) Fault dist(1.55km), Zone 1 optd.	Line-Ground fault	
8	17-Sep-21	16:14hrs	17-Sep-21	16:24hrs	0	-86.71	220kV Tsirang feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL671	Main 1: Yph trip, Z1/z1B trip. Fault dist; 17.5km. Main 2: Yph trip, Z1 trip, Fault dist; 20.25km.	Line-Ground fault	tharged as per BPSO instruction
9	17-Sep-21	16:14hrs	17-Sep-21	16:41hrs	o	1.01	220kV Dagapela feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL670	Main 1: RYYph trip, Z1/z1B trip, Fault dist; 20.9km. Main 2: Yph trip, Z1 trip, Fault dist; 18.2km.	Line-Ground fault	charged and charged as per BF
10	29-Sep-21	13:37hrs	29-Sep-21	13:51hrs	o	-29.67	220kV Tsirang feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL671	Main 1 optd Fault Loop(L1-L3 to ground), Fault dist(21.1km), Fault Current Ir=0.45kA, Iv3.25kA, Ib=2.82kA	Line-Ground fault	Closed tripped on same fault
11	29-Sep-21	13:37hrs	29-Sep-21	14:26hrs	0	1.87	220kV Dagapela feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL670	Main 1 optd ,Fault Loop(L2- L3and ground),Fault dist(25.4km) Fault current Ia-0.02ka Ib-3.09ka Ic-3.22ka	Line-Ground fault	
12	29-Sep-21	13:51hrs	29-Sep-21	14:04hrs	o	-29.67	220kV Tsirang feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL671	Main 1 optd ,Fault Loop(L1-L3 to ground), Fault dist(21.1km), Fault Current Ir=0.45kA, Iy3.25kA, Ib=2.82kA	Line-Ground fault	Closed tripped on same fault
13	29-Sep-21	14:04hrs	29-Sep-21	14:264hrs	0	-29.67	220kV Tsirang feeder	220kV	Tripping	Distance Relay: SIPROTECT 7SA52 & REL671	Main 1 optd Fault Loop(L1-L3 to ground), Fault dist(21.1km), Fault Current Ir=0.45kA, Iy3.25kA, Ib=2.82kA	Line-Ground fault	

) 66k	V and above												<u> </u>
	1 13.09.2021	14:19:15hi	13.09.2021	14:28:54hr	4 )	78.5	Jigmeling feeder	Dhajay SS	Main 1 Ia-0.0	1 86.1 &2, Distance re	Main I=31,3KM, Main II=28	.1 Tripped	Line restored as per BPS
	2 17.09.2021	16:13hrs	17.09.2021	16:20hrs	0	86.5	Jigmeling feeder	Dhajay SS			Main I=20.1KM, Main II=20		Line restored as per BPS
	3 29.09.2021	13:36hrs	29.09.2021	13:53hrs	0	29.54	Jigmeling feeder	Dhajay SS	Main 1 Ia=0.5	86.1 &2, Distance re	Main I=13.7KM, Main II=10	4 Tripped	Line restored as per BPS0
	4 29:09:2021	14:03hrs	29.09.2021	14:12hrs	0	0	Jigmeling feeder	Dhajay SS	Main 2,	a 86.1 &2, Distance rel	lay Main II	Tripped	since the line couldn't res
	5 29.09.2021	14:03hrs	29.09.2021	14:07hrs	0	1.02	ICT-II	Dhajay SS	ONLY 87 relay pic	k 86.1 &2, 87 relay		Tripped	Since Rurichu feeder was
	6 29.09.2021	14:03hrs	29.09.2021	14:08hrs	0	0	ICT-I	Dhajay SS	Diff A=1.83I/In0, F	e 86.1 &2, 87 relay		Tripped	Since Rurichu feeder was
	7 29.09.2021	14:03hrs	29.09.2021	14:21hrs	0	2.9	Dagachu	Dhajay SS	Main 2,	a 86.1 &2, Distance rel	lay Main II	Tripped	Since Rurichu feeder was
132	/66/33/11kV Gelephu	Substation											
66k	V and above												
1	14.09.2021	16.28hrs	14.09.2021	17.02hrs		21.8	132kv Gel-Sal fdr	132kv Gel-Sal fdr		General trip,YB- ph,Zone I,Dist.6.03kn,Fault current;R-98.97A,Y- 2736.19A,B- 2618.54A,N- 19.05A			Charging code= NLDC BTN=1600,NLDC IND=767,NERLDC=8357
	/33/11kV Tintibi Substa	ation					70 -			T		Y.	
1	9/1/2021	14:58	9/1/2021	15:38	o	18.7200	132kV Tingtibi-Nangl	a 132kV Tingtibi-Nangla	Tempoary Fault	Distance Protection Relay:Trip phase ABC,Start phase :AN,Fault Loaction:30.82kM,Fa ult Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
	9/9/2021	10:33	9/9/2021	10:42	ō	31.6100	132kV Tingtibi-Nangl	a 132kV Tingtibi-Nangla	Tempoary Fault	Distance Protection Relay:Trip phase ABC,Start phase :AN,Fault Loaction:XY 17.6kM,Fault Zone-1.	132kV Tingtibi-Nanglam	Tempoary	
2									Tempoary Fault	Distance Protection	132kV Tingtibi-Jigemling	Tempoary	

#### October 2021

	SI ZU		IE MONTE	OFOCT	ORER UNDE	ER SMD DEOTHA	NG, TD, RPC.							
Division: Substition: Month:	531	D-DEOTH kV Killkhar Oct-21	LNG											
Name of Feeder	Voltage Level	Type of Outage	Shutdown	Tripping	Norm	alization Time Lime	Duration (Hrs)	of Outage (Min)	MW before Outage (MW)	Trip Protecton Relay Optd	ping Details Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
Feeders 1 Kurichu	132kV	Tripped	02-10-2-21	06:45 hrs		07:34 lans		49	21.78	Nati	Nill	Nill	Grid fail	Grid faild from Nongkhor end.
Division:	SM	D DEOTH V Kanglan Oct-21	LNG											
o. Name of	Voltage	Outage		Tripping		alization Time	Duration		MW before Outage (MW)		ping Details	Type/Cause of Fault	Reason for Shutdown	Romarks
Feeder	Level	ers	Date	Time	Date	Time	(Hrs)	(Min)		Protecton Relay Optd	Fault Details (As recorded by relay)			and the state of t
		132kV												
funtskothu	132	Shudown	29.09.2021	16:12	01.10.2021	16:45	48	33	0.072	NA NA	NA.	Shadown	Change of jumpering at location 89	Opening code:0343, issued by BPSO: Tshering Chodon, Duty personal. Closing code: 1671 i by Kinley Wangno, BPSO.
Corlung	132	Geid failed	02.10.2021	6.42	02.10.2021	7:34	0:52	52	-18.468	NA NA	NA NA	Whole Eastern Power Grid finled	NA	Source Failed
5MVA Transform er - II	132	Tripped	17.10.2021	10:21	17.10.2021	L4:08	3.	47	0.849	NA -	NA	30F OLTC bockz tripped	NA	Trapped on OLTC Sucholz pressure low
5MVA Transform er - II	132	Tripped	19.10.2021	21:15	20.10.2021	(1:35	14	20	0.969	NA .	NA NA	30F OLTC Bocholz tripped	PRV limit switch short circui	Tripped on OLTC Bucholz pressure low
Division: Substation: Month:		D DEOTIL kV Nangkor Oct 21										1		
o, Name of Feeder	Voltage Level	Outage		Tripping Time	Norma Date	alization Time Time	Duration (Hrs)	of Outage (Min)	MW before Outage (MW)		ping Details  Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
Nangkor- Ngmglam	iazky	Tripping	10/2/2021	06:38 hrs	10/2/2021	07:33 hrs	ā	⊹ <b>55</b> ⊹	2.66	місом Рыз	Directional -O.C. & E/F Relay: Tripped O N: Stat O CN, O/C start D-1, E/F1 start ND-12, in DN-12-VAB-13-5 6AV, VBC-017, ib/V-CA-0-11, 134V, VAB-0-7, 03 V.VBN-76, 834V, VCN-96-6 (15-VLA-47, 94 A, IB-70, 684A, IC-697, 1AA, INDerived-633-5A, Div measured-633, 2A & tripping relay 86 operated of our end.		Ų.	At 06.45 Ins test charged the freeder but CR couldn't get closed, inspected all the equipment in respect to the freeder, checked the Spring and closed: On at 07/26 Ins the couldn't stand, laterian BPSCA, Art 71/16 CR from Programs and was opened and that to test charging CR spring discharged at our end. The freeder was charged at 07/133 Ins after fully charging the CB spring of CR in open condition at Nigergians and.
5MVA Transform et-l, 132/22/11	132kV	Tripping	10/3/2021	01:38 hrs	10/3/2021	01:42 hrs	0	4	0.46	Non directional PROTN Relay operated	O/C relay-50A & tripping relay 86 operated	Tripped on feeder fault	影	Tripped while test charging 33&V Wanrong feeder.
Nangkor- Deothang	132kV	Tripping	20.630.630	05 23 krs	dunaunan	05:42 hrs	0	19	47.4	MICOM P442	Directional -O/C & E/F Rolay: Tripped U N : Star 6 CN; O/C start F-1, E/F1 start INF12, Trip INF12-VABEF133, Styl. VBC-124.2 M; V/CA-101.8 M; VABN-14.33 V,VBN-76.2 A; VCN-97.2 M; VALN-18.4 A, IB-202.5 A; IC-754.9 A, INDerived-635.4 A; Inscentred to Go. & ripping relay 86 operated on rend.	Townson for N	¥	Informed to BPSO. Thimplus and Charged the fender with closing code-1713 from their end
5MVA Transform er-L 132/22/11 kV	132kV	Tripping	******	08;45 lars	17/10.2021	08:56 hrs	0	6	0.54	Non directional PROTN Relay operated	O/C relay-50A & tripping relay 86 operased	Tripped due to feeder finilt	8	Tripped due to fault on 33kV Nammy feeder.
5MVA Transform er-II, 132/22/11	132kV	Tripping	******	08:45 hrs	euseuseu	08:48 hrs	0	3	0.34	Non directional PROTN Relay operated	O-C relay-50A & tripping relay 86 operated	Tripped due to feeder finilt	20	Tripped due to fault on 33kV Nanung feeder
5MVA Transform er-L 132/22/11	132kV	Shut down	******	13:10 lirs	*******	16:44 hrs	3	34	0.42	(8	28	8	To Install CT for 2.5MVA IFR-1	Slnz down taken by SMD Group Deedunag
SMVA Transform et-II, 132/22/11 kV	132kV	Shat down	sus sus su	13:10 hrs	#46#4##W	16:56 les	3	46	0.25	ii.	8		To lastall CT for 2.5MVA TFR-1	Shar down taken by SMD Group Deothang

	Introduction in			03210											
Si	Division:			ANG n Substation											
	Monthi		Oct-21												
SL No.	Name of Feeder	Voltage Level	Outage	Shutdown	Tripping Time		alization Time Time	Duration (Hrs)	of Outage (Min)	MW before Outage (MW)	Protecton Relay Optd	ping Details Fault Details (As recorded by relay)	Type/Cause of Fault	Reason for Shutdown	Remarks
132kV			100		2.0010	2.000		(441-0)	Comp		Transmission of the			ny:	
1	anglum-Tin	132kV	Tripping	02 10 2021	06:35	02.10.2021	05:43	0	5	12.86	Micom relayP443	IA-31.63A IB-151.048.06A IC- 164.9818.6A IN-300.RA VAN-80.55kV VBN-78.78kV VCN-128.441.41kV A/R lockout 86operated	Earth Fault/Transieur Fault		Supply restored after coodination to BPSO and Tingtibi end with vide Switch ON code# 1570, Issued by Madam Karma Choden. BPSO
2	A Transform	132kV	Tripping	09.10.2021	15:20	09.10.2021	[5:23	U	3	0.628	E/F & O/C Microm relay	NA NA	Trippe due to 33kV Panbang feeder earth fault		
L 400/2	20/132/334	V Jigmelin	g Substation		_								- AMAR	-	
SL No.	Date of Telpping	Time of Outuges/ Time of Tripping	Date of	Time of Fault was Cleared	of	Duration of Outages (Min)	MW before Outage (MW)	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location(KM)	Type of outages	Remarks	
) 66kV	Above	A-1015-5	<u> </u>		1212-011						ali .			<u> </u>	
9	10-Oct-21	04:52 hrs	10-Oct-21	cocs hn	ī	16	154.55	400kV Algurdane Quad moose Inc > 2	400kV Alipurdner and jigrochages	Line-Ground finds, fools current ILS + 1.75kA.	SIPROTECT 1SA52 & SIPROTECT TSA611	Main I (R phase pick up, ground pick up, zonel optd and Zonel B optd at distance 136.8km) Main2(R phase pick up, ground pick up,conel oped and Zonel B optd at distance 133.6km	Line-Oround fault,	Line Charged as per BPSO instruction (Karma Yangden)	
	3/11kV Ton		on												
) 66 KV	and Above														
i	10/2/2021	6.39	10/2/2021	6.45	0	7	16.3400	132kV Tingthi-Naud	132kV Tingtibi-Nongla	Temposry Fault	Distance Protestion Ruley-Trip phase ABC,Start phase :CN,Finit Loutiers 10.826M,Finit Zonr-1.	132kV Tingtibi Nonglom	Tempeary		
1	05.10.2021	2023 lm	05.10.2021	2027 hrs	0	4	U	Transformer 2	Danji Substation & all outgoing Feeders	Trip	50 N & 86 OPID	NA		Tripped due to earth finilt on Punakha Feeder H02	
2	07.10.2021	0842 hrs	07.10.2021	0848 hrs	0	6	0.51	Transformer 2	Dunji Substation & all outgoing Feeders	Trip	50 N & 86 OPTD	NA NA		Tripped due to earth fault on Punnkha Feeder H02	
3	07.10.2021	2240 hrs	07.10.2021	2243 hrs	ō.	3	0.35	Transformer 2	Damji Substation & all outgoing Fooders	Trip	50 N & 86 OVID	NA NA		Tripped due to earth fruit on Punskha Feeder H02	
14	11.10.2021	1509 lus	11.10.2021	1513 lm	0	4	0.96	Transformer 2	Damji Substation & nll outgoing Feeders	Trip	50 N & 86 OPTD	Na		Tripped due to earth fealt & over current on Pauckha Feeder H02	
6	16.10.2021	0206 lirs	16.10.2021	0217 hrs	0	40	0.32	Transformer 2 & Incomer 2	Damji Substation & all outgoing Feeders	Trip	DIFF PRIN OUTD	NA NA		B Phase trip	
9 3	18.10.2021	0640 lbrs	18:10:2021	0646 hrs	0	6	0.64	Transformer 2	Damji Substation & all outgoing Feeders	Trip	50 N & 86 OPTD	NA		Tripped due to earth fault on Gasu Feeder HD8	
8	18.10,2021	2258 hrs	18.10.2021	2302 hrs	0	4.1	6.42	Transformer 2	Damji Substation & all outgoing Feeders	Trip	50 N & 86 OPTD	NA		Tripped due to earth fault on Punakha Feeder 1102	
9	19:10:2021	0849 krs	19:10:2021	0855 hrs	.0:	5.	0.66	Transformer 2	Danji Substation & nll outgoing Feeders	Trip	50 N, B Ph Trip & O/C	NA		Tripped due to earth fault & over current on Gasa Feeder H08	
10	29.10.2021	0957 krs	20.10.2021	1002 hrs	0	5;	0.57	Transformer 2	Damji Substation & all outgoing Feeders	Trip	50 N, RYB Trip & EF	NA		Tripped due to earth fault on Punakha Feeder H02	
11	20.10.2021	1341 les	20.10,2021	1345 hzs	0	5	0.62	Transformer 2	Damji Substation & nll outgoing Feeders	Trip	50 N, RYB Trip & EF	NA:		Tripped due to earth fault on Gasa Feeder H08	

## November 2021

MONTHLY OUT	AGE REPORT FOR	THE MONTH	OF NOVEMBER	UNDER SMD DEC	OTHANG, TD, BPC.

132/33/11kV Kilikhar Substation

			Type of	Shutdown	Trinning	Norma	dization Time	Duration	of Outage		Tring	ing Details	Type/Ca	Reason	
Sl. No.	Name of Feeder	Voltage Level	Outage (Shutdown	Date	Time	Date	Time	(Hrs)	(Min)	MW before Outage (MW)	Protecton Relay Optd	Fault Datails (As recorded	use of	for Shutdow	Remarks
32kV	Feeders	<u>e</u>											9		
3kV I	'eeders														
1	10mva transformer LV(33kV side)	33KV	Tripped	11/3/2021	14:00hrs	11/3/2021	16:28hrs	3	28	0.555	IADiff 3.689pu,IBDiff 3.688pu,	IADiff 3.689pu,IBDiff 3.688pu,	Tripped	Tripped	Tripped due to LA blast Y phase.

	Division:		D-DEOTH														
	Substation: Month:	132/33k3	V Motanga #REF!	Substation													
	Stone:	1	HECK!		1												
		Voltage	Outage	Shutdown	/Tripping	Norm	alization Time	Duration	of Outage		Tripp	ing Details	Type/Ci	for			
d. No.	Name of Feeder	Level	(Shutdown	Date	Time	Date	Time	(Hrs)	(Min)	MW before Outage (MW)	Protecton Relay Optd	Fault Details (As recorded by relay)	use of Fault	Shutdow	Remarks		
1	132kV Rangia Feeder	132kV	Tripping	11/5/2021	20:25	11/5/2021	20:49		24	16.9	OC & EF	IL1=0.789,IL2=0.180,IL3=0.1 68	Tripped on fault	-	Infromed BPSO, as instructed to closed CB with code no.NLDC Blat- 1792,NLDC India-320,NERLDC-277 CB closed at 20:49hrs from our end.		
3	15MVA Transformer	132/33kV	Tripping	********	8:00	anutuanu	8:21		21	1.85	OC & EF,86A & 86B OPTD,SEF OPTD.	Nii	Tripped on fault		CB closed at 18:21hrs from our end.		
6	DML Factory Feeder	132kV	Tripping	********	22:59	annkuann	23:03		4	0	OV/UV,R,Y,B TRIP,86A & 86B OPTD	Nil	Tripped on fault		Informed BPSO, as instructed to closed Cb with code no. NLDC BHT-1860 closed at 23:04hrs from our end.		
	7%	0.00		31	33										A),		
SL No.	Date of Tripping	Time of Outages/ Time of Tripping	Date of Normaliza	Time of Fault was Cleared	Duration of Outages (Hrs)	Duration of Outages (Min)	MW before Outage (MW)	MU Lost During Outages	Name of feeder	Name of the Substation/lines Affected by the Fault	Reasons of Fault	Relay Operations	Fault Location (KM)	Type of outages	No. of Customers Affected	Custome r* Hours Affrecte	Remarks
	66/33kV Dhajay Subst	ation			100000	I I I I I I I I I I I I I I I I I I I							-			-	
-	26.11.2021	20:37hrs	26.11.202	20:48hrs		11	13.88	2.544666667	Jigmeling feeder	Dhajay Subsation	over current	21.2 distance relay main-2, la	-1161.51/	Tripped	Entire area who are given supply from this feeder.	0.18333	feeder restored after as pe
2	26.11.2021	20:37hrs	26.11.202	20:49brs		12	47,12	9.424	Dagachu Feeder	Dhajay Subsation	over current	21.2 distance relay main-2, la	Line seg	Tripped	Entire area who are given supply from this feeder.	0.2	feeder restored after as po BPSO instruction.
. 220/3	33kV Dagapela Substa	tion												_			
	& Above	-											_				
	04.11.2021	0.536806	04.11.202	0.549306	0	19	2.8	2.8	220/33kV Transform	Dagapela		86A	-81	transient	whole Dagana	0.01319	tripped while tripping incomer at 33kV side
	04.11.2021	0.536806	04.11.202	0.549306	0	19	2.8	2.8	220/33kV Transform	Dagapela		86A	-	transient	whole Dagana	0.01319	tripped while tripping incomer at 33kV side
	10.11.2021	0.117361	10.11.202	0.349306	5	35	7.74	7.74	220/33kV Transform	a Dagapela		86A	Relay se	l transient	whole Dagana	0.23264	tripped number of times in between due to higher loa and low relay setting. Charged successfully after CNPD changed the setting
	10,11,2021	0.117361	10.11.202	0.349306	5	35	7.74	7,74	220/33kV Transform	aDagapela		86A	Relay se	t transient	whole Dagana	0.23264	tripped number of times in between due to higher load and low relay setting. Charged successfully after CNPD charged the setting

#### December 2021

Sul	Division: betation: Menth:		MD-DEOTH INV KRAmo Dec 21	r Substation					][			L.,		J	
SL No.	Name of	Voltage	Type of	Shutden	wTripping	Norm	nlization Time	Duration of	f Outage	MW hefere Outage (MW)	- Y	Tripping Details	Type/Cause of Fault	Reason	B
P INOT	Feeder	Level	Outage	Date	Time	Date	Time	(Hrs)	(Mis)	AIN Becore Outage (5119)	Protecton Relay Optd	Fault Details (As recorded by relay)	Type/Cause of Faile.	for	Remarks
2kV F	enders														
	Cortong	1321V	Trippad	12/2/2021	09:45les	12/2/2031	09:47tm		2	12.02	Nill	IA-21 65A, IB-32 49A, IC-20 68A, VAN-75 3 8kv, VBN-77 90kv, VCN-77 43kv Fault 20ac none	Openin of CB Kuricha -Nangkhar line from Nangkhar and.	Nill	Tripped due openin of CB Karieku-Nongkhor line from Nangkhor en (CB pole Discrepency) at same time Corlung hipped from kilikhar em

	Month:	_	Dec-21												
No.	Name of	Voltage	Type or	Shublows	/Tripping	Norm	udication Time	Duration	of Outage	MW before Outage (MW)		Tripping Details	Type Cunse of Fault	for	Remarks
	Feeder	Level	Outage		Time.		Time	(Hrs)	(Mis)	NIM Becase Outage (DLW)	Protectua Reby Optid	Fault Details (As recorded by roby)	Type-Cause of Faunt	lor	Komarks
	132/33kV, 5MVA Tri	132kV	Tripping	EESTEES	63-05 les	acentes.	03-10 km	o o	£1	0.42	Non-directional PROTN Relay operated	O/C rolay-S6A & tripping rolay \$6 operated	Tripped due to Seeder Suits	33	Tripped due to Salt on \$3kV Waterong Geider.
4	132/33kV, 5MVA Tri II	132kV	Tripping	AKTOOKTO	03:05 hrs	******	03:11 les	0.	6:	0.162	Nex directional PROTN Relay operated	O/C relay-50A& tripping relay 86 operated	Tripped due to feeder Sult	93	Tripped due to fault on 33kV Watarong feeder.
5	132/338V, 5MVA Tri I	132kV	Tripping	********	08:35 les	******	08 40 km	0	5	0.63	Non-directional PROTN Relay operated	O/C relay-50A & tripping relay 86 operated	Tripped due to feeder (init	÷	Tripped while test charging 33kV Wanteng feeder
6	192/88kV, 5MVA Tri II	132kV	Tripping	********	08:35 hrs	******	08:41 km	0		0.42	Nox directional PROTN Relay operated	O/C relay-50A& tripping relay 86 operated	Tripped due to freder fault	š	Tripped while test charging 33kV Wanrong feeder
7	132/33kV, 5MVA Trf I	132kV	Tripping	**********	11:57 hrs	nevnesn	11:58 km	0	10	0.6	Non-directional PROTN Relay operated	O/C relay-50A& tripping relay \$6 operated	Tripped due to freder fault	8	Tripped while test charging 3 3kV Wannong feeder
8	132/33kV, 5MVA Tri II	13217	Tripping	EE30E50	11:57 lev	******	11:58 les	0	13	0.42	Non-directional PROTN Relay operated	O/C relay-50A& tripping relay \$6 operated	Tripped due to Seeder Guit	8	Tripped while test charging 33kV Wannong feeder
9	132/33EV. 5MVA Trif I	132kV	Tripping	********	16:32 hrs	******	16:39 krs	0	*	0.39	Non-directional PROTN Relay operated	O/C relay-50A& tripping relay 86 operated	Tripped due to feeder fault	Ş)	Tripped due to fault on 33kV Tselvar feeder
10	132/334V, 5MVA Tri II	132kV	Tripping	*********	16:32 hrs	ACTIVITY	16:37 les	00	\$2	0,38	Non-directional PROTN Relay operated	O/C relay-50A& tripping relay \$6 operated	Tripped due to feeder fault	8	Tripped due to fealt on 33kV Tsebur feeder
4P9'2	20/132/338	V Jigastin	Substation					1000000	77	77 17					
No.	Tripping	Time of Outagos' Time of Tripping	Normaliza	Time of Fault was Cleared		MW before Outage (MW)	Name of feedur	Name of the Substation lines Affected by the Finds	Ressons of Fault	Relay Operations	Fault Loration(KM)	Type of outages	Rounds		
	Above 24.12.2021	11:05 hrs	24.12.2021	15:21 hm	4	0.60	Gdepha 98	Distonce relay main 2 pickup & main 2 nipped, B plase trip, Z nip,	Fault leap L3-N.	SEPROTECTSAS2 & REL 670	Fault Distance 14. Hors.				
		ajay Substa													
	and above		incu.									and the			
1	09.12.2021	12.17.13m	09.12.2021	12:29:06hr	K.	1.4	Equicling feeder	Dhayay Subsettion	Broken conductor	distance rolay main-1, fa=0.06A, fb=0.07A, fc=0.09A, fb=0.11A , Va=129.84EV, Vb=130.48EV, Vc=129.9EV,		Tripped	feeder restored after as per BPSO instruction.		
2	09.12.202	13:23:50lm	10.12.2021	10:32hrs		9	Jignoeling feeder	Dhajay Subsation	Broken conductor	distance relay main-2, la=0.08A, B=0.15A, lc=0.12A, ln=0.05A, Va=130.24EV, Vb=131.10kV, Vc=130.49kV.		Tripped	feeder restored after as per BPNO instruction.		
3	29.12.2021	13:52:06b	-29 12 2021	13:59hrs		27.65	Juncting feeder	Dhajay Subsetion	Broken conductor	distance relay main-1, fa=.08A, B=0.19A, Is=0.16A, In=0.09A, Va=131.01EV, Vb=131.77EV, Ve=13.95EV.		Tripped	feeder restored after as per BPSO instruction.		
	6/33/11kV and above	Gelephu Si	eberation												
	24.12.202 I	11.05hrs	24.12.202 1	11.29km		-3	132hv Gel-Sel	Gelephu SS	Equipment Failure	Dist trip C,Zone +1A=114.8A;B=160.7A;IC=1.510KA &VAN=80.968	Gelaphu s/s	teperary .	Charging Code; NLDC BTN-1791, NLDC IND-369 & NERLDC-272 & Voltage magnitude=YAB-133 Nr. YBN-138 Nr. VCA-134 Nr. &VN-1884v		
		11.12hrs pela Substat		15.19laslas	4	0	132kv Ocl-Fig	Gelepho 88	Equipment Fashare	Hand tripped	Gelephu s∕s				
	& Above														
	25.12.202	0.629861	25.12.2021	0.651389	0	7.75	220/36kV Transfer	m Dagapela	IA=70.81stA. IB=188.2mA. IC=162.5mA, HV 67 optd.	86A		transient	Charged after isolating Lamozingkha . Tripped along with 33kV baseou	pler	

## **Annexure- II**

# **Western Grid Outages** January 2021

Tripping	for the month	n of Janua	ry 2021, SMD							-	The street of the second	
Sl No.	Date of Tripping	Time of outages	Date of Normalizat ion	Time of fault was cleared	Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/line s affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Remarks
A) 400	/220/66/11	kV Malba	se Substatio		(ms)	(1111)		iduit		_	Substation	2/,
1	21.01.2021	111	21.01.2021	16:50	15	18	50/63MVA Transformer II	Malbase S/S	Min	OLTC BUCH trip, 27 trip	OLTC, OSR	Tripped on OLTC Buchlloz at 1:35 Hrs and issued shutdown to maintenance team, SMG vide PTW No. MSS/03/2021 to rectify the OLTC OSR at 9:50 Hrs. Checked LV CB, the inter tripping scheme of the transformer and charged then transformer at 16:50 Hrs.
2	22.01.2021	22:27	23.01.2021	12:18	13	20	50/63MVA Transformer II	Malbase S/S	# <b>#</b> **	OLTC BUCH trip, 27 trip	OLTC, OSR	Tripped on OLTC Buchlloz at 22:27 Hrs dated 22.01.2021 and issued shutdown to maintenance team, SMG vid PTW No. MSS/04/2021 to rectify the OLTC OSR at 9:30 Hrs. After rectifying the fault charged the transformer at 12:18 Hrs of 23.01.2021
B)220/6	6/11 kV Sing	ghigoan S	ubstation							no tripping		
B)66/33	/11 kV Phun	tsholing	Substation									
1	10.01.2021	12:42	10.01.2021	12:47	0	0.51	5MVA transformer (66/11kV)	11kV fdr II, V and 11kV fdr VII	Tripped	OLTC trip, 86	Substation	5 MVA transformer got tripped due to heavy fault on $11 kV$ feeder VII(Hospital). At $12:47 hrs$ normalsied the transformer.
2			11.01.2021	8:55	8	idle	66kV Malbase-Pling feeder	66kV Malbase- Pling feeder		Nil		At 08:55hrs charged 66kV Pling-Malbase feeder which was under idle condition with charging code 1134 from BPSO, since 66kV Pling-Gedu section was taken shutdown by TMD,Pling for replacement of borken insulator a Kabreytar Guster area. On dated 12.0.1.0201 at 11.39hrs as per instruction from BPSO opened CB of 66kV Plin Malbase feeder with opening code 0022 from BPSO at our end and feeder was kept under idle condition.
2	21.01.2021	9:13	23.01.2021	14:50	5	idle	66kV Malbase-Pling feeder	66kV Malbase- Pling feeder		Nil		At 09:13hrs 66kV Pling-Malbase feeder (feeder under idle position) was taken shutdown by TMD, Pling with work permit no 604 for carrying out annual maintanence at location PS # 16 with opening code 0040 from BPSO. On dated 23:01:2021 at 14:50hrs normalised the feeder with charging code 1186 from BPSO.
3	23.01.2021	15:12				-2.49	66kV Malbase-Pling feeder	66kV Malbase- Pling feeder		Nil		At 15:21hrs 66kV Pling-Malbase feeder CB was kept open from our end with opening code 0048 as per instruction from BPSO.
3			25.01.2021	8:36	8	idle	66kV Malbase-Pling feeder	66kV Malbase- Pling feeder		Nil	Line	At 08:36 hrs charged 66kV Pling-Malbase feeder which was under idle condition with charging code 1181 from BPSO, since 66kV Pling-Gomtu feeder was taken shutdown by TMD, Pling for replacement of polymers insulate and RoW clearing.
4	25.01.2021	8:36					66kV Pling-Gomtu feeder	66kV Pling- Gomtu feeder		Nil	Line	At 08:36hrs 66kV Pling-Gomtu feeder was taken shutdown by Parash, AE, TMD, Pling with work permit no. 60 opening code 0051 from BPSO for replacement of polymers insulators and RoW clearing.
D) 66/3	3/11 kV Ged	u Substa	tion									
1	07.01,2021	20:35	07.01.2021	20:37	0	0.87	8MVA 66/33kV Tx.	33kV Gurungdara feeder-I	Differential fault on Transformer.	Differential relay     Tripping relay 86	Line segment	Test charged and hold normal.
2	07.01.2021	20:43	07.01.2021	21:01	0	0.87	8MVA 66/33kV Tx.	33kV Gurungdara feeder-l	Differential fault on Transformer.	1. Differential relay 2. Tripping relay 86	Line segment	Test charged and hold normal.
3	07.01.2021	21:20	07.01.2021	21:22	0	0.87	8MVA 66/33kV Tx.	33kV Gurungdara feeder-l	Differential fault on Transformer.	Differential relay     Tripping relay 86	Line segment	Charged after opening breaker towards power house fdr from 33kV Gurungdara Substation.
4	07.01.2021	21:57	07.01.2021	22:03	0	0.87	8MVA 66/33kV Tx.	33kV Gurungdara feeder-I	Differential fault on Transformer.	Differential relay     Tripping relay 86	Line segment	Charged after opening breaker towards power house fdr from 33kV Gurungdara Substation.
5	11.01.2021	8:57	12.01,2021	11:37	2	1.81	66kV Chukha- Phuntsholing Line.( Pling-Gedu section)	Nil	To replace broken Insulator.	Nill	Line segment	Shutdown taken by TMD, BFC, Phuentsholing for replacing of broken insulators at PC-1 to PC-6 at Kabreytar cluster area as per shutdown approval request on dt. 22.12.2020.
6	12.01.2021	11:26	12.01.2021	11:28	0	0.54	8MVA 66/33kV Tx.	33kV Gurungdara feeder-I	Differential fault on Transformer.	Differential relay     R-phase 2.     Tripping relay 86	Line segment	Test charged and hold normal.
7	26.01.2021	10:16	26.01.2021	10:18	0	0.51	8MVA 66/33kV Tx.	33kV Gurungdara feeder-I	Differential fault on Transformer.	Differential relay     R-B phase     Tripping relay 86		Test charged and hold normal.
8	26.01.2021	10:25	26.01.2021	10:28	0	0.51	8MVA 66/33kV Tx.	33kV Gurungdara feeder-l	Differential fault on	Differential relay     R-B phase     Tripping relay 86	Line segment	Test charged and hold normal.

(F) 66/33	//11 kV Gor	nto Sele	station									
(1) 00/33	ALKY GOL	mu sub	The state of the s						Replacement of		and the second second	
1	25.01.2021	08:36				5.19	66kV Pling feeder	Nil	old insulator and ROW clearance	Nil	Location PP#20 to PP#40	Replacement of old disc with polymer and clearing RoW/location/bench cutting. Line still under shutdown
1721	7.5		tching station	03200750	505000	(-		Fed from 66kV				
1	18.01.2021 (B) 66/33kV V	0955hrs	18.01.2021	1010hrs	15min	)10.2MW	66kV Chukha fdr	Jemina IC	transient fault	CB open, G/trip	Chukha PH	
1		15:20hrs	15/01/2021	15:24hrs	4min	.350MW	66KV SF6 Breaker	Fdr. I and II	OC, OCH, EF and EFH	OC, OCH, EF and EFH relay operated	Fdr. I wanakha	Test charge at 15:21hrs and line got hold and again after 1 min line got tripped and breaker charged after opening Fdr. Isolator.
2	18/01/2021	9:55hrs	18/01/2021	10:06hrs	11min	.490MW	66KV Incommer	Fdr. I and II	Relay L23 got tripped at chukha end	Relay L23 got tripped at chukha end	66KV Incommer	66KV supply fail fro chukha ead
3	21/01/2021	00:12hrs	21/01/2021	00:18hrs	6min	.250MW	66KV SF6 Breaker	Fdr. I and II	OC, OCH and EF	OC, OCH and EF and EFH relay operated B phase	Fdr. II chapcha	Test charged at 00:12hrs but line could not hold, again test charged after keeping Fdr. I wanakha line open but line could not stand and finally line charged after oprning isolator of Fdr. II chapcha
4	24/01/2021	11:45hrs	24/01/2021	11:46hrs	1min	.430MW	66KV SF6 Breaker	Fdr. I and II	OC, OCH, EF and EFH	OC, OCH and EF and	Fdr. I wanakha	The breaker got tripped several times (Transent fault) and Fdr. I wanakha kept open to segregate fault and breaker had not tripped.
5	24/01/2021	12:20hrs	24/01/2021	12:21hrs	1min	.190MW	66KV SF6 Breaker	Fdr. I and II	OC, OCH, EF and EFH	OC, OCH and EF and	Fdr. I wanakha	Breaker charged after opening of Fdr. I Wanakha and inform to ESD personal
6	24/01/2021	13:31hrs	24/01/2021	13:33hrs	2min	.350MW	66KV SF6 Breaker	Fdr. I and II	OC, OCH, EF and EFH	OC, OCH and EF and	Fdr. I wanakha	Breaker tripped as ESD betikha had closed LBS of Betikha and breaker charged again after opening of Fdr. I Wanakha
7	27/1/2021	14:54hrs	27/1/2021	14:57hrs	3min	.390MW	66KV SF6 Breaker	Fdr. I and II	OC, OCH, EF and EFH	OC, OCH and EF and EFH relay operated B phase	Fdr. I wanakha	As it was transient fault breaker had been tripped 3 times and Fdr. I kept open and charge the breaker
	(C) 66/33kV	Olakha S	ubstation						Part Part Part Part Part Part Part Part	is phase		
1	1/11/2021	4:13	1/11/2021	4:15	2	4.4	66/33kV 20MVA, Transformer I	All the 33kV Outgoing feeders got effected as the 33kV Incomer I&II got tripped on same time	Cable Flash Over	TRAFO DIFFL. PROTN. RELAY 87.Indication: 1,3,4 & 5. 1. General Trip ,3.Diff Trip  Yph.4.Diff Trip Bph.5.Diff Prot Optd.DIR.O/C& E/F PROTN.RELAY 67Trip Relay 86.	RICB Thimphu	The Transformer was tripped due to flash over of 11kV Incomer Cable at RICB Thimphu as confirmed by the ESD Personal .Test charged the Transformer & hold normal
2	1/11/2021	4:34	1/11/2021	4:35	1	4.4	66/33kV 20MVA, Transformer I	All the 33kV Outgoing feeders got effected as the 33kV Incomer L&II got tripped on same time	Cable Flash Over	TRAFO DIFFL. PROTN. RELAY 87.Indication: 1,3,4 & 5. 1. General Trip ,3.Diff Trip Yph.4.Diff Trip Bph.5.Diff Prot.Optd.DIR.O/C& E/F PROTN.RELAY 67Trip Relay 86.	RICB Thimphu	As per the information received from ESD Thimphu, The Incomer was tripped due to flash over of 11kV incomer cable at RICB Thimphu. Test charged the Transformer & hold normal
3	1/11/2021	4:50	1/11/2021	4:52	2	4.4	66/33kV 20MVA, Transformer I	All the 33kV Outgoing feeders got effected as the 33kV Incomer I&II got tripped on same time	Cable Flash Over	TRAFO DIFFL. PROTN. RELAY 87. Indication: 1,3,4 & 5. 1. General Trip yh. 4. Diff Trip Bph. 5. Diff Prot. Optd. DIR. O/C& E/F PROTN. RELAY 67. Trip Relay 86.	RICB Thimphu	As per the information received from ESD Thimphu, The Incomer was tripped due to flash over of 11kV incomer cable at RICB Thimphu. Test charged the Transformer & hold normal
4	1/21/2021	0:03	1/21/2021	0:05	2	-14.8	66kV Olakha- Semtokha	66kV Blackout as there is no supply from Changidaphu Substation		DISTANCE PROTN RELAY-21.Indication 1,2,4&12. 1.General trip. 2.Distance Optd. 4.Zone2 Optd. 12.LBB Optd. Trip relay-86	Line Segments	Reset the relay and test charge the 66kV incomer and stood normal
5	1/21/2021	8:56	1/21/2021	8:59	3	-22	66kV Olakha- Semtokha	66kV Blackout as there is no supply from Changidaphu Substation		DISTANCE PROTN RELAY-21 Indication 1,2,4&12. 1.General trip. 2.Distance Optd. 4.Zone2 Optd. 12.IBB Optd. Trip relay-86	Line Segments	Reset the relay and test charge the 56kV incomer and stood normal
6	1/21/2021	9:35	1/21/2021	9:39	4	-19	66kV Olakha- Semtokha	66kV Blackout as there is no supply from Changidaphu Substation		DISTANCE PROTN RELAY-21.Indication 1,2,4&12. 1.General trip. 2.Distance Optd. 4.Zone2 Optd. 12.LBB Optd. Trip relay-87	Line Segments	Reset the relay and test charge the 66kV incomer and stood normal with closing code 1167 from NLDC.

(F) 66/33/11I	vV Jemina	Substation									
20.01.2021	8:58	20.01.2021	9:03	5		66 kV Chumdo line & 66 kV C/daphu line	Black out	Over Current	Start I>1	Line segment	Non directional O/C operated, Auto reclose lock out & distance protection optd. Indicated. Upon test charging at 09:03 Hrs, both the line stood normal.
20.01.2021	20:50	20.01.2021	20:54	4		66 kV Chumdo line & 66 kV C/daphu line	Black out	Over Current	Start I>1	Line segment	Non directional O/C operated, Auto reclose lock out & distance protection optd. Indicated. Upon test charging with system code: 1163 at 20:54 Hrs, both the line stood normal.
21.01.2021	9:36	21.01.2021	9:38	2	Chumdo: -3.03 C/daphu: 0.33	66 kV Chumdo line & 66 kV C/daphu line	Black out	Distance protection operated	Started phase BC	Line segment	Distance protection optd. & Auto reclose lockout, Started phase BC, Tripped phase ABC, Trip Zone I, fault location: 6.132 KM & 6.112 KM, Chumdo & C/daphu respectively. Upon test charging at 09:38 Hrs, both the line stood normal.
21.01.2021	11:25	20.01.2021	11:27	2	4:33	66 kV Chumdo line	Black out	Distance protection operated	Started phase AC	Line segment	Distance protection optd. & Auto reclose lockout, Started phase AC, Tripped phase ABC, Trip Zone I, fault location: 6.789 KM. Upon test charging at 11:27 Hrs with the code 1169, the line stood normal.
21.01.2021	11:25	20.01.2021	11:30	5	_ 5.31	66 kV C/daphu line	Black out	Distance protection operated	Started phase AC	Line segment	Distance protection optd. & Auto reclose lockout, Started phase AC, Tripped phase ABC, Trip Zone I, fault location: 6.616 KM. Upon test charging at 11:30 Hrs with the code 1170, the line stood normal.
(H) 66/11kV	Haa Subs	tation									
05.01.2021	13:33	05.01.2021	13:39	06minutes	-2.36	66kV Incomer	All the feeders	Unknown	O/C	Pangbesa s/s	Incomer tripped from Pangbesa substation on over current. Supply was resumed further, after informing the concern person.
21.01.2021	11:39	21.01.2021	11:52	14minutes	1.29	5MVA Tr- II	Incomer - II & Tr-I	To fill up the SF6 gas	Nil	Haa S/s	5MVA transformer - II was taken shutdown by substation Head to fill up the SF6 gas. The same was energised after completing the work.
(J) 66/33/1	1kV Pan	igbesa subst	tation								
05.1.2021	13.36Hrs	05.1.2021	13:39Hrs	3	2.21	66kV OG to Haa	66kV OG to Haa	O/C	Distance relay	Pangbisa-Haa	
(K) 66/33kV	Changida	phu Substatio	n								
20.012.021	857hrs	20.012.021	1213hrs	16.00	1.017	66KV Cgangidaphu	66KV Cgangidaphu		Distance Protection. zone:1(R.Y.B phase)		
20.012.022	2050hrs	20.012.022	2059hrs	9.00	6.120	66KV Cgangidaphu	66KV		86trip(A and B)		
20.012.023	857hrs	20.012.023	1213hrs	16.00	1.017	66KV Cgangidaphu	66KV		Distance Protection.		

#### February 2021

Tripping report of 66kV and above feeders for the month of February, 2021

SI No.	Date of Tripping	Time of outages	Date of Normalizatio n	Time of	Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Remarks
B)66	/33/11 kV Ph	untsholing	g Substation									
1	06.02.2021	14:48	06.02.2021	14:53	0	0.12	66kV Chukha-Pling feeder	66kV Chukha-Pling feeder		Dist Prot OPTD, Fault imp- 6.40, fault angle- 54 deg, fault current-0.359Amp, location-5.93KM, 34.5% & 86 relay.	Line	At 14:48hrs 66kV Chukha-Pling feeder got tripped on both the end. At 14:51hrs normalised the feeder,
(D) 6	6/33/11 kV G	edu Subs	tation			(a)					ole .	
1	06.02.2021	14:48	06.02.2021	14:53	0	2.34	66kV Chukha-Phuntsholing fdr.	Black out	Lightning and thundering		Line segment	Trpped from Chukha end.
2	06.02.2021	15:43	06.02.2021	15:44	0	0.49	8MVA 66/33kV Tx.	33kV Gurungdara feeder-I	Differential fault on Transformer.	1. Differential relay R-B phase 2. Tripping relay 86	Line segment	Test charged and hold normal.
3	18.02.2021	12:31	18,02,2021	12:33	0	0.41	8MVA 66/33kV Tx.	33kV Gurungdara feeder-I	Differential fault on Transformer.	Differential relay R-B phase 2.     Tripping relay 86	Line segment	Test charged the transformer but it didn't hold. Informed to Mr. Tshering Penjor JE ESSD. Received information of tree fall on the 11kV Mirching fdr of Gurungdara substation. The Mirching fdr kept on tripped condition at Gurungdara substation and charged the 33kv Gurungdara fdr I at 12-44brs and stood normal.
(E) 6	5/33//11 kV C	Gomtu Sul	bstation	. ,							V.	
1	04.02.2021	09:51	04.02,2021	13:34	3	2.98	66kV Gomtu-P/ling	Níl	Oil leakage from CT	Nil	Phuntsholing Sub Station	For arresting oil leakage from CT Y phase
(F) 2	20/66/33 kV I	Dhamdum	Substation									
1	19.02.2021	8:00	21.02.2021	19:45	11		220 kV Buscouplier	N/A	N/A	CB SF6 0/l,CB TC Trouble, CB faulty	Domdum yard, Breaker of 220kV buscoupler.	Due to chattering sound on the breaker of 220kY buscoupler, we have avail shoutdown from th BPSO on the request of our substation head. The shutdown code No. 0167 is issued by Mrs. Phu Zam. The feeder was charged at 19:50 hrs against charging code 1329
	(B) 66/33kV W	atsa Substuti	ion			-						
1	14/2/2021	08:00hrs	14/2/2021	10:31hrs	1hr	.272MW	Feeder I Wanakha	Feeder I Wanakha	O/C, OCH on ABC phase	O.C. OCH on ABC phase operated	Tree fallen on 33Kv line at wanakha as per ESD wanakha	
	(G) 66/33/11k	V Dechench	holing substatio	n								
1	2/9/2021	14:22Hrs	2/11/2021	14:27Hrs	71 Hrs	0.293	66KV Gass fdr.	Nil		O/C, B & C phase IA- 42.70A, IB-2.568KA & IC- 2.577KA, 86A & 86B	not known	Fdr tripped due to falling of huge tress on the Y & B phase, and damage both the conductor. TMD Olakha mtc team rectified it and recharged the fdr on dated 11.02.2021 at 14:27Hrs.

#### March 2021

SI No.	Date of Tripping	Time of outages	Date of Normalizatio n	Time of	Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Remarks
(A) 4	100/220/66/	11 kV Mal	base Substatio	n								
1	13.03.2021	16:50	13.03.2021	16:56	0	33	50/63MVA Transformer III	Malbase Substation	Tripped due to fault on Samtse Feeder.	Differential trip		II.1=7.28A<128.9deg, II.2=143.65A<135.55deg, II.3=70.14A<159.48deg. (Note, weather conditions were heavy rainfall, lightning, thundering and heavy wind).
2	13.03.2021	16:50	13.03.2021	16:57	0	10	220kV Malbase - Samtse Feeder	Malbase &Samtse Substation	Tripped due to Overcurrent and Earthfault	Distance protection operated and O/C protection operated.		Fault data from IDMTL Relay, 61 Phase A (FWD) IDMTL-HSI> IA =3009A, Phase B < FWD> IB= 98.19A, Phase c < FWD> IC = 3264A, Earthfault < REV> IE=2686A, (Note, weather conditions we heavy rainfall, lightning, thundering and heavy wind).
(B)2	20/66/11 kV S	inghigoan	Substation									
1	13.03.2021	16:50	13.03.2021	17:08	0	3	220kV Singhigoan -Samtse Feeder.	Singhigoan GIS & Samtse Feeder	Tripped due to Overcurrent and Earthfault	Distance protection operated and 86 operated.		II.1=2803A, II.2=75.79A, II.3=2765A, IE=2042A.
(B)6	6/33/11 kV Ph	untsholin	g Substation									
1	05.03.2021	18:27	05.03.2021	18:33	0	0.14	66kV Chukha-Pling feeder	66kV Chukha-Pling feeder	Distance Protection	Dist Prot OPTD, Fault imp- 7.9, fault angle- 51 deg, fault current- 2.617Amp, location- 40.9% & 86 relay.	Line	At 18:27hrs 66kV Chukha-Pling feeder got tripped on both the end. At 14:51hrs normalised the feeder. Weather condition was lightning and raining during the time of tripping.

D) (	66/33/11 kV G	edu Sub	station									
1	05.03.2021	300000	05.03.2021	18:33	0	3.19	66kV Chukha-Phuntsholing fdr.	Black out	Lightning, thundering & raining		Line segment	Trpped from Chukha end.
1	6/33//11 kV 0 04.02.2021	09:51	04.02.2021	13:34	3	2.98	66kV Gomtu-P/ling	NII	Oil leakage from	Nil	Phuntsholing Sub Station	For arresting oil leakage from CTY phase
) 2	20/66/33 kV 1	Dhamdun	Substation			1	**		A Albert	<u> </u>	1 Partition of the last of the	
1	13.03.2021	16:50	13.03.2021	17:04	0	-2.83	220kV Singhigoan	N/A	Over current	REL 670 MAIN 1- General trip,Zone 1, Rand Bphase fault.	N/A	Trip values. II.1- Fault mag-207.78A, Fault angle88.76deg. II.2- Fault mag-91.40A, Fault angle10.80deg. II.3-Fault mag-347.06A, Fault angle64deg.
	(B) 66/33kV W	atsa Substa	tion									
ı	7/3/2021	10:10hrs	7/3/2021	10:13hm	0	.480MW	66KV Incommer	Fdr. I and II	Olakha fdr. Got tripped at chukha	66Kv fail from chukha end as olakha fdr. Got tripped at chukha end		
	(C) 66/33kV C	Dlakha Sub	station									
1	3/7/2021	8:40	3/7/2021	8:42	0	-26.6	66kV Semtokha-Olakha line	Olakha substation	Line Fault	DISTANCE PROTN RELAY-21.Indication 1,2,4&12. 1.General trip. 2.Distance Opted. 4,Zone2 Opted. 12.LBB Optd.Trip relay-86		66kV Semtokha-Olakha line was tripped on distance protection relay Zone 2.Reset the relay and charged the 66kV incomer and stand normal.
2	3/7/2021	8:54	3/7/2021	8:55	0	-13.1	66kV Semtokha-Olakha line	Olakha substation	Line Fault	DISTANCE PROTN RELAY-21.Indication 1,2,4&12. 1.General trip. 2.Distance Opted. 4.Zone2 Opted. 12.IBB Optd.Trip relay-86		66kV Semtokha-Olakha line was again tripped on distance protection relay Zone 2.Reset the relay an charged the 66kV incomer and stand normal.
3	3/7/2021	9:20	3/7/2021	9:22	0	-21.1	66kV Semtokha-Olakha line	Olakha substation	Line Fault	DISTANCE PROTN RELAY-21 Indication 1,2,3&12. 1 General trip. 2.Distance Opted. 3.Zone 1 Opted. 12.LBB Optd.Trip relay-86		66kV Sentokha-Olakha line was tripped on distance protection relay Zone 1.Reset the relay and charged the 66kV incomer as per the instruction received from BPSO and stand normal.
1	3/7/2021	10:24	3/7/2021	10:29	0	-27.7	66kV Semtokha-Olakha line	Olakha substation	Line Fault	DISTANCE PROTN RELAY-21.Indication 1,2,4&12. 1.General trip. 2.Distance Opted. 4.Zone2 Opted. 12.LBB Optd.Trip relay-86		66kV Semtokha-Olakha line was tripped on distance protection relay Zone 2. Reset the relay and charged the 66kV incomer as per the instruction received from BPSO and stand normal.
5	3/7/2021	14:26	3/7/2021	14:31	0	-28.3	66kV Semtokha-Olakha line	Olakha substation	Line Fault	DISTANCE PROTN RELAY-21 Indication 1,2,3&12, 1,General trip, 2,Distance Opted, 4,Zone 2 Opted, 12,LBB Optd,Trip relay-87		66kV Semtokha-Olakha line was tripped on distance protection relay Zone 2.Reset the relay and charged the 66kV incomer as per the instruction received from BPSO and stand normal.
6	3/30/2021	21;11	30/3/2021	21:13	0	12.2	20MVA Transformer I	All the Outgoing feeders got effected as the 33kV Incomer I & II was tripped.		Differential Protection Operated. Indication 1,3,4 &5. L.General trip. 3. Differential trips on Y Phase 4 Differential tripped on B Phase, 5. Differential protection operated		The 66/33kV 20MVA Transformer I was tripped due to tripping of 33kV O/G feeder VI (DPH II)
7	3/30/2021	21:20	30/3/2021	21:21	0	12.2	20MVA Transformer I	All the Outgoing feeders got effected as the 33kV incomer I & II was tripped.		Differential Protection Operated. Indication 1,3,4		The 66/33kV 20MVA Transformer I was tripped due to tripping of 33kV O/G feeder VI (DPH II)

	(D) 66/33/11k	V Lobeysa	Substation								
	18.03.2021	09:16hrs	31.05.2021	17:00hrs	1791	2,140	66kV LSA-SEM	NA	NA	NA	66kV LSA -SEM taken shutdown as per the shutdown approval No.10A/BPC/BPSO/PSOD/Vol-1/71 carry out the re-conducting HTLS Project from Semtokha to Dochula. Supply no interruption feeded from Basochu.
	(E) 66/33/11 1	kV Paro Su	bstation					1			
1	3/7/2021	10:16	3/7/2021	10:17	0	9.29	66kV Line IN	Tripped from Chumdo	Tripped from Ch	umdo	
	(F) 66/33/11k	V Jemina S	ubstation				100		114-11-11		
1	07.03.2021	8:14	07.03.2021	8:45	0	3.09	66 kV Chundu	Black out	Distance relay operated, Phase ABC, Zone 1	Dist. Relay, Ph. ABC, Zone 1.	Both the 66 kV lines, Chundu & Changedaphu tripped on Phase ABC, Zone 1 as shown by operated Distance relay at 08:14 Hrs, the Chando line charged at 08:45 Hrs with charging code; 13:94.
2	07.03.2021	8:14	07.03.2021	8:47	0	-5.27	66 kV Changedaphu	Black out till 08:45 Hrs	Distance relay operated, Phase ABC, Zone 1	Dist. Relay, Ph. ABC, Zone 1.	Both the 66 kV lines, Chunds & Changedaphu tripped on Phase ABC, Zone 1 as shown by operated Distance relay at 08.14 Hrs, the Changedaphu line charged at 08.17 Hrs with charging code, 1394.
3	07.03.2021	8:50	07.03.2021	9:00	0	3.09	66 kV Chundu	Black out	Distance relay operated, Phase ABC, Zone 1	Dist. Relay, Ph. ABC, Zone 1.	Both the 66 kV lines, Chundt & Changedaphu tripped on Phase ABC, Zone 1 as shown by operated Distance relay at 08:50 ftr after charging the Changedaphu line at 08:47 Hrs, the Chundu line charged at 09:00 Hrs after instruction from BPSO
4	07.03.2021	8:50	07.03.2021	10:10	1	-5.27	66 kV Changedaphu	Black out till 09:00 Hrs	Distance relay operated, Phase ABC, Zone 1	Dist. Relay, Ph. ABC, Zone 1.	Both the 66 kV lines, Chundu & Chungedaphu tripped on Piase ABC, Zone 1 as shown by operated Distance relay at 08:50 firs, after charging the Changedaphu line at 08:47 Hrs. the Changedaphu line was kept open, however, again at 10:10 Hrs. with the charging code; 1395 from BPSO, the Changedaphu line was charged, but the line couldn't hold and tripped along with 66 kV Chundu Thereafter, the Changedaphu line kept open.
5	07.03.2021	10:10	07.03.2021	10:16	0	-2.97	66 kV Chundu	Black out	Distance relay operated, Phase ABC, Zone 1	Dist. Relay, Ph. ABC, Zone 1.	Both the 66 kV lines, Chunda & Changedaphu tripped on Phase ABC, Zone I as shown by operated Diviance relay at 10:10 firs after charging the Changedaphu line at 10:10 Hrs, the Chunda line charged at 10:16 Hrs after instruction from BPSO.
	(I) 220kV Suk	ostation Sea	ntokha			),		II			
1	3/18/2021	0915hrs				-2.040	no interruption	shut down taken by Mr. Kinley Wangchuk (project manager)for re-conducting HTLS line for new bay at Semtokha S/S			
	(J) 66/33/11	kV Pang	besa substatio	on							
	Nil										
	(K) 66/33kV	Changidaph	u Substation								
1	3/7/2021	814hrs	3/7/2021	851hrs	0.00	5.230	66kV Jemina to Changidaphu	Changidaphu	Covering of Insulator by Snow/Ice	Distance Protection	
2	3/7/2021	1104hrs	3/18/2021	1031hrs	263.00	5.230	66kV Jemina to Changodaphu	Changidaphu	Covering of Insulator by Snow/Ice	Distance Protection	
3	3/7/2021	854hrs	3/7/2021	1105hrs	2.00	-0.990	66kV Olakha to Changidaphu	Olakha	Covering of Insulator by Snow/Ice	Only 86 Relay Operated	

# April 2021

							Trip	ping report of 66kV as	nd above feeders fo	or the month of April, 2021			
SI No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
(A) 400	/220/66/11 kV Mal	base Substatio	in .										
1	22.04.2021	12:40	22.04.2021	13:08	0	27	400kV Siliguri Feeder	Siliguri Substation	Transient fault	Main I & 86A B optd.			IL1=376.9A<100.1deg, IL2=256A<47.17deg, IL3=1613A<90.29deg, IL4+4342A<87.05deg (Note: weather conditions were light rainfall with lightning).
2	22.04.2021	12:40	22.04.2021	12:48	0	0	220kV Bus coupler	Malbase Substation	Transient fault	10> trip, 86 optd.			Earthfault. (Note: weather conditions were light rainfall with lightning).
(B)220/6	6/11 kV Singhigoan	Substation								24			
1	22.04.2021	12:40	22.04.2021	12:47	0	5.1	66kV Bhutan Concast fdr.	Singhigoan GIS	Tripped due to Overcurrent	Directional overcurrent trip, IEp Trip, 86 optd			IL1=0.12kA, IL2=0.02kA, IL3=0.08kA,
2	22.04.2021	12:40	22,04,2021	12:48	0	0	66kV Main Bus I	Singhigoan GIS	Tripped due to Overcurrent	0/C Trip, General Trip, 86 optd			II.1=0 22kA, II.2=0.26kA, II.3=0.04kA,
(B)66/33	VII kV Phuntsholing	g Substation							a continuo de la continua del continua del continua de la continua				
1			13,04,2021	9:05	9	idle	66kV Malbase- Pling feeder	66kV Malbase-Pling feeder					At 09.05hrs charged 66kV Pling-Malbase feeder which was under idle condition with charging code 1969 from B750 (for supply reliability at Pling Sa), aime 66kV Chukha-Gedu section was taken shutdown by TMD, Tahimalahka for carrying out annual maintenance on 66kV chukha-Gedu section (i.e replacement of insulator with glass and polymer). On dates 18.04.2021 at 17:50hrs opened CB of 66kV Pling-Malbase feeder with opening code 0413 from BFSO and again the feeder was kept under felle condition.
2	22.04.2021	3:07	22.04.2021	3:16	0	9.00	66kV Pling- Gomtu feeder	66kV Pling-Gomtu feeder	Tripped	DSTN 0PTD, 186&86	Line		At 03:07hrs 66kV Pling-Gomta feeder got tripped at our end and 66kV Chukha-Pling feeder got tripped at Chukha-Pling feeder got tripped at Chukha-end causing black out at Phuentsholing. Weather condition was rating with lightning during the time of triping, at 03:10hrs charged 66kV Malbase-Pling feeder after informing BFSO. At 03:16hrs normalized 68kV Pling-Gomta feeder after getting delarance from BPSO. At 03:25hrs nopended CS of 66kV Pling-Malbase feeder with opening code 0433 from BPSO and again the feeder was kept under idle condition.

E) 66/3	3/11 kV Gomtu Su	bstation											
1	22.04.2021	03:09	22.04.2021	03:33	0	-7.57	66kV Incomer Damdum & Gomtu- Phuntsholing	Gomtu Substation	Transient fault	General trip Zone-4 trip R ph. Fault	Line segment	Transient Fault	66 kV Phuentsholing supply resumed at 3:16 hrs. 66kV Damdum feeder charged after informing to BPSO and Dhamdum Substation.
	66/33 kV Dhamdu			2.65	-		Leanne	40.4		4.24		1 2000	Parties and the second
1	22.04.2021	3:07	22.04.2021 for the month of Al	3:33	31	7,7	66 kV Gomtu fdr	N/A	Tripped	N/A	-	N/A	66kV Gemtu fdr tripped on B phase fault at 3:07HRS.
		тирринд керогі	for the month of Al					Name of the			Exact location of fault		
SL No.			Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Substation/lines affacted by the fault	Reasons of fault	Relay operations	[Line segment/ Substation]	Type of outages	Remarks
	(A) 66kV Chumdu												
	(B) 66/33kV Watsa												
	(C) 66/33kV Olakh	a Substation											
1	08/04/2021	10:40	08/04/2021	12:43	0	7.7	66kV Olakha- Changidaphu Line	Olakha substation	Due to fault at Dechenchholing line	Distance protection relay 21 operated. Indication 1(general trip)	66kV Gasa line from Dechenchholing	Transient Fault	The Supply was fail from Semtokha due to fault at 66kV Dechenchboling to Gase Line as information received from BPSO and shift duty of Semtokha Substation.
4	19/04/2021	11:58	19/04/2021	12:10	0	5	66kV Olakha- Changidaphu Line	Olakha Substation	Under voltage	Only Trip relay 86 Operated	Olakha Substation	Temperary	The supply was fail due to under voltages. Reset all the relays and charged the feeder, hold normal.
5	4/22/2021	1:40	4/22/2021	1:42	0	3.3	20MVA Transformer I	Only 33KV Chubachu freder IV was effected as the other feeders was fed from Transformer II	Due to tripping of 33kV Chubachu feeder (Fdr.IV)	TRAFO DIFFL. PROTN. RELAY 87.Indication: 1,3,4 & 5. 1. General Trip, 3 Diff Trip Yph.4.Diff Trip Bph.5 Diff Prot.Optd.DIR. O/C & E.F. PROTN.RELAY 67.Trip Relay 86.	Line Segment	Transient Fault	The 66/33&V 20MVA Transformer I was tripped due to tripping of 33&V O/G feeder IV (Club'achu) Charged the feeder and hold normal.
6	4/22/2021	13:15	4/22/2021	13:37	0	8.80	20MVA Transformer I	Only 33KV Chubachu feeder IV was effected as the other feeders was fed from Transformer II	33kV Chubachu	TRAFO DIFFL PROTN. RELAY 87 Indication: 1,3,4 & 5. 1. General Trip, 3. Diff Trip Yph 4. Diff Trip Bph 5. Diff Prot Opti Trip Relay 86.	Line Segment	Transient Fault	66/33kV 20MVA Transformer I tripped the to tripping of 33kV O/G IV (Chubuchu feeder) Charged the feeder after confirmation and clearance received from ESD personal and hold normal.
	(D) 66/33/11kV Lo	beysa Substation											
1	26.04.2021	20:19firs	26.04.2021	21:45hrs	1	-9.450	66kV LSA-Basoch	Lobeysa substation	Basochu muchine tripped	NA	Basochu Plant	NA	66kV LSA -Basschu feeder tripped at 20:19hrs from Basochu end and No relay& breaker operated at our end Supply resumed at 21:45hrs from Basochu end.
2	26 04 2021	23:05hrs	27.04.2021	00:21hrs	1	-7.020	66kV LSA-Basocia	Lobeysa substation	Basochu machine tripped	NA NA	Basochu Plant	NA	66kV LSA «Basochu feeder tripped at 23:05trs from Basochu end and No relay& breaker operated at our end Supply resumed at 00:21hrs from Basochu end on 27:04:2021.
	(E) 66/33/11 kV Pa	ro Substation						JO COLO DE SESSES DOCUMBRISTON	110000000000000000000000000000000000000	1-0000		0.5.80	
	Nil												
	(F) 66/33/11kV Jer Nil	nina Substation											
	(G) 66/33/11kV De	ahanahallun suket	ntlan				100						
1	4/8/2021	10:47Hrs	4/8/2021	11:08Hrs	ō	3.113	Both 10MVA Tr.	Whole o/g fdr.	Due to insulator Puncture/broken	ouly 86 relay	Opposite of Dling S/S, 66KVline Semtokha to Dling incomer fdr.	Tripped	Sound came out like boom blast from opposite of our substation from double circuit tower, lat we have found out that one side of double stringing insulator was puncture/broken due to low rating, 66KV incomer line tripped from senstokla end, however, both 10MVA Tr. are tripped our red.
	(H) 66/11kV Han S	ubstation			10	l.	0						
1	01.04.2021	11:28	01.04.2021	11:39	0	-2 28	66kV Incomer, along with all the feeders.	unknown	oc	Pangbess substation, Paro	66kV incomer tripped from Pungbesa substitution on overcurrent. The same was normalised further.		
2	09.04.2021	14:07	09.04.2021	14:10	0	-1.8	66kV Incomer, along with all the feeders.	unknown	oc	Pangbesa substation,Paro	66kV incomer tripped from Pangbesa substation on overcurrent. The same was normalised further.		

	(I) 220kV Substan	tion Semtokha											
1	08.04.2021	10:44hrs	08.04.2021	10:52hrs	0,00	21.560	50MVA Transformer 1	220kV Semtokha Substation	R phase Isolator purctured above Dechencholing	HV and LV Backup protection Optd. (HV: Ia=287.2A, Ib=61.27A, Ic=63.11A) (LV: Ia=979.7A, Ib=183.2A, Ic=195.4A)	220kV Semtokha Substation	Trasient	
2	08.04.2021	10:44hrs	08.04.2021	10:45hrs	0.00	21,610	50MVA Transformer 2	220kV Semtokha Substation	R phase Isulator practured above Dechencholing	HV and LV Backup protection Optd. (HV: Ia=156.1A, Ib=119.5A, Ic=84.66A) (LV: Ia=509.5A, Ib=386.3A, Ic=281.4A)	220kV Semtokha Substation	Trasient	
3	28.04.2021	12:10hrs	28.04.2021	12:14hrs	0.00	17.870	50MVA Transformer 1	220kV Semtokha Substation	Due thunder and lightning Dechencholing line triped and samultenously both 50MVAtripped.	Differential protection optd. HV and LV Backup protection. Optd.	220kV Semtokha Substation	Trasient	
4	28.04.2021	12:10hrs	28.04.2021	12:13hrs	0.00	17,900	50MVA Transformer 2	220kV Semtokha Substation	Due thunder and lightning Dechencholing line triped and samulteneously both SUMVArraped.	Differential protection optd. HV and LV Backup protection. Optd.	220kV Semtokha Substation	Trasieut	
5	08.04.2021	10:44hrs	08,04.2021	10:59hrs	0.00	6.850	66kV Semtokha- Dechencholing Feeder	220kV Semtokha Substation & 66kV Dechencholing Substation	R phase Isolator purctured above Dechencholing	In>> Trip Ia= 1.951kA, Ib=56.87A, Ic=45.23A		Permanent	
5	28.04.2021	1.2:10hrs	28.04.2021	12.21hrs	0.00	7.420	66kV Sentokha- Dechencholing Feeder	220kV Semtokha Substation & 66kV Dechencholing Substation	R phase Isulator punctured above Deciseactioning	Distance Protection Optd. In>> Trip Ia= 3.318kA, Ib=74.6A, Ic=62.66A		Trasient	
	(J) 66/33/11kV	Pangbesa sub	station			()	10						
1	02.04.2021	11:33Hrs	02.04.2021	11:39Hrs	0	2.21	66kV OG Haa feeder	Haa	o/c			Transiera	
2	09.04.2021	14:07Hrs	09.04.2021	14:10Hrs	0	1.74	66kV OG Han feeder	Han	o/c			Transierd	
	(K) 66/33kV Cha		on		5			T.					
	(L) 66/33kV Dam	iji Substation											
1	08.04.2021	10:48hrs	11.04.2021	3:40hrs	76	•0.29	5/33KV Incoming li	ne	Failure of insulator	NA NA			66kv incoming line was tripped at 10.48 hrs and line at Damji Substation had been back feed from Punakhu at 14:07 hrs. 66kv line charged at 15:40 hrs as per the closing code 1961 from BPSO.
2	28.04.2021	12:14hrs	28.04.2021	12:27hrs	0	-0.29	6/33kv incoming lin	ie:	Hand trip	NA NA			66kv line breakdown ( Hand trip) from Semtokha.

# May 2021

Si No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line Substation]	segment/	Type of or	utages		Remarks
(A) 400/3	20/66/11 kV Ma	albase Substation	n					Jaun		<u> </u>						
56kV & A	03.05.2021	10:25	03.05.2021	13:48	3	-44	220kV Chuldha-Malboso Feeder 3	Malbase s/s	Overcurrent	zone 1 trip, 86 Operated, fault loop L2- N, diastance at 10 97 km	L2-N=10 97 km		Overcurre	et fault	Ia =68.66 A, Ib=5.381kA, Ic=157A	
2	3 05 2021	13:25	03.05.2021	15:02	1	23	50/63 Mva Trafo 3	Malhase S/S	Overcurrent	Differential trip,27 Trip, 36 operated harm BLK trip			Overcure	et fault	R phase=148 22A/6.70deg, Y phase N=229.97A/175.10deg	=708.53A/1.90deg, B phase=89.23A/72.53 dog,
3	03.05.2021	14:50	03.05.2021	14:58	0	10	220kV Malbase-Samtse Feeder	Dhamdum S/s	Earth foult	Main 1 trip,zone 1 trip,8/U trip, 86 operated,fault loop-L1- N, distance at 18.8 km	fault loop: L1-N=18.8	lan	Overcurre	nt fault	R phase-4308A/283.9deg, Y phase N=4141A/283.9deg	-55.02A/116.5deg, B phase-108.4A/109.8deg,
4	3.05.2021	15:01	03.05.2021	15:52	0	·9.	220kV Malbuso-Samtse Feeder	Dhamdum S/s	Earth fault	Main 1 trip,zone 1 trip,B/U trip, 36 operated/suit loop-L1- N, distance at 16 km	fault loop- L1-N=16 l	karı	Оунголги	nt fault	R phase= 4608A/283.8deg,Y phase N=4447A/ 283.6deg	54.84A/119.2deg, B phase= 107.2A/111 deg.
5	03.05.2021	0:22	03.05.2021	0:31	0	7	220kV Malbase-Samtse Feeder	220kV samtse feeder	Overcurrent	Rel 511, overcurrent protection operated, distance protection operated, Main 1 trip, Trip R,Y,B phase, zone 1 trip			Overcurre	at fault	67/67 N, G1 phase A FWD IDMTC[E FWD[IDMTC]=1924A, E.F. (REV) le	IIS) In=3952A, Ib= 135.7A,Ic 3337AA
6	04.05.2021	1:08	04:05.2021	1:15	0	16	66 kV Pasakha Feeder 1	66kV pasakha feeder 1.	Overcurrent	Ral670,IEF-50N trip,86 operated,general trip,IOC50 trip			Overcurre	st fault	R phase= 2316.17<43.77deg.Y phase 1887.63A<53.50 deg.N=832.07A<1	e= 1997.79A<175.7deg, B phase= 64.16deg
76	04.05.2021	1:08	04.05.2021	1:15	0	20	66 kV Pasaidha Feeder 2	66kV pasakha feoder 2.	Overcurrent	Rel670, 51 start, 86 operated, IOC50 trip, general trsp, IEFSON trip			Overourre	at foolt	R phase=3233.90A<70.75deg,Y pha 525.15A=86.90 dag	se= 2128.21A<173.84deg, B phase=
8	04.05,2021	1:08	04.05.2021	1:15	U	21	66 kV Pasaidas Feeder 4	66kV pasakha feeder 4.	Overcurrent	Rel 670,51 start,86 operated,10050N trip,general trip,IEF50N trip			Overcurre	st fault	R phase=3345A<66.27deg,Y phase- dog	3948.39A<164.22deg, 8 phase= 5860.2A<35.05
9	11.05.2021	18:17	12.05.2021	12:43	18	72	200 MVA ICT Malbase S/s	Malbase S/S	BuchbolzTrip	B phase buchholz aların, buchholz trip, 86 Kelay trip	ICT B phase transform	ner			L1=0.092 A<13.83 deg, L2=0.022 A	140.4 deg, 1,3=0.087 A/<6.15 deg
(B)220/	66/11 kV Sing	ghigoan Subs	station													
1	03.05.20	21 1	5:11	03.05.2021	16:03	0	3.5	220kV	Singye Samtse	GIS, Singhigoan s/s	Overcurrent		ent trip and otpd.			Overcurrent Fault
(B)66/3	3/11 kV Phun	atsholing Sut	station								<u></u>		- V			
1	03.05.20	21 1	3:37	03.05.2021	15:00	1	-2.26	66kV Chi	ukha-Pling feeder	66kV Chukha-Pling feeder		DSTN OP	TD, 186&86			
2				03.05.2021	13:42	13	idle	66kV	Malbase-Pling feeder	66kV Malbase- Pling feeder						
3	03.05.20	21 1	5:12	03.05.2021	15:18	0	-4.60	66kV Chi	ukha-Pling feeder	66kV Chukha-Pling feeder	3	DSTN OP	TD, 186&86			
4	05.05.20	21 1	3:56	05.05.2021	14:04	0	+3.09	66kV Chi	ukha-Pling feeder	66kV Chukha-Pling feeder	:	DSTN OP	TD, 186&86			
5	05.05.20	21 1	3:56	05.05.2021	15:41	1	-1.48	66kV Pli	ng-Gomtu feeder	66kV Pling-Gomtu feeder	Tripped	DSTN OP	TD, 186& <b>86</b>		Line	
6				05.05.2021	14:01	14	idle	66kV	Malbase-Pling feeder	66kV Malbase- Pling feeder						
7	14.05.20	21 0	):42	14.05.2021	0:48	0	-3.83	66kV Chi	ukha-Pling feeder	66kV Chukha-Pling feeder	1	DSTN OP	TD, 186&86			

Ds 66/3	3/11 kV Gedu Su	ibstation											
1	03.05,2021	13:37	3.05.2021	14:15	0	1.73	66kV Chukha- Phuntsholing	Black out	Due to bad weather		Line segment		Weather condition: Heavy Rainfall, 66kV line was charged from Chulcha after improving weather condition.
2	03.05.2021	15:10	03.05.2021	15:18	0	1.73	66kV Chukha- Phunetholing	Black out	Due to bad weather		Line segment		Weather condition: Heavy Rainfall, 66kV line was charged from Chukha after improving weather condition.
3	00.05,2021	10:12	10.05,2021	20:33	10	0.44	5MVA 66/33kV Tx-III	33kV Gurungdara feeder-Eand II	33kV Supply extended from 33kV Gurungdara-1		Substation	Shutdown	Taken shutdown for installation and commissioning of JJkV Bus section-II penels vide work permit No. 39 issued to Mrs. Rinchen Zangmo, Sr. Engineer of SMD Pling.
4	10.05.2021	9:26	10.05.2021	9:48	0	0.4	8MVA 66/33kV Tx-I	33kV Gurungdara feeder -I	Bad weather	Differential fault on R phase	Line segment		Weather Condition: Thundering and Raining. Test charged after weather got clear and stoc normal.
5	14.05,2021	0:42	14.05,2021	0:46	0	1.54	66kV Chukha- Phuntsholing line	Blackout	Due to bad weather	10.000	Line segment		Weather condition: Raining and thundering, 66kV line charged from Phantsbeling end.
6	19.05.2021	16:45	19.05.2021	16:55	0	0.55	8MVA 66/33kV Tx-I	33kV Gurungdara foeder-1 & 33kV Gorungdara-H	REF	REF	Line segment		Test charged and hold normal.
7	20.05.2021	15:33	20.05.2021	15:42	0	0.41	8MVA 66/33kV 7x-1	33kV Gurungdara fdr-l	REF	REF	Line segment		Test charged and hold normal.
(E) 66/3	3/11 kV Gemtu S												
1	03.05.2021	15:11	03.05.2021	15:18	0	-9.584	66kV Dhamdam	Gomtu Substation	Nil	Nil	Malbase Substation	Tripped on Fault	66kV supply tripped from Malhase Sub Station.
2	04.05.2021	12:32	04.05.2021	19:54	7	-7.029	66kV Dhamdum	Nil	Over Current	General trip, Zone- trip, R ph fault, Y ph fault, B ph fault V.T fuse fail.	66kV Samtse-Gomtu Line	Tripped on Fault	66kV Dhamdum tripped due to rainstorm and supply could not withstand from the both end thereby test charged informoring to BPSO at 07:54 hours and the line withstand.
3	05.05.2021	13:59	05.05.2021	14:08	0	-10.734	66kV Dhamdum & Gomtu Phuntsholing	Whole Gorntu	Over Current/Transient Fault	General trip, Zone- 4trip, R ph fault, Y ph fault, B ph fault	66kV Samtse-Gomtu Line	Tripped on Fault	66kV Dharndum tripped due to rainstorm. Supply charged with confirmation from BPSO at 14.00hours. 66kV Gomtu-Phuntaboling supply resumed at 15.41hrs.
(F) 220µ 220k V	66/33 kV Dhamdi	um Substation		"				<u> </u>				"	
1	03.05.2021	15:11	3.05.2021	16:04	0	-3.19	Singeygaong Damdum Feeder	Damdom S/S	Transent fault	REL670(21L-M1)	6.5 KM	Line fault	L1 &N Fault , Fault distance 6.5 Km, Zone +1 fault ,
2	04.05.2021	0.21	04.05,2021	0:35	0	-1 93	Singeygaong Damdum Feeder	Damdom 5/5	Transent fault	REL670(21L-M1)	20 KM	Line fault	Line tripped due to heavy rainfall and lightning and thunder. Line fault record as under: Zone 1. 4Phase to phase fault (R. to B) Distance/fault location 20.1 KM (50.3%)
66kV			-						'				
1	04.05.2021	0:36	04.05,2021	7:29	6.	7.32	Gomtu feeder	NA.	Heavy rainfall and lightning and thunder	REL670(211)	NA	Line fault	Line tripped due to heavy rainfall and lightning and thunder. Line fault record as under: Zone 1. $O/C$ on R 8B $\theta$ fault, 1) Abs Dist: 19.99. 2) Fault Rel Dist: 49.98%, 3F ault to pt 13.1.
2	05.05.2021	13:54	05.05.2021	14:06	0	12.33	Comitu feeder	NA.	Heavy rainfall and lightning and thunder	REL670(21L)	NA	Line fault	Line tripped due to heavy rainfall and lightning and thunder. Line fault record as under: Zone 2&3 started. 1   Fault loop type: L2 with N, 2)Fault location. 15KM (100%)
		Tripping Report f	or the mouth of N	1AY 2021		]							
SI, No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
	(A) 66kV Chumdu	switching station	ė.										
2	05.05.2021	1320tos	03.05.2021	1325hrs		(-)5.7MW	66kV both vic	Pare and Pangbase	Transcient finalt	O/C & CB open	Chrende	Trip	
2	50 1898540-0511 1	1355hrs		1.405hrs		(-)8.7MW	66kV Cukha ie	Paro and Punghasa fed from 66kV	Rectifications of the last	77,098578531049014	55/45/65/55		
3.0	09.05.2021	1614hre	09.05.2021	190thrs	2hrs	(-)6.3MW	66kV Jemina i e	Chukha i/c	Fault at Clisidia end	CB open	Fault at Olakha end	Trip	Could not charge due to DC faiture
	(B) 66/33kV Wate			-	-							1	
		13:38hrs	3/5/2021	14 Othes		0 260MW	66KV Incommer	Fdr.1 and IT	SOLE GOVE THESE BY LAKE	Incommer failed from chold	ha eral as chang golaphis got tripped at warsa are tree to no appuar mannenance at ec aucus-	Trip	
		9.00brs	24/5/2021	10:12hrs	The	.260MW	66KV Incommer	Fdr.1 and II		mon and inspect party. A comple	school: Exided Scott algorida or	Shuldown	
	28/5/2021	LE Lithes	28/5/2021	16.25hrs	There.	330MW	56KV Incommen	Febr. Land II	Stud down taken by TMD	Ismaskla for Re jumper at	Watsa Tie line after completion of armul maintenance	Sandown	

	(C) 66/33kV Ola	hha Sabatation											
	(C) 96/35KV OIA	MHA SHOSTADOR					1	Olakha substation				1	
1	5/3/2021	13:49	5/3/2021	13:51	0	6,5	20 MVA transformer I	and all outgoing feeders					Sopply fail from Chikhn (unit fail) supply fail from Chikha at 13:38frs and charge at 14:08frs.
*	3/9/2021	16:22				4.5	66kV Otakha-Changidaphu Line	66kV Olakha- Chaegidapha Line		On Relay 78A611 Distance Protection Relay 21, 1. General Trip 2. Distance Operated 3. Zone One Operated dang with Tripping relay 86 operated. On Relay 78162 21, General Tripped, 2. Direction Over Current and Earth Full Operated.	II park son Serbifiang		The 66kV Olakha-Changidaphu was tripped on distance relay, so the 66kV line was not Charged owing to the indication and operation of relay. Operational personal has seen that there was pour to not be Gantry of Y Parie conductor during tripping happent, therefore informed to BFRO in this congest Since parallog could not proceed the to time constrain, The 66kV line was kept under shat down for next day Patroling by TMD line person.
30	5/9/2021	16:22	5/9/2021	17:24	1		66kV Bas Complex	Olaklıs Substaticus		On Relay 78J61 Over Current and Earth fault Protection Relay 50/S1. 1. General Trip 3. Earth Fault Operated 4. LBB start along with Tripping relay 86 operated.			Supply fail from 66kV Semisiku Line and 66kV Champidaphu Line
4	5/9/2021	16:52	5/9/2021	17;21	0	-16.8	66kV Semtokka-Olakha line	Olakha substation and all outgoing Seeders		Ou Relay "SA611 Distance Protection Relay 21, 1. General Trip 2. Distance Operated 1. Zone One Operated 1. Long Operated Operated along with Tripping relay 86 Operated			Supply fail from 66kV Sembolin Line and 66kV Changidapha Line
3	5/11/2021	15:52	5/11/2021	15:53	0	-13.7	66kV Olakha-Semtokha	Olakha substation and all outgoing feeders		1.LLB operated			Feeder was triped while Test charging of 66kV Olakha-Changidaphn feeder which was under shandown for changing of 3 phase Conductor between death end tower and 66kV gamry at Olakin substation. Are resetting all relays, sest charge the feeder and hold normal.
6	5/11/2021	15:52	5/12/2021	17:38	25	4.5	66kV Ölakha-Changidaplus Line	66kV Olakha- Chaegidaphu Line	conductor burns at IT park	On DISTANCE PROTN Relay 21,1, General Trip 2. Distance Operated 3.2one 1 Opered along with Tripping relay 86 operated.	IT park		Standown taken by Dupthe Wingdi to provide trusion fiftings for long opinional revenuing and critical. As per Approved repress and, EEE Add Sch SETEMOTOTERS (2012-10), 147, 148, 148, 148, 148, 148, 148, 148, 148
1	5/11/2021	15:52	5/11/2021	16:05	0		66kV Bus Coupler	Olakha Substation	OC&EF and Distance protection	Trip Relay 86	Ofakha-Chang daphu feeder	Тепроситу	Foeder was triped while Tost charging of 56kV Olakha-Changidaphs foeder which was under shardown for changing of 5 plane Conductor between death end tower and 66kV gastry at Olakho substation. After resetting all relays test charge the feeder and hold normal.
		Lohoysa Substation											
1	05.05.2021	12:41hrs	05.05.2021	13:06hrs		-7.140	66kV LSA-Basochu	NA	NA NA	NA NA	NA NA	NA NA	Grid fail from Basochu Plant(machine tripped)
- 2	26.05.2021	00:15hrs	26.05.2021	01:21hrs	1	0.000	66kV Basochu- LSA	NA	Grid fail	NA.	Basochu	black out	66kV LSA-Dochala feeder tripped at 00:15hrs with out any relay & breaker is opreated at
3	10.05.2021	11:45les 16:09les	10.05.2021	13:40hrs 17:05hrs	0	0.000	66kV LSA-Dochula 66kV LSA-Dochula	NA NA	Cable problem at Cable problem at	OC/EF relay operated OC/EF relay operated	Dochula end Dochula end	NA NA	66kV LSA -Dochala feeder tripped on OC/EF relay operated, opening breaker at our end. 66kV LSA -Dochala feeder tripped on Dist & OC/EF relay operated, opening breaker at
5	22.05.2021	11:15hrs	22.05.2021	17:05tms 11:57hms	0	14.230	66kV LSA-Dochula	NA NA	NA NA	86 relay operated	NA NA	NA NA	66kV LSA-Dochula feeder tripped on Dist.8. OC/EF relay operated, opening breaser at 66kV LSA-Dochula feeder tripped of 11:15hrs operating breaker open at our end at that
- 6	26.05.2021	00:15hrs	26.05.2021	01:21hrs	1	0.000	66kV LSA-Dochula	NA NA	Grid fail	NA NA	Basoclau	black out	66kV LSA-Dockula feeder tripped at 00:15krs with out any relay & breaker is optrated at
7	27.05.2021	08:36hrs	27.05.2021	23:23hra	14	20,050	66kV LSA-Dochula	NA.	Shutdown	NA NA	NA NA	NA NA	66kV LSA -Dochula-Semtokha taken shutdown as per approval
	(E) 66/33/11 kV		8110008088	20,2000		20000	SORT DOLL DOCUME	200	OHIMAD WA	.50	193	190	look a post approved a securioral sustain accompanies for approved
1	5/3/2021	13:35Hrs	5/3/2021	14:07Hrs	0	2.2	66kV Chrando Line in	Olathong all incoming and outgoing feeders	Tripped from chuida				Grid failure from clutchs
8	2 5/9/2021	13:35Hrs	5/9/2021	16:28Hrs	0	2	66kV Chumdo Line in	Olathong all incoming and outgoing feeders	Tripped from chrisha				
	(F) 66/33/11kV J	lemina Substation											
ī	03.05.2021	13:47	03,05.2021	14:30	0	-3.24	66 kV Changedaphu	-	Distance relay operated with auto reclose lock out.	Distance relay			CB II operation: 236, CB C operation: 239, Ia broken: 47.50 mA, Ib broken: 224.5 mA, Ic broken: 239.6 mA, CB operation: 652.6 ms. Ia: 44.16 A, Ib: 48.86 A, Ia: 40.63 A, Vax 23.1V, Vbm 25.38 IV, Vem 20.15 VV. Charged the feeder at 14.10 Hrs, upon communicating with BPSO Operator.
2.8	03.05.2021	14:07	03.05.2021	14:26	0	1.29	66 kV Chando	700	Distance relay operated with auto reclose lock out.	Distance relay			Jan 271.7 A., Br. 50.13 A., Im. 44.31 A., Van: 21.82 kV., Vba: 37.97 kV., Von: 37.34 kV. Charged the feeder at 14:20 Hrs. upon communicating with BPSO Operator.
3	09.05.2021	16:20	09.05.2021	19:17	2	1.89	66 kV Clando	Black out	Non directional EF operated & auto reclose lock out	IN1>2 trip			In 98.1.3 A. Br. 226.8 A. Iz. 144.8 A. Val. 21.56 EV, Vice 64.19 EV, Vor. 58.07 W. D7 measured for derived 61.6 9. A, View 20.51 EV, View 35.10 EV, Vor. 38.10 EV, For. 50.00 EH, upon communicating with BPSO Operator, the Substantion was supplied from Chandro of 1917 Her SI Changedopha and. Inc. 10 eA, It. 230.1 A, Ir. 140.6 A, Vol. 21.57 EV, Vier. 64.34 EV, Vor. 58.28 EV, IN measured
4	09.05.2021	16:20	09.05.2021	19:17	2	-3.42	66 kV Changedaphu	Black out	Non directional EF operated & auto reclose lock out	INI>2 trap			Inc. Lo &A, Tr. 239.1 A, Icr. 146.6 A, Valu. 21.57 LV, Vive: 64.34 kV, Vor. 38.28 kV, IN measured. 628.8 A, IN derived: 629.5 A, Van: 20.88 kV, Vlox. 35.69 kV, Vor. 38.51 kV, Fig. 50.08 Hz. upon communicating with BPSO Operator, the Substation was supplied from Chando in 19.17 Hrs till. Changedisplus end.

		V Dechencholing sub		10000000	0.000		ARVOUR						
1	03.05.2021	13:38hrs	03.05.2021	14:07hrs	0	-6.034	66KV I/C	000	Supply failed from source	SE .	19	Tr.	uli
2	08.05.2021	01:20Hrs	08:05:2021	01:29Hrs	0	0.125	66KV Gase O/O		Over current	0/C,& 85 A& B	Gasa end	tripped	Fdr tripped doe fault at Gaya end.
è	09.05.2021	16:22Hrs	09.05.2021	17:12hrs	0	-6.228	66KV I/C	57995	Supply failed from Sent	okhu -	9		
	15.05.2021	18:53hrs	15.05.2021	19:00hrs	0	+5.481	10MVA Tr1 & II	2001		50B & 50C.86		tripped	Transformer impped due to jerking of JSKV Thamphu Hydro fault.
	17:05:2021	11:43hru	17.05.2021	11:50hrs	.0	-1.225	do	-		86 relay		tripped	Transformer tripped on REF prote.
	01.05.2021	09:42 Hrs	01.05.2021	17:19Hrs	5 hrs	3.784	10MVA Tr-II	Nil			for fixing the 30MVA Transformer accessories b		
	01.05.2021	17:25Hes	01.05.2021	19:08Hrs	2 hrs	6.028	10MVA Tr-I	Nil			nservator Tank at new 30MVA Transformer by F	ydra machine	
	01.05.2021	18:15Hrs	01.05.2021	19:36Hrs	1 hrs	6.662	10MVA Tr-II	Nii			kha TPO for connecting conservator accessories.		
	03.05.2021	11:10 hrs	03.05.2021	17:44hrs	5 hrs	2.806	RIMVA Tr-II	Nil			g the filter Machine to switchyard by Hydra Mach		
	04.05.2021	11:10Hrs	04.05.2021	11,32 hrs	0	3,674	16MVA Tr-II	7011		took the shut down for	unloading snother filter machine at transformer y	and by the Hydra machine.	
	04.05.2021	11:35Hrs	04.05.2021	12:16Hrs	0	3,674	10MVA Tr-L	Nil	Same work		- Control of Control		
	04.05.2021	12:16Hrs	04.05.2021	18:02hrs	6lus	7,427	10MVA Tr-II	Nil	Shifting of Filter muchin				
	08.05.2021	12:15Hrs	08.65.2021	19:06Hrs	6lus	3,384	10MVA Tr-I	Nil			for fixing the 30MVA Transformer-I radiator(fin		
	12.05.2021	10:40Hm	12.05.2021	16:43hm	5hrs	3.077	10MVA Tr-II	Nil			for fixing the 30MVA-II Transformer-II HV bash	ing current transformer with help	of Hydra Machine.
5	13.05.2021	09:10hrs	13.05.2021	18:14hrs	9hrs	3.175	10MVA Tr-II	Nil	Intellation of bushing CT				
6	14.05.2021	09:15Hrs	14.05.2021	18:56Hrs	9hrs	2.923	RIMVA Tr-II	Nil	Shut down by PIO office	e to fixed the pipe line	of conservator tank to main transformer body.		
7	15.05.2021	09:36hrs	15.05.2021	10:55Hrs	0	3.043	16MVA Tr-II	Nii	For shifting the filter ma	chine from transformer	II location to near the transformer-I		
Ė	15,05,2021	11:10hru	15.05.2021	14:22Hm	3hru	2.496	10MVA Tr-1 & 2.5MVA Tr- 1	Nil			nade alignment of 33KV side Bus coupler. Isolato	r, space fdr line & bus isolator.	
9	15.05.2021	14:58hrs	15.05.2021	19:00hrs	3hrs	4.733	10MVA Tr-li	Nii	Shut down taken by Olal	ha project office to co	meet the pipe.		
0.	1T.05.2021	10:30Hrs	17.05.2021	15:18hrs	4lus	0.728	10MVA Tr-II	Nil			d adjustment of pipe on conservator timk.		
t	18.05.2021	10:45hrs	18.65.2021	18:26hrs	7lus	2.729	10MVA Tr-II	Nil			to for retrofitting new digital relay of 10MVA-II		
	19.03.2021	10:02hru	19.05.2021	14:09Hrs	4hrs	2,332	10MVA Tr-I	Nil	For shifting of CCTV fo				
13	19.05.2021	14:10Hrs	19.05.2021	19:50Hrs	5hrs	3.908	16MVA Tr-II	Nil			Tr-II by Smd mic semiokhs.		
4	20.05.2021	10:10Hrs	20.05.2021	19:29bs	9hrs	2,329	10MVA Tr-II	Nii	Continuation of replaces				
	21.05.2021	10:10hrs	21.05.2021	18:30hrs	Sturs	2,376	10MVA Tr-II	Nil	30MVA transformersII				
26	22.05.2021	10:40hrs	22.65.2021	18:19Hrs	7hrs	2.169	10MVA Tr-II	Nil			V side CT of 30MVA Transformer & installation	a of relay.	
17	24.05.2021	10:15hrs	24.05.2021	16:21hrs	6lus	1.85	10MVA Tr-II	Nil	For Testing 30MVA Tr-				
	24.05.2021	16:24hrs	24.05.2021	19:11Hrs	3hrs	3,928	10MVA Tr-I	Nil	For installation of Radia				
9	25.05.2021	09:55hrs	25.05.2021	20:23hrs	10hrs	2.11	10MVA Tr-II	Nii	For testing 30MVA Tr-I	& installation of Mete	r in control room		
10	26.05.2021	14:05hrs	26.05.2021	16:441im	2hrs	1.89	10MVA Tr-II	Nil	Continuation of testing	OMVA -Tr-II.			
11	27.05.2021	10:05hcs	27.05.2021	11:30Hrs	Thrs	2.269	10MVA Tr-II	Nil	For installation of HV &		Transformer-II		
	29.05.2021	12:12hrs	29.05.2021	14:22hrs	2hrs	0	20MVA Tr-II	Nil	For releasing the Air fre				
33	31.05.2021	11:17hrs	31.05.2021	15:45hrs	Ahrs	0	30MVA Tr-II	Nil	For testing 30MVA rela-				
34	31.05.2021	11:22Hrs	31.05,2021	17:40Hrs	6hrs	0	30MVA Tr-II	Nil	For testing 30MVA Tr L				
-	(H) 66/11kV H		777777777	***************************************	2000	7.0	7,0000000000000000000000000000000000000			accords (CC)			- 11
1	09.05.2021	16:21	69.05.2021	16:27	0	-1.96	66kV Incomer, along with all the feeders.	unknown	o.c	Source fid, Childra	66kV incomer tripped from the source on oversurrent. The same was compulsed further.		
2	29.05.2021	16:15	29.05.2021	16:20	0	-1.34	66kV Incomer, along with all the feeders.	unknown	oc	Panghesa substation, Par	50kV incomer tripped from Purgbess substation on overcurrent. The same was normalised further.		
-	an matarisas	station Semtokha											
7.7	Toronto	T. C. C. C.	1100000000000	1 10000000	1 3901	10000000	220kV Semtokha-Chokha	220kV Semtok	dia	BOULDSE KERY	open.		
1	22.05.2021	11:16hrs	22.05.2021	11:27hrs	1.00	-28.940	Line	Chukha Line	E TRIBUNIT LL-LS FO	sh Fault Loop=12-1. pool tose kelië		Trasicat	No customer affected
2	22.05.2021	11:27hrs	22.65.2621	12:17hrs	0.00	-28.940	220kV Semtokha-Chakha Line	Clmkba Line	e Trustent 1.2-1.3 Par		, Zone- 45.4km	Trasicut	No customer affected
3	25.05.2021	00:21hrs	25.05.2021	00:43hrs	0.00	16.490	220kV Semtokha-Chakha					4.00	
200	100000000000000000000000000000000000000	Serve and other		100000000000000000000000000000000000000			Line	Chukha Line Semtokhu ssa			1,150	Trasient	No customer affected
4	09.05.2021	16:23hts	09.05.2021	16:27hrs	0.00	15.730	50MVA-1		Childre Inc.			Trasteut	Whole Thimphii
5	09.05.2021	16:27hrs	09.05.2021	17:20hrs	0.00	15.730	50MVA-1	Seulotha St.	A Impped along with 0	olev Earth fault, HV	\$ LV	1000000	
			20000000000	9-2003-0-0	75/642	Owner	6246912436	Olakka sa Semtokha sa	a Imped wife they	Backus Protection Differential prote	Octó	Trasient	Whole Thimphu
6	11.05.2021	15:51lms	11.05.2021	15:55las	0,00	12.640	50MVA-1	Olakha ss	Compatible and	Optd.		Trasient	No customer affected
70	09.05.2021	16:23hrs	09.05.2021	16:28hrs	0.00	15.750	30M(VA-2	Seurtokha sa Olakha sa	Olskia Inc	6kv Earth fmilt, HV Backup Protectio		Trasient	Whole Thimplu
8	09.05.2021	16:28hrs	09.05.2021	17:15hrs	0.00	15.750	50MVA-2	Semtokha sa Olakha sa		6kv Earth findt, HV Backup Protectio		Trasient	Whole Thimplus
9	09.05.2021	16:23hrs	09.05.2021	17:16brs	0	1	66kV Semtokha-Olnkha 6.77 Line	Semtekhn sis Olakha ss		Directional	EF	Trasient	Whole Thimplu
	11.05.2021	15:51hrs	11.05.2021	15:56lus	0	1	65kV Semtokha-Olakha 1.83 Line	66kV Semtokha- Olakha Line	Dir. EF/OC	In-130A,Fb-4.04 Ic-111.2A	4kA,	Trasient	No customer affected
0		- (0.0400-m)	C1 C	1 2011/10/2015			Tribi Civina and a	PROPERTY OF THE PARTY OF THE PA		5 AT 15 AT 1		100 (000)	
	the ne tions	00:21hrs	25.05.2021	00:25hrs	0		1.21 10MVA-1	All 11kV Outgo:	77.55.0	OC/EF		Trassest	All 11kv Direct customers affected.
11	25.05.2021	00:21hrs	25.05.2021	00:26brs	0		1.21 10MVA-2	All 11kV Outgo	ing fo OC/EF	OC/EF		Trasicut	All 11kv Direct customers affected.
1	25.05.2021 25.05.2021		01.06.2021	00:43lms		9.560	Scottokha Substation				sectionalizer of 66kV bus		
11	25:05:2021			West Toward		35,0500	District Control of the Control of t	-			and the same of th		
11 12 13	25:05:2021 31:05:2021	23:44hrs	1 2000	DV305517									
11 12 13	25:05:2021		01.06.2021	05:26hrshrs	5,00	9.550	Semickha Substation	Shutdown taken	by Penna Letho to remove	droping conductor of	SECTIONALIZED OF BUILD THIS		
11 12 13	25:05:2021 31:05:2021	23:44hrs	1 2000	05:26hrshrs 00:48hrs	5,00	9.550	Semickha Substation Semickha Substation	-		Harris Control of the	sectionalizer of 66kV bus		
10 11 12 13 14	25.05.2021 21.05.2021 31.05.2021 31.05.2021	23:44hrs 23:44hrs 23:44hrs	01.06.2021 01.06.2021	00:48hrs	1.00	15,050	Semickha Substation	Shutdows taken	by Pema Letho to remove	droping conductor of	sectionalizer of 66kV bus		
11 12 13	25:05:2021 31:05:2021 31:05:2021	23:44hrs 23:44hrs	01.06.2021	100000000000000000000000000000000000000		302700000		Shutdown taken Shutdown taken	by Penna Letho to remove by Penna Letho to remove	droping conductor of droping conductor of	The same of the sa		

(J)	66/33/11kV Par	ngbesa substatio	DEL									
1	29.05.2021	16:15Hrs	29.05.2021	16:22Hrs	0.	2.2	66kV OG Haa feeder	Haa	0/0		Transient	
	(K) 66/33kV Ch	angidophu Substati	ion									
E	09.05.2021	16:23hrs	12.05:2021	17:38hrs	73	-1.92	66kV Oʻskha-Changidaphu Line	Olakha ss	Rph Condutor suspped and got contact with Yph conductor	Bobese ocar IT perk	Permanent	
2	14.05.2021	08:16hrs	14.05.2021	18:43hrs	10.00	-5.810	66kV Olakha-Changidaphu Line	Changidaphu and Olokha so	No Indication		Permanent	TMD carried out the maintenance work on the same line
3	09.05,2021	18:26hrs	12.05.2021	17:38hra	59.00	-1.920	66kV Olakha-Changidaphu Line	66kV Olakhu- Changi dapha Line	Shindown taken by TMD to rectify Rph conductor non II park Babesa			
4	13.05,2021	08:25hrs	13.05,2021	17:58hre	9.00	-1.920	66kV Otašha-Changidophu Line	66kV Olakha- Changi daphu Line	Annual Maintenance of the line by TMD.			
	14.05.2021	08:16hrs	14.05.2021	18:43hrs	10.00	5.810	66kV Olakha-Changidaphu Line	66kV Olaklus- Chongi dophu Line	Annual Maintenance of the line by TMD.			
6	17.05.2021	08:15hrs	17.05.2021	18:25lus	10.00		66kV Otaldra-Changidaphu Line	66kV Olakha- Changi dapho Line	Annual Maintenance of the line by TMD.	Near Jomina		
	(L) 66/33kV Dat	mji Substation										
1	03.05.2021	13.38hrc	03:05:2021	14.08hrs	0	-28	66/33ky Incoming line		Ontagés			Outsoes of 66ky line from Dling due to orid failure from the source.

## June 2021

SI No.	Date of Tripping	Time of outages	Date of Normalizatio n	Time of fault was cleared	Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
(A) 4	00/220/66/	11 kV Mai	base Substatio	n	VIII.			A STATE OF THE STA		M			
66kV	V & Above 01.06.2021	22:58	02.06.2021	1:42	1	21	50/63MVA Transformer I	Maibase s/s	Overcurrent	General trip, LBB trip, 86 optd, 51 trip.	66kV Pling line	Overcurrent fault	II.1=759.97A<-1.97 deg, II.2=750.2A<-124.4deg, II.3=733.06A<- 11.67 deg.II.4=22.13A<-127.06deg. Note: Due to permanent fault in pling line, Feeders connected to the same bus of it could not withstand while test charged. After knowing the fault and isolating pling line only we could charged rest of the feeders.
2	01.06.2021	22:58	02.06.2021	1:45	1	21	66kV Pasakha feeder I	Malbase S/S	Overcurrent	50trip,86 optd,General trip.	66kV Pling line		ll.1=991.76A<-8.95.deg, ll.2=1324A<-134deg, ll.3=1164A<115.41deg,ll.4=455.4A<5.36deg,
3	01.06.2021	22:58	02.06.2021	14:58	15		66kV Bus Coupler	Malbase S/S	Earth fault		66kV Pling line	0/C&E/F	IL1=7691.81A<-84.3 deg, IL2=340.5A<115.9deg, IL3=138.67A<91.54deg, IL4=7437.5A<-84.27deg.
4	05.06.2021	20:37	05.06.2021	20:42	0	81	200MVA ICT	Malbase S/S	Earth fault	67/67N optd and 86 optd.		O/C&E/F	G2 PHASE A[FWD] 
5	05.06.2021	20:37	05.06,2021	20:45	0	21	50/63MVA Trasformer III	Malbase S/S		OLTC-BUCH trip			IL1=29.1A<99.23 deg, IL2=69.09A<-176.39deg, IL3=121.24A<126.15deg,IL4=189.78A<139.84deg.
6	06,06.2021	23:20	06.06.2021	23:29	0	20	50/63MVA Trasformer I	Malbase S/S	Overcurrent	LBB trip, General trip,86 B otpd	66kV Pling line	Overcurrent fault	IL1=768A<-3.29 deg, IL2=694.51A<133.45deg, IL3=392A<137.94deg,IL4=614A<117.75deg,
7	06.06.2021	23:20	06.06.2021	23:31	0	20	66 kV Pasakha Feeder I	Malhase S/S	Overcurrent	General trip,IOC 50trip, 86 trip	66kV Pling line	Overcurrent fault	II.1=549A<10.19deg, II.2=175.3A<139.15deg, II.3=209.96A<138.42deg,II.4=171.57A<-1302deg
8	06.06.2021	23:20	06.06.2021	23:26	0	8	220kV Bus Coupler	Malbase S/S	Overcurrent	SPAJ 140C relay optd. I> trip,	66kV Pling line	Common and the second second	Bus coupler tripped due to jerk from 66kV side.
9	06.06.2021	23:20	06.06.2021	23:30	0	*	66kV Bus Coupler	Malbase S/S	E/F	IOC trip, General trip, IEF 50N trip.	66kV Pling line	& E/F	IL1=7695.44A<-23.75deg, IL2=290.58A<-17.36deg, IL3=68.15A<-33.41deg,IL4=7695A<-23.75deg.
10	12.06.2021	9:19	12.06.2021	9:24	0	24	66 kV Pasakha Feeder IV	Malbase S/S	E/F	General trip, IEF 50N trip.86 optd.	66kV Pasakha IV line	E/F	IL1=2427.31A<-45.63deg, IL2=271.05A<-76.9deg, IL3=166.6A<90.27deg,IL4=2538.37A<133.82deg.
11	12.06.2021	9:19	12.06.2021	9:24	0	24	66 kV Pasakha Feeder II	Malbase S/S	Overcurrent	General trip, IEF 50N trip.86 optd.	66kV Pasakha II line	Overcurrent fault	IL1=0.27A<40.72deg, IL2=1233.14A<35.39deg, IL3=768.98A<56.88deg.
12	12.06.2021	9:19	12.06.2021	9:24	0	25	66 kV Pasakha Feeder IV	Malbase S/S	Overcurrent	General trip, IEF 50N trip.86 optd., IOC 50-trip.	66kV Pasakha IV line	Overcurrent fault	II.1=1111.43A<-51.27deg, II.2=401.95A<166.54deg, II.3=579.73A<120.4deg.
13	19.06.2021	21:18	19.06,2021	21:25	0	23	66 kV Pasakha Feeder I	Mslbase S/S	E/F	General trip, IEF 50N trip.86 optd.	66 kV Pasakha Feeder I line	E/F	IL1=2592.08A<-47.93deg, IL2=299.68A<-94.45deg, IL3=151.74A<127.77deg,IL4=2651.87A<127.7deg.
14	19.06.2021	21:18	19.06.2021	21:25	0	23	66 kV Pasakha Feeder II	Malbase S/S	Overcurrent	General trip, IEF 50N trip 86 optd.	66 kV Pasakha Feeder II line	Overcurrent fault	II.1=0.32A<-140.89deg, II.2=1299.73A<-147.96deg, II.3=848.99A<-131.43deg.
15	19.06.2021	21:18	19.06.2021	21:25	0	24	66 kV Pasakha Feeder IV	Malbase S/S	Overcurrent	General trip, IEF 50N trip.86 optd.	66kV Pasakha IV line	Overcurrent fault	lL1=911.17A<-31.23deg, lL2=304.4A<146.04deg, lL3=615.55A<104.45deg.
16	19.06.2021	21/18	19.06.2021	21:25	0		66kV Bus Coupler	Malbase S/S	E/F	General trip.		E/F	IL1=1437.31A<-46.94deg, IL2=467.77A<-33.38deg, IL3=330.93A<-66.28deg,IL4=2226.45A<-31.4deg
17	22.06.2021	20:30	22.06.2021	20:39	0	78	200MVA ICT	Malbase S/S	Overcurrent	67/67N optd and 86 optd.	•	(0.0)	PHASE A[FWD] <ls>IDMTL IA=1190A, PHASE B [FWD] IB= 166.1A, PHASE C[FWD]<ls>IC=1418A, E/F [FWD] IDMTL IE=923.4A.</ls></ls>
18	22.06.2021	20:30	22.06.2021	20:43	0	27	50/63MVA Transformer III	Malbase S/S	2	Diff. trip		- F	IL1=21A<171.66deg, IL2=121.64A<133.03deg, IL3=59.47A<- 175.64deg,IL4=186.2A<-150.48deg.
19	22.06.2021	20:30	22.06.2021	20:53	0	51	220kV Birpara Feeder	Malbase S/S & Birpara line	Overcurrent	Zone 1 trip, 86 OPTD.	18.77 kM	Overcurrent fault	ll.1=4.613kA, IB=379.7A, IC =5.197kA
(B)22	20/66/11 kV Si					V /		122		4		NA.	
2	05.06.2021 12.06.2021	9:19	05.06.2021 12.06.2021	9:20	0		220kV Samtse feeder 66kV Bhutan Concast & Druk cement Feeder	GIS, Singhigoan s/s GIS, Singhigoan s/s	E/F Overcurrent	O/C trip, 86 trip.  General trip, O/C trip, IE>> trip, L>> Directional trip,IEP Directional Trip.	Samtse line	E/F Overcurrent Fault	IL.1=5.06 A, II.2=64.75A, II.3=83.95A, I4=4866A II.1=5.24kA, II.2=0.42kA, II.3=0.22kA
3	19.06.2021	21:18	19.06,2021	21:27	0	1	66kV Bhutan Concast & Druk cement Feeder	GIS, Singhigoan s/s	Overcurrent	1>>D irectional trip, General trip	1340	Overcurrent Fault	II.1=5.28kA, II.2=0.42kA, II.3=0.28kA

/B) 46	MANUEL TO DE.	tobThe	C. bedeller										
(B)66	/33/11 kV Phu	intsnotin	goubstation					ří –		1			At 09:00hrs issued shutdown to Jigme Gyaleg, Sr.Engineer,TMD Pling with work.
1			04.06.2021	9:00	9	idle	66kV Malbase-Pling feeder	66kV Malbase-Pling feeder					permit no 522 for re-string snapped conductor between location PS-3 & PS-4. After completion of works at 18:30hrs CB closed from Malbase end and 66kV Malbase-Pling feeder kept under idle position.
2			05.06.2021	11:27	11	idle	66kV Malhase-Pling feeder	66kV Malbase-Pling feeder					At 11:27hrs charged 66kV Pling-Malbase feeder which was under idle condition with charging code 1035 as per instruction from BPSO (for supply reliability at Pling Se), since 66kV Chukha-Pling feeder taken shutdown by Gedu substation for rectification of isolators at Gedu substation. At 13:45hrs: opened CB of .66kV Pling-Malbase feeder after getting clearance from BPSO with opening code 0008 and again the feeder was kept under idle condition.
			08.06.2021	10:00			66kV Malbase-Pling feeder	66kV Malbase-Pling feeder			Líne		66kV Malbase-Pling feeder test charged with charging code 1070 for checking th healthiness of line as per instruction from BPSO. At 10:39hrs opened CB of said feeder as per instruction from BPSO with opening code 0017.
##			20.06.2021	17:37	17	idle	66kV Malbase-Pling feeder	66kV Malbase-Pling feeder			Line		66kV Malbase-Pling feeder test charged with charging code 1753 from from BPSO, since there was shutdown on 66kV Chukha-Pling feeder. At 18:44hrs opened CB of said feeder as per instruction from BPSO with opening code 0075.
22	30.06.2021	2:06	30.06.2021	12:08	10	0.98	66kV Pling-Gomtu feeder	66kV Pling-Gomtu feeder		DSTN OPTD, 186&86	Gomtu substation		66kV Pling-Gomtu feeder tripped at our end and 66kV Chukha-Pling feeder got tripped at their end causing blacknut at Pling, At 02-09hrs supply was extended from Malbas substation after informing to BPSO. At 02-25hrs 66kV Chukha-Plin, feeder normalised from chukha end. 66kV Pling-Gomtu fdr taken shutdown by Gomtu substation since jumper conductor got snapped at Gomtu se end. After completion rectification works at Gomtu at 12-08hrs 66kV Pling-Gomtu feeder normalised with charging code 1283 from Gomtu substation. Opened CB of 66kV Malbase-Pling with opening code 0106 from BPSO and feeder was kept under idle charged.
(D) 6	6/33/11 kV Ge	edu Subs	tation										
1	03.06.2021	13:29	03.06.2021	13:32	0	0.17	66/33/11kV 5MVA Tr III	33kV Gurungdara-II	12401240071001	REF	Substation		Charged the Transformer after Isolating the out going feeder. 33kV Gurungdara feeder- was charged from 33kV Gurungdara feeder-I.
2	04.06.2021	9:35	20.06.2021	22:00	12	0.13	66/33/11kV 5MVA Tr III	Nil	Isolator alignment problem and oil filtration		Substation	Shutdown	Work permit No. 71 issued to Mrs. Rinchen Zangmo, Sr. Engineer of SMD Pling to carry out HV isolator alignment problem and to perform oil filtration.
3.	05.06.2021	11:36	05.06.2021	13:50	2	0.18	66/33/11kV 5MVA Tr III	Nil	Isolator alignment problem		Substation	Shutdown	Work permit No. 72 issued to Mrs. Rinchen Zangmo, Sr. Engineer of SMD Pling to entry out HV isolator alignment problem on 5MVA 66/33kV transformer-III.
4	07.06.2021	18:10	07.06.2021	20:33	2	1.16	66kV Chukha -Pling Line	Black out	Rectificatin of isolator alignment.		Substation		For rectification of SMVA transformer-III HV side isolator alignment.
5	08.06.2021	12:17	08.06.2021	12:33	0	1.58	66kV Chukha -Pling Line	Black out	Rectificatin of isolator alignment.		Substation		For rectification of SMVA transformer-III HV side isolator alignment.
6	17.06.2021	12:52	23.06.2021	11:30	372	1.6	5MVA 66/11kV Tr-II	Nil	Oil filtration		Substation	Shutdown	Work permit No. 76 issued to Mrs. Rinchen Zangmo Sr. Engineer of SMD Pling for transformer oil filtration.
7	20.06,2021	18:08	20.06.2021	18:40	0	1.48	66kV Chukha - Pling Line	Black out	Rectificatin of isolator alignment.		Substation		For rectification of 5MVA transformer-III HV side isolator alignment.
8	21.06.2021	12:27	26.06,2021	14:35	122	0.34	8MVA 66/33kV Tr	Nil	Oil filtration		Substation	Shutdown	Work permit No. 77 issued to Mrs. Rinchen Zangmo Sr. Engineer of SMD Pling for transformer oil filtration.
9	23.06.2021	11:17	27.06.2021	16:57	101	0.79	5MVA 66/11kV Tr-I	Nil	Oil filtration		Substation	Shutdown	Work permit No. 78 issued to Mrs. Rinchen Zangmo Sr. Engineer of SMD Pling for transformer oil filtration.
10	26.06.2021 30.06.2021	14:30 2:06	27.06.2021 30.06.2021	11:58 2:10	21.	0.43	66/33/11kV 5MVA Tr III 66kV Chukha -Pling Line	Nil Black out	Oil filtration		Substation	Shutdown	Work permit No 79 issued to. Mrs Rinchen Zangmo, Sr Engineer for oil filtration on Ot.TC.  Supply charged from Phuntsholing end.
CONTRACTOR OF THE PARTY OF THE	5/33/11 kV Go			4.490	- *	State:		Editor State			******		The state of the s
1	30.06.2021	2:06	30.06.2021	02:41	0	-0.301	Dhamdum	Whole Gomtu	NA.	NA NA	Gomtu Sub Station		Supply failed from Dhamdum Sub Station.
2	30.06.2021	2:06	30.06.2021	12:08	10	0.24	Gomtu-P/Ling	Nil	Over Current	IDMTL Over Current 51AX,51BX,51CX	Gomtu Sub Station		Y phase conductor between Wave trap and Line isolator burned to dead.
	20/66/33 kV D	hamdur	Substation							n concentrations		111	
220k	05.06.2021	20:37	05.06.2021	20:46	0	-6.74	220 kV Singyegoan	N/A	Transient fault	REL670:General trip,Zone- 1, R Ph	N/A	N/A	220kV singyegoan feeder tripped from both the end and charge at 20.46hrs as per the clearance given by BPSO, T/phu. Dist. Showing:19.56km and 48.90% and C/B Closed from Malbase end at 21:07 hrs.
2	30.06.2021	2:06	30.06.2021	2:41	0	0.25	66kV Gomtu feeder	Gomtu	Transient fault	REF615=DIR.O/C 67 Trip. R,Y,B Ph fault.	N/A	N/A	66kV Gomtu Feeder feeder tripped at both the ends at 02:06hrs and charged at 02:41 hrs as per the charging code No 1280 by Phub Zangmo, BPSO Thimphu.

# **July 2021**

Sl No.	100000000000000000000000000000000000000		Date of Normaliz ation	Time of fault was cleared	Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	
	0/220/66/1	11 kV Mal	base Substa	tion									
66kV 8	Above						T 120000					10	1
1	24.07.202	18:28	24.07.202	21:40	3	22	50 MVA Transformer III.	Malbase 5/5		86, RET 670	fault on 66kV multicircuit Line.	Overcur	11=469.31A, 12=58.87A, 13=92.28A, 14=389.75A
2	24.07.202 1	18:28	24.07.202 1	18:42	0	40	200MVA ICT	Malbase S/S	Inter Tripped as 400kV	67/67N,86	fault on 66kV multicircuit Line.	Overcur rent fault	l1=1029A, I2=184.573A, I3=400A, I4=576.68A
3	24.07.202	18:28	30.07.202 1	12:46	138	20	66 kV Pasakha fdr	Malbase S/S	snapped and touched on the 66kV Multicircuit feeder going towards Industerial	86,operated. IOC-50- trip, IEF-50N-TRIP	fault on 66kV multicircuit Line.	Overcur rent fault	11=6075A, [2=322.2A, 13=124.71A,I4=137.63.
4	24.07.202	18:28	30.07.202 1	12:46	138	20	66 kV Pasakha fdr II	Malbase S/S	State	86 operated, IOC-50- trip, IEF-50N-TRIP	fault on 66kV multicircuit Line.	Overcur rent fault	l1=0.16A, l2=454.65A, l3=166.34A,
5	24.07.202 1	18:28	30.07.202 1	12:45	138	20	66 kV Pasakha fdr IV	Malbase S/S		86 operated. General trip IEP directional trip	fault on 66kV multicircuit Line.	Overcur rent fault	11=1048.38A, 12=239.34A, 13=511.47A,
(B)66/3	3/11 kV Ph	untsholin	g Substatio	n									
1	24.07.202 1	15:30	24.07.202 1	18:54	3	0.75	66kV Pling-Gomtu feeder	66kV Pling-Gomtu feeder		DSTN OPTD, 186&86 fault imp- 14.3, fault angle-27, fault current-2.07A, fault location-49.0	Line		66kV Pling-Gomtu feeder tripped at our end. At 18:36hrs te- charged after getting clerance from BPSO but got tripped on same fault. Informed to BPSO. At 18:54hrs charged after getting clearance from BPSO after opening CB from Gomtu end and stood normal.
(E) 66/	33/11 kV G	omtu Sul	station						9				-
1	24.07.202	18:30	24.07.202 1	18:55	0	-0.81	66kV Gomtu- P/ling	Whole Gomtu	Grid failed	Distance and over current	Malbase		Distance relay and over current relay optd. at P/ling Substation.
2	24.07.202	18:30	24.07.202 1	18:59	0	-3.765	66kV Dhamhum	Whole Gomtu	Grid failed	NA NA	Malbase		Charged after the given instruction from BPSO.
(F) 220	/66/33 kV D	Dhamdum	Substation	i i									
220kV											ž.		
1	24.07.202	18:30	24.07.202 1	19:05	0	-7.33	220kV Malbase	220KVMalbase	Line fault	NA NA	Malbase	N/A	Dhamdum feeder got tripped from Malbase substation. We were informed that the Conductor has snap and fallen on the
2	24.07.202 1	18:30	24.07.202 1	19:05	0	-0.6	220kV Singeygoan	220KVSingeygoan	Line fault	NA NA	Singeygoan		Multicircuit at Malbase substation causing tripping of 220 kV (bus coupler and ICT). After isolating the fault, line was the result of 2.05 pm from Malbase substation.
3	24.07.202	18:30	24.07.202 1	18:56	(0)	3.95	66 kV Gomtu	66 kV Gomtu	Line fault	NA II	Gomtu	N/A	Since 220 kV { Malbase and Singeygoan } feeder was tripped from Malbase end, there was power interruption from 66 kl Dhamdum to Gomtu. 66 kV Pling Gomtu ring system could not be charged from Pling SS. At 18.56 Hrs Pling -gomtu and GomtuDamdum charged. No tripping of CB was encountered in Dahmdum substation.

	(C) 66/33kV	V Olakha S	ubstation										ř
1	7/7/2021	9:08	7/7/2021	9:10	0	7.8	66/33kV 20MVA Transformer I	All the out going feeders was effected as both the 20 MVA I & II transformer was tripped.	Due to tripping of 33kV Chubachu feeder (Fdr.IV)	TRAFO DIFFL. PROTN. RELAY 87.Indication: 1,3,4 & 5, 1, General Trip ,3.Diff Trip Yph.4.Diff Trip Bph.5.Diff Prot.Optd.Trip Relay 86.	Olakha	Transient Fault	The 66/33kV 20MVA Transformer I was tripped due to tripping of 33kV O/G feeder IV (Chubachu).Charged the feeder and hold normal.
2	7/7/2021	9:08	7/7/2021	9:10		7.7	66/33kV 20MVA Transformer II	All the out going feeders was effected as both the 20 MVA I & II transformer was tripped.	Due to tripping of 33kV Chubachu feeder IV, the transformer got tripped	DIR. Over current and Earth fault Protection relay 86 Indication: 1 & 5 1 General Trip & 5 O/C & E/F operated.	Line Segments		The 66/33kV 20MVA Transformer II was tripped due to tripping of 33kV O/G Chubachu feeder IV.
3	7/9/2021	14:10	7/9/2021	14:11	0	7.0	66/33kV 20MVA Transformer I	The supply was not effected as the	Temporary Fault	TRAFO DIFFL. PROTN. RELAY 87.Indication: 1,3,4 & 5, 1. General Trip ,3.Diff Trip Yph.4.Diff Trip Bph.5.Diff Prot.Optd.Trip Relay 86.	Olakha	Transient Fault	Reset the relays, charged the Transformer I and hold normal.
4	7/12/2021	8:46	7/12/2021	13:27	4	7.7	66/33kV 20MVA Transformer I	Only 33KV DPH II Feeders VI was effected as the feeders was fed from 66/33kV 20MVA Transformer II	The transformer was tripped due to tripping of 33kV DPH II feeders VI	TRAFO DIFFL. PROTN, RELAY 87. Indication: 1,3,4 & 5, 1. General Trip ,3.Diff Trip Yph.4.Diff Trip Bph.5.Diff Prot.	33KV DPH II Feeders VI line	Transient Fault	The transformer was tripped on differential. Issued the work permit no 1059 to Sr. Engineer SMD and TCCD Sherub Dorji for checking the relay coordination between Transformer and outgoing feeders. Charged the feeder after checking relays and hold normal.
5	7/16/2021	7:02	7/16/2021	13:07	6	6.5	66/33kV 20MVA Transformer I	Only 33KV Chubachu feeders IV was effected as the feeders was fed from 66/33kV 20MVA Transformer II	The transformer was tripped due to tripping of Chubachu feeders IV	TRAFO DIFFL. PROTN. RELAY 87.Indication: 1,3,4 & 5, 1, General Trip ,3.Diff Trip Yph. 4.Diff Trip Bph. 5.Diff Prot.	33KV Chubachu Feeders IV line	Transient Fault	The transformer was tripped on differential. Issued the work permit no 1060 to Engineer SMD and TCCD Sherub Dorji for checking the relay coordination between Transformer and outgoing feeders. Charged the 20MVA Transformer I after checking relays setting and hold normal.
7	7/19/2021	20:45	7/19/2021	20:48		10.2	66/33kV 20MVA Transformer II	All the out going feeders was	O/C & E/F	DIR.Over current and Earth fault portin relay 67 indication: 5 O/C &E/F operated.	Line Segments		The 66/33kV 20MVA,Transformer II was tripped and test charged the feeder and hold normal.
10	7/28/2021	18:54	7/28/2021	19:22	0	7.3	66/33kV 20MVA Transformer I	The supply was not effected as the feeders was fed from 66/33kV 20MVA Transformer II	Transformer Differential Protection relay Operated	TRAFO DIFFL. PROTN. RELAY 87.Indication : 1.4 & 5. 1. General Trip .4.Diff Trip Bph.5.Diff Prot.	Olakha	Tempora ry	20MVA Transformer I tripped on differential protection, informed to maintenance engineers for test charging of the Transformer. Charged the transformer after confirmation received and hold normal.
11	7/28/2021	19:06	7/28/2021	19:10		20.3	66/33kV 20MVA Transformer II	All the out going feeders was	O/C & E/F	DIR, Over current and Earth fault portn relay 67 indication: 1,2,5 O/C &E/F operated.	Olakha Substation	Over load	Due to overload, transformer II was tripped as Transformer I and 33KV Incomer I was in trip position due to differential protection indication.
	(I) 220kV S	ubstation !						4	<del>1</del>	y. y.			
1	21.07,202	15:50hrs	21.07.202	15:55hrs		31.030	50MVA-II	Semtokha SS	Over Current	RET316 relay optd.		Transient	
2	21.07.202	16:35hrs	21.07.202	16:46hrs		0.130	66kV Semtokha- Dochula Line	SCADA data valida	tion at both Semtokha and BPSO	end.		Torontone	No customer affected

# August 2021

SI No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
	/220/66/11	kV Malbase 5	ubstation										
66kV &	Above						400kV Tala -		- 12 - 00 - V	4.0 4.00			
1	17.08.2021	1:16	17.08.2021	1:34	0	418	Malbase fdr.	Malbase S/S	tripped due to OC on Y phase at Tala end.	A-B start, A/R L/out	line fault	Overcurrent fault	No fault displayed, 86 did not operate but both Main and Tie breaker open/tripped.
2	17.08.2021	3:40	17.08.2021	3:56	0	-133	220kV Chukha feeder	Malbase S/S	tripped due to OC on B phase .	Dist.trip, Zone1,AR location shot.	Distance=10.23km	Overcurrent fault	IL1=268.6A, IL2=551.5A, IL3=5.417KA
3	17. 8.2021	3:40	17.08.2021	4:20	0	24	50 MVA Transformer no III.	Malbase S/S	Tripped due to chukha feeder.	86,operated, Diff. Trip.	Switch Yard	tripped	IL1=9145A<-48.45dog, IL2=151.5A<-109.62dog, IL3=74.87A<-115.61dog, IL4=279.28A<-94.61dog.
4	25.08.2021	1:21	25.08.2021	14:00	12	73	200 MVA ICT	Malbase S/S	Buchholz trip	86,B phase BUCHH trip	transformer yard	tripped	IL1=0.121A<-50.21deg   IL2=0.032A<-155.6 deg   IL3=.007A<-48.2deg,
5	25.08.2021	9:30	25.06.2021	13:15	3	73	Z00 MVA ICT(R Y B) phase	Malbase S/S	Shutdown	~	34	Shutdown	PTW no.51 was issued to Mr. Parsu Ram Mishra, SMG pling, for rectification of Bucchholz trip.
B)220/6	6/I1 kV Sing	higoan Subs	ation										
1	19.08.2021	14:44	20.08.2021	20:00	29	0.074	11kV Feeder I	GIS, Singhigoan s/s	Overcurrent on R, Y phase	Ip trip, O/C trip, 1>> Trip, General trip,	Pole washed away by flood at Gurungdara.( 2 span conductor damaged)	tripped	IL1-8.73kA, IL2-8.32kA, IL3-0.01kA
B)66/33	VII kV Phunt	tsholing Sub	station										
1	06.08.2021	14:35	06.08.2021	15:02	0	0.16	66kV Pling- Gomtu feeder	66kV Pling-Gomtu feeder		DSTN OPTD, 186&86	Line	Tripped on Fault	66kV Pling-Gomtu feeder tripped at our end and 66kV Chukha-Pling from their end causing black out. At 14:59hrs 66kV Chukha-Pling feeder normalised from chukha ond and at 15:02hrs test charged after getting derance from BFSO and stood normal.
2			06.08.2022	14:40	14	idle	66kV Malbase- Pling feeder	66kV Malbase-Pling feeder					At 14:40 hrs charged 66kV Malbase-Pling feeder after getting approval from BPSO with charging code 14.4 which was under idle charged condition. At 15:02 hrs opened CB of 66kV Malbase-Plin feeder with opening code 0.193 from BPSO after normalising 66kV Chukha-Pling and 66kV Pling-Gontu feeder.
3			06.08.2022	21:35	21	idle	66kV Malbase- Pling feeder	66kV Malbase-Pling feeder					At 21:35 hrs charged 66kV Malbase-Pling feeder with charging code 1418 from BPSO which was under tille charged condition, since at Comtu end B phase conductor got snapped. At 15:02 hrs opened CB of 66kV Malbase-Pling feeder with opening code 0193 from BPSO after normalising 66kV Chukha-Pling and 66kV Pline-Comtu feeder.
4	07.08.2021	11:03			#NUM!	0.75	66kV Malbase- Pling feeder	66kV Malbase-Pling feeder					At 11:03hrs opened CB of 66kV Malbase-Pling feeder with opening code 0197 from BPSO and feeder kept under idle condition.
D) 66/3	3/11 kV Gedi	u Substation											
1	06.08.2021	14:37	06.08.2021	14:40	.0	1.29	66kV Chukha- Phuntsholing line.	Black out	Bad weather		Line segment		Charged from Chukha end.
E) 66/3	VII kV Gom	tu Substatio	n										
1	06.08.2021	14:38	06.08.2021	14:59	0	0.42	66kV Dhamdum/P/li ng	Gumtu	Grid Fail	Nil	Line Segment		Both Supply failed from Dhamdum and Phuentsholing
2	06.08.2021	21:24	07.08.2021	10:56	13	0.42	66kV P/Ling	Nil	B Phase conductor snapped	Nil	Gomtu Substation		Hand tripped the breaker against shutdown Code No. 0194 and charged against charging Code No. 1420
F) 220/4	66/33 kV Dh	amdum Subs	lation.										
1	06.08.2021	14:38	06.08.2021	14:54	0	6.71	66kV Gomtu	Gomtu	Transient fault	REF615=DIR.0/C(6 7) TRIP:R,Y,B Ø fault	Gomtu line	N/A	Relay indication: (67-Direction over curent/Earth fault relay) IL1 = 1.7 kA, IL2 = 1.5 kA, IL3 1.7 k, , (3 phase fault). Since weather condition was bad, BPSO has informed us to charge the line.

										SMD Semtokha			
		Tripping Reg	ort for the month of		021								
No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
	66kV LSA	Bockula feed	or			1							
ě	07,08.2021	15:47hrs	07.08.2021	15:55hrs	0	17,460	6kV LSA-Dochul	NA .	line fault	OC& EF with 86 relay	NA NA	NA	66kV LSA -Dochula feeder tripped at 15:47hs operating breaker at our end & Dochula end and informed to BPSO, at 15:55hrs with the charging code 1422 breaker towards closed towards Dochula and line stand thereafer.
	11.08.2021	01:27hrs	11.08.2021	01:35hes	0	19.170	6kV LSA-Dochul	NA .	line fault	OC& EF with 86 relay	NA NA	NA.	66EV LSA -Dochula feeder tripped at 01:27hrs operating breaker at our end & Dochula end and informed to BPSO, at 01:35hrs the -breaker towards closed towards Dochula and Basochu and line stand thereafter.
3	11.08.2021	01:43hrs	11.08.2023	03:57hrs	2	22,150	6kV LSA-Dochul	NA	line fault	NA	NA	NA	66kV LSA -Dochula feeder tripped at 01:43hrs without any relay or breakers operated at our end and at 03:57AM supply resumed from Basochu.
Ę	16.08.2021	03:40hrs	16.08.2021	04:10hrs	0	19,240	6kV LSA-Dochul	NA	line fault	OC& EF relay with 86 relay	NA NA	NA	66kV LSA -Dochula feeder tripped at 03:40krs due to under voltage at Dochula and closed the breaker with the closing code from BPSO at 04:10krs and line stand thereafter.
	66kV LSA -	Gewathang-I	Basochu feeder				Car Lori Domini		Table Man	oo reny	-112		Williams deposing desire treat per of the first office and time desired inter-content.
	11.08.2021	01:27hrs	11.08.2021	01:35hrs	0	19.170	6kV LSA-Basoch	NA .	line fault	OC& EF with 86 relay	NA	NA	66kV LSA -Baoschu feeder tripped at 91:27hrs operating breaker at our end & Basochu end and informed to BPSO, at 01:35hrs the breaker towards closed towards Basochu and line stand thereafter.
2	11.08.2021	01:43hrs	11,08.2021	03:57hrs	2	22,150	6kV LSA-Basoch	NA	line fault	NA	NA	NA	66kV LSA -Basochu feeder tripped at 01:43hrs without any relay or breakers operated at our end and at 03:57AM supply resumed from Basochu.
	(H) 66/11kV	Han Substat	ion										N022
î	08.08.2021	4:03	08.08.2021	6:22	2hrs	-0.5	All the feeders	due to Danntheng feeder	EF & O'C	Yangto, Han	Incomer tripped along with all the outgoing feeders dure to the fault on the Dranthing feeders. Incomer supply test charged from Pinaghete and with the olosing code 1427 from BPSO but finited to stand, so, effer isolating the faulty feeder (Dranthing), oblev lineomer was once again test charged vide clossing code 1420 and it was found nemed. The faulty feeder was kept isolated as to carry out line particularly by ESD, Hatting by ESD, Hatting by ESD, Hatting by ESD, Hatting		
	(I) 220kV S	ubstation Sem	tokha										
Ε	11.08.2021	01:28hrs	11.08.2021	01:46hrs		-45.770	220kV Semtokha- Rurichu Line	220kV Semtokha- Rucichu Line	Over Voltage	Main-1 Dist. Optd, Over Voltage trip		Temporary	
2	10.08.2021	10:16hrs	10.08.2021	10:19hrs		36,870	220/66kV 50/63MVA-2	Secutokha and Dochula Substation	Over Current (Tripped while opening Decimia to lobesa line)	Over Current and Inst. Over current Optd.		Temporary	
3	11.08.2021	03:50hrs	11.08.2021	03:51hrs		37.820	220/66kV 50/63MVA-2	Semtokha and Dochula Substation	Over Current (Tripped while opening Dochula to lobesa line)	Over Current and Inst. Over current Optd.		Тепіросагу	
1	11.08.2021	01:29hrs	11.08.2021	01:37hrs		33.670	66kV Senatokha- Dochula Line	Seintokha and Dochula Substation	Broken Conductor	Dist. Relay Optd., Broken conductor trip		Тетросату	
5	10,08.2021	10:17hrs	10.08.2021	11:54hrs	1.00	1.730	66/11kV 10MVA_2	Semtokha Substation	Hand trip to extend station s	uppy form 10MVA+1			
i	31,08.2021	08:59tas	31.08.2021	12:50hrs	4.00	42.060	66kV Semtokha- Dochula line	66kV Dochula Substation	Shatdown taken by Mr. Kinley Wangchak, Project Manager to make jumper connection on tower location 31 and jumper opening at tower 32			Trasient	No customer affected
)66/		angbesa sut							on the second control			Down Call	1 15-57 (1552) (1553) (1553) (1553)
t	07.08.2021	15:12	07.08.2021	15:14	0	0.99	66kV OG-Haa		Tripped on O/C	Distance Relay		Transient	
2	08.08.2021	4:02	08.08.2021	6:23	2	0.53	66kV OG-Haa		Tripped on O/C & E/F	Distance Relay		Long	Despit Test charging in coordination with BPSO, the line couldnot stand. Lastly it was found out that Has end one of 11kV fift had a problem where 66 Line was charged after isolating 11kV feeder.

## September 2021

SI No.	Date of Tripping	Time of outages	Date of Normalizati on	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
	220/66/11 kV Mal	lbase Substat	tion										
6kV & /	02.09.2021	4:38	02.09,2021	4:45	0	5.75	220kV Malbase- Damdum foeder	Malbase S/S and Danidum	OC trip on Y phase-Earth fault	main 1 trip,Zone 1 trip,86 optd	30,8 km	Overcurrent fault	IL1=102.6A<350.1deg,IL2=2966A<163.4deg,IL3=75.83eA<348.7deg,JL4=2794A<163deg
2	06.09.2021	2:09	06.09.2021	15:20	13	22	50/63MVA transformer l	Malbase Substation	Trip due to fault in 66kV p/ling feeder	I.BB optd	66kV pling line		II.1=972.71 A2.24deg,II.2=949 23A121 92deg,II.3=947.4A-117.92deg,
3	06.09.2021	15:09	06.09.2021	15:25	0	22	66kV Pasakha feeder I	Malbase Substation	Trip due to fault in 66kV p/ling feeder	86optd.IOC 50trips	66kV pling line		II,1=1132.19A<-85.03deg/IL2=1787.25A<152.75deg/IL3=898.56A<37.4deg
4	06.09.2021	15:09	06.09.2021	15:20	0	15.	66kV bus coupler	Malbase Substation	Trip due to fault in 66kV p/ling feeder	86 optd, IEF50N trip	66kV pling line		IL1=12132.49A<-39.7deg.IL2=11926.93A<-161.8deg.IL3=12012.05A<77.94deg.IL4=538.29A<28.6deg
5	12.09.2021	0:28	12.09.2021	14:30	14	100	66kV pling feeder		O/C&E/F	86 optd,IN1>trip	66kV pling line		IL1=1.689A,JL2=8.632kA,JL3=3.255A,JN=8.627kA.
6	12.09.2021	0:28	12.09,2021	14:04	13	12	66kV bus coupler	Malbase Substation	O/C&E/F	IOC 50trip,IEF50N trip,general trip	66kV pling line		ILI-646.11A<-130.91deg;IL2-12296.21A<-145.5deg;IL3-376.16A<71.12deg;IN-12628.97A<-145.8deg
7	12.09.2021	14:30	12.09.2021	14:33	0	17	66kV Pasakha feeder I	Malbase Substation	O/C&E/F	1EF 50N trip,86 optd	66kV pasakha line		II1=555.61A<179.64deg, IL2=1310.29A<25.33deg, IL3=277.12A<86.45deg, IL=1058.95A<-127.45deg
8	12.09.2021	14:30	12.09.2021	14:32	0		66kV bus coupler	Malbase Substation	0/C&E/F	IEF 50N trip,86 optd	66kV pasakha line		IL1=2461.34A<-21.13deg, IL2=12416.11A<-146.14deg,IL3=381.59A<67.03deg,IN=10844.10A<-136.65deg
9	12.09.2021	14:30	12.09.2021	14:34	0	19	66kV Pasakha	Malbase Substation	o/c	IEF 50N trip,86	66kV pasakha line		IL1=567.86A<42.45deg,IL2=1634.29A<15.41deg,IL3=189.93A<60.84deg.
10	13.09.2021	13:02	13.09.2021	13:28	0	44	feeder IV 220kV Birpara feeder	Malbase Substation	O/C on B Phase	86 optd, AR lockout shot, zone1 trip	fault location =24.46km		IL1-414.5A;IL2-313.9A;IL3-3345A
11	13.09.2021	13:02	13.09.2021	13:30	0	23	50/63MVA transformer III	Malbase Substation	tripped due to Birpara feeder	Differential trip	24.46km		IL1=89.02A<32.26deg, IL2=122.49A<-108.89deg, IL3=77.94A<121.91deg, IN=37.71A<-126.02deg.
12	16.09.2021	13:36	16.09.2021	13:44	0	24	50/63MVA transformer III	Malbase Substation	bit para teetier				IL1=136.19A<6.63deg, Il2=47.19A<-5.87deg,Il3=68.59A<68.29deg,IN=217.28A<19.97deg.
13	17.09.2021	18:54	17.09.2021	20:03	4	-3	400IV Siliguri feeder	Malbase Substation	O/C&E/F	Main 1 trip,zone1 trip	44.8 km		IL1=248.6A<46.87deg,fl2=265.2A<28.07deg,fl3=1157A<36.8deg,IL4=3321A<36.49deg.
1220/6	/11 kV Singhigoar	Substation					100001			шр			
1	02.09.2021	4:38	02.09.2021	4:58	29	0.4	Singye-samtse feeder	Singyegoan	Overcurrent	86 opted	220kV samtse line	O/C trippted	11=96.04A, 12=2556A, 13=86.7A, 14=2376A.
2	16.09.2023	13:35	16.06.2021	16:14		1.16	Singye-samtse feeder	Singyegoan	Overcurrent	86 opted	220kV samtse line	O/C trippted	I1=102.2A, I2=35.35A, I3=64.32A
)66/33/	11 kV Phuntsholin	g Substation											
1	21.09.2021	14:47	21.09.2021	17:15	2		66kV Chukha and Gomtu feeder	66kV Chukha and Gomtu feeder	Tripped		Chukha and Gomtu end		Both 66kV feeder got tripped at their end causing blackout at Phwentsholing, Informed to BPSO and supply was extended from 66kV Malbase.
2			21.09.2021	14:50	14	idle	66kV Malbase- Pling feeder	66kV Malbase-Pling feeder					At 14:50hrs charged 56kV Malbase-Pling feeder since both 66kV Chukha and Gomtu feeder got tripped at their end. At 17:18hrs opened CB of 66kV Malbase-Pling feeder with opening code 0320 from BPSO and feeder keep under tide condition.
i) 66/33	VII kV Gedu Subs	station											
1	21.09.2021	14:47	21.09.2023	14:50	0	1.08	66kV Chukha- Phuntsholing line.	Black out			Line segment		Supply resumed from Chukha, CHP.
66/33	/11 kV Gomtu Su 21.09.2021	bstation 14:54	21.09.2021	14:56	0	-7.367	66kV Dhamdum	Nill	General tripped		Dhamdum	General	Test charged from Dhamdum and supply stood normal
2	21.09.2021	15:40	21.09.2021	15:47	0	-7.395	66kV Dhamdum	Gomtu substation	General tripped		Dhamdum	General	Test charged from Dhamdum and supply stood normal
3	21.09.2021	15:40	21.09,2021	15:45	0	5.32	66kV P/Ling		General tripped		P/Ling		Test charged from Dhamdum and supply stood normal
		Tripping Repo		of SEPTEMBER	2021								
sl. No.	Date of Tripping	Time of outages	Date of Normalizatio	Time of fault was cleared	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
	(A) 66kV Chumdu s	witching statio	on				1000000						
Ŧ	28.09.2021	1305hgs	28.09.2021	1316hrs		4.44MW	66kV Jemina Feeder	Fed from 66kV Chulchs feeder	Transient fault	G-trip,3ph trip, CB open.	chands	Trip	
2	29.09.2021	1400hrs	29.09.2021	1414hru		(-) 10.65MW	66kV Chukha Feeder	Paro, Panghasa, Jemina	Grid failure	No opertation at chumdo end.	Generation end	Grid failure	
	(B) 66/33kV Watsa					2400							
	an allegan									O/C, OCH & E/F	Fdr. II Chapcha		
1	20/9/2021	14:37hrs 13:38hrs	29/9/2021	14:42hrs 13:43hrs		.250MW	66KV SF6	Fdr. I and Fdr. II		66KV supply fail	66KV supply fail from source	2. 1	Tree fallen on 33KV line at Zimla

	(C) 66/33kV Olaki	ha Substation	1 1										
1	9/1/2021	2:10	9/1/2021	3:15	(4)	2.83	20MVA Transformer II	All the 33kV Outgoing feeders got effected as the 33kV Incomer I & II was tripped.		Directional Over current and Earth fault protection relay and tripping relay 86.	Olakha substation	DC Supply failed	20AIVA Transformer II could not charged due to failure of DC. Charged the Transformer after the DC supply was rectified.
2	9/1/2021	2:10	9/1/2021	3:23	1	2.9	20MVA Transformer I	All the Outgoing feeders got effected as the 33kV Incomer I & II was tripped.	Over current and Earth fault, the Transformer could not charged due to failure of DC,		Ołakha substation	DC fuse blown out	Charged the Transformer after the DC supply was rectified. The fuse blown at charger and was replaced with new one.
3	9/8/2021	11:27	9/8/2021	11:37	0	-16.63	66kV Semtokha- Olakha line	All the 33kV Outgoing feeders was effected due to Grid failure	Grid fail	Nii	Line Segments	Grid fail	As confirmed by the shift duty of Sentokha Substation, the 66kV Supply was tripped from Riruchha end.
4	9/8/2021	11:27	9/8/2021	11:37	0	4.32	66kV Olakha - Changidaphu line	All the 33kV. Outgoing feeders was effected due to Grid failure	Grid fail	Nil	Line segment	Grid fail	As confirmed by the shift duty of Semtokha Substation, the 66kV Supply was tripped from Riruchha end. The 66kV incomer was charged after information received from BPSO
5	9/12/2021	12:10	9/12/2021	12:17	0	3.46	66kV Olakha - Changidaphu line	All the 33kV Outgoing feeders was effected due to Grid failure	Grid fail	Nil	Line segment	Grid fail	As confirmed by the shift duty of Semtokha Substation, the 66kV Supply was tripped from Riruchha end.The 66kV incomer was charged after information received from BPSO
6	9/12/2021	12:10	9/12/2021	12:17	0	-18.9	66kV Semtokha- Olakha line	All the 33kV Outgoing feeders was effected due to Grid failure	Grid fail	Nil	Line Segments	Grid fail	As confirmed by the shift duty of Semtokha Substation, the 66kV Supply was tripped from Rinuchha and.
7	9/29/2021	13:04	9/29/2021	13:14	0	-9.65	66kV Semtokha- Olakha line	All the 33kV Outgoing feeders was effected due to failure of Basachhu line	Supply failed from the Basochhu	Nil	Line Segments	Grid fail	As confirmed by the shift duty of Semtokha Substation, the 66kV Supply was tripped from Rinuchka end.
8	9/29/2021	13:58	9/29/2021	14:23	0	0	66kV Olakha - Changidaphu line	All the 33kV Outgoing feeders was effected due to Grid failure	Grid fail	Nil	Line segment	Grid fail	As confirmed by the shift duty of Sentokha Substation, the 66kV Supply was tripped from Riruchlan end The 66kV incomer was charged after information received from BPSO
9	9/29/2021	13:58	9/29/2021	14:23		5.58	20MVA Transformer I	All the Outgoing feeders got effected as the 33kV Incomer I & II was tripped,	Grid fail	Nil	Line Segments	Line Segments	Charged the 20MVA Transformer I and stood normal
10	9/29/2021	13:58	9/29/2021	14:23		5,58	20MVA Transformer II	Olakha substation	Grid fail	Nil	Line Segments	Grid fail	Charged the 20MVA Transformer and hold occural.
	(D) 66/33/11kV Le		ion								E		
-	66kV LSA - Dochi			27723						1000			<u> </u>
1	29.09.2021 66kV LSA - Basec	13:59hrs	29.09,2021	14:24hrs	0	20.950	66kV LSA-Dochul	Lobeysa Substation	Grid fail	NA.	NA.	NA	66kV 1.SA -Dochula feeder grid fail at 13:59krs without any relay or breakers operated at our end and supply
1	29.09.2021	13:59hrs	29.09.2021	14:24hrs	0	-24 520	66kV LSA-Basoch	Lobeysa Substation	Grid fail	NA.	NA.	NA.	66kV LSA -Dochula feeder grid fail at 13:59krs without any relay or breakers operated at our end and supply
1	(E) 66/33/11 kV P		29.09.2021	14:24hrs		*24.520	DOKY LNA-Dasoch	Lobeysa Sabstation	Orid fail	NA.	NA.	NA.	OOKY LSA -LIOCHIMA feeder grid this at 13:59 hrs without any relay of dealers operated at our end and supply
1	15.09.2021	20:27	29.09.2021	20:32	0	7,43	66kV Chundo Line In	Black out at pare	Tripped from chumdo end		); 		
2	29.09.2021	13:38	29.09.2021	13:42	0	4.95	66kV Churodo	Black out at paro	Tripped from				
2	29.09.2021	14:00	29.09.2021	14:13	0	4.95	Line In 66kV Chundo Line In	Black out at paro again	Chukha Tripped from chukha				
	(F) 66/33/11kV Jes	omle a Substation	_										
1	12.09,2021	12:05	12.09.2021	12:19	0	0.60 Chundu & - 2.13 Changedaphu	66 kV lines, Clundu & Changedaphu	Blackout	Earth Fault	Earth fault & Auto reclose lockout	line segment		In: 15.67 A, Ib: 22.02 A, Ic: 85.05 A, In measured: 63.19 A, Vulo 64.53 V, Velo 60.24 V & V for Chundu & Ib: 11.17 A, Ic: 74.4 & In measured: 63.34 A, Vulo 64.45 V, Vlo: 64.68 V & Voc: 60.54 V for Chargedophu.
2	28.09.2021	13:05	28.09.2021	13:16	0	2.91 C/daphu & 4.53 Chundu	66 kV lines, Chundu & Changedaphu	Blackout	Supply failed from Chundu	Nil	Chundu Switching station end, shown general trip.		2
3	29.09.2021	13:37	29.09.2021	13:41	0	3.15 C/daphu & 4.62 Chundu	66 kV lines, Chundu & Changedaphu	Blackout	Distance protection operated at Changedaphu end	Nil	Changedaphu end, Distance relay operated.		-
4	29.09.2021	13:59	29.09.2021	14:17	0	3.15 C/daphu & 4.62 Chundu	66 kV lines, Chandu & Changedaphu	Blackout	Supply failed from Rurichu, at that time Sem - Chu under Shutdown.	Nil	Source		-

	(G) 66/33/11kV	Dechencholing s	abstation				1							
1	08.09.2021	11:26Hrs	08.08.2021	11:37hrs	0		66KV I/C Semtokha	Whole fdr.	Supply failed fro	m source.				
2	12.09.2021	12:06Hrs	12.09.2021	12:23hrs	0		66KV I/C Semtokha	Whole fdr.	Supply failed fro	m source,				
3	13.09.2021	14:19Hrs	13.09.2021	14:27hrs	0		66KV I/C Semtokha	Whole fdr.	Supply failed fro	in source.				
4	28.09.2021	13:06Hrs	28.09.2021	13:17hrs	0		66KV I/C Semtokha	Whole fdr.	Supply failed fro	un source. Tripped fro	om Basachu end.			
5	29.09.2021	13:59las	29,69,2021	14:18hrs	0		66KV I/C Semtokha	Whole fdr.	Supply failed fro	un source. Tripped fix	on Basachu end.			
							3,1110,772							
		100000000000000000000000000000000000000	200 (1.00000)	000100000	60KV side	e Shut down	T mosco society	county food from 20M/CA		10 00 000				
1	01.09,2021	13:00Hrs	01.09.2021	16:09Hrs	3hrs	44	30MVA T-I	supply feed from 30MVA II						
2	02.09.2021	08:32hrs	02.09.2021	08:55Hrs	0	900	33KV O/G-III	Only O/G-III			hase sequence correction			
3	11.09.2021	21:23Hrs	11.09.2021	23:38hrs	2hrs	-	30MVA T-I	11	Taba-II) Same nig	ht our note team had ree	tified the hotspot perion an	d charged .	0MVA Tr-I and c	text to our equipment we requested Taba end to reduce the load, so they permitted us to hand tripped the 33KV OO -I - ( sharped Tobo O'G-I and informed them to increase the lood as normal. Same night minitenance Engineer had shorted. Bus
4	15.09.2021	11:93Hrs	15.09.2021	13:02hrs	lhrs	****	30MVA T-I	supply feed from 30MVA II	Shut down issue	d to SMD team to arre	st the Hot spot at LV side	30MVA	Tr-l VCB breake	er terminal in Y phase.
	(H) 66/11kV Has	Substation												
1	29.09.2021	14:00	29.09.2021	14:14	Ohrs	-1.14	All the feeders	Due to tripping of 220kV Tserang • Jigoneling line			Supply failed due to trig Jigmeling - Toering line, was normalised after exte supply from 220kV Tsi BHP power plan	The same uding the using to		
7	(I) 220kV Substat		Programme I	170 240			2 2							
1	08.09.2021	11:27hrs	08.09.2021	11:37hru		-17,740	Supply I	siled from both 220kV source		end		Tempo	cary	
2	28.09.2021	13:04hrs	28.09.2021	13:14hrs		-77.180		Grid Failed. No trippin	210.012.000			Tempo	eary	
3	29.09.2021	13:59hrs	29.09.2021	-77.18		-77.180	66kV Semtokho-	Grid Failed. No trippin		Dist. Relay Optd.,		Тепаро	cary	
4	02.09.2021	12:09hrs	02,09.2021	12:22hrs		59.900	Doctuda Line 60kV Semiokha-	Dochula Substation 2	ault Loop= L1-L2 Ge	Imicen conductor		Trasier	nt	
5	02.09.2021	04:08hrs	02.09.2021	04:14las	0.00	59.530	60KV Semrokko-		ph Line Isolator Ge	neral Trio neral trio, Rob		Trasic		
6	09.09.2021	20:47hrs	09.09.2021	23:24hrs	2.00	64.570	Dochula Line 60kV Semiokas-	Document of the second of the	amner snacmed at this	Zone I trin	72.7	Perman	sect	
7:	11.09.2021	19:28hrs	11.09.2021	19:36hrs	0.00	61.890	Dochule Line		eult Loop= L1-L3 Ge	screll trip, Right trip	4,6	Trasies		
8	13.09.2021	13:10hrs	13.09.2021	13:20lms	0.00	42.300	Dochula Line 66kV Semiokho-	Dochula Substation	ault Loop~ L1-L2 Di	t Relay Ontd		Trasier		
9	16.09.2021	16:13hrs	16.09.2021	16:13hrs	0.00	63.840	Dochula Line 66kV Semiokas-	Dochula Substation F	ault Loop= L1-L2 Ge ault Loop= L1-L2 Ge	neral Tein	1.8	Trasics		
10	17.09.2021	16:14hrs	17.09.2021	16:34hrs	0.00		s Declada Line	Dochula Substation F	ault Loop= L1-L2	acral Tree	0	Trasic		
11	21.09.2021	15:09hrs	21.09.2021	15:15hrs	0.00	64.050	Doctula Line		sult Loop= L1-L2 Di		0	Trasier	nt	
12	13.09.2021	14:19hrs	13.09.2021	14:27hrs	0.00	15.150	Orchendolige 1	Dechencholing Substation U				Trasics		
13	28.09.2021	13:04hrs	28.09.2021	13:04hrs	0.00	19:840	Dechescholing	Dechencholing Substation	Inder Voltage trip Gi	d failed		Trasies	ut .	
14	22.09.2021	11:09hrs	22.09.2021	12:53hrs	1.00	10.030	40/50MVA Traformer	attain the oil leakage on Y <sub>1</sub>	ph Bushing					
(J)	)66/33/11kV Par	ngbesa substa	tion							N. Control				
1	29.09.2021	13:38	29.09.2021	13:42	0	1.6	66kV Chumdo Line In	Black out at paro	Tripped from chukha					
2	29.09.2021	14:00	29.09,2021	14:13	0	1.6	66kV Chumdo Line In	Black out at paro again	Tripped from chukhu					
_	(K) 66/33kV Cha	ingidaphu Subst	ation				2000		1					
1	29.09.2021	13:37hrs	29.09.2021	13:41hrs			Changidapho- Jemina Line	66kV Changidaphu-Jemin Line	Grid Failed	Dist. Relay optd, RYBph Trip, Power Swing			Trasient	
2	08.69,2021	11:25hrs	08.09.2021	11:42hrs			66kV Changidaphu- Olakha Line	Changidaphu Substation	a Grid Failed	Dist. Relay optii, Bph Trip, Power Swing			Trasient	

	(L) 66/33kV Damji	Substation										
1	08.09.2021	1125 hrs	08.09.2021	1136 hrs	0	-0.27	56 kV Incoming line	66 kV Thimphu-Gasa Line, Damji Substation & all outgoing Feeders	Trip	NA	NA	Line trip from Semtokha Substation
2	12.09,2021	1209 hrs	12.09.2021	1225 hrs	0	+1.07	56 kV Incoming line	67 kV Thimphu-Gasa Line, Damji Substation & all outgoing Feeders	Trip	NA	NA:	Line Trip from Semtokha Substation, i.e. 220 kV CHP-SEM Feeder Trip on B Phase Fault (Earth Fault)
3	13.09.2021	1419 hrs	13.09.2021	1428 hrs	0	-0.71	56 kV Incoming line	58 kV Thimphu-Gasa Line, Damji Substation & all outgoing Feeders	Trip	NA	NA	Line Trip from Sentokha Substation, i.e. 220 kV CHP-SEM Feeder Trip
4	28.09.2021	1305 hrs	28.09.2021	1316 hrs	0	-0.85	56 kV Incoming line	68 kV Thimphu-Gasa Line, Damji Substation & all outgoing Feeders	Trip	NA	NA	Line Trip from Semiokha Substation, i.e. 220 kV Ruricha Feeder Trip at Basochu end.
5	29.09.2021	1400 hrs	29.09.2021	1418 hrs	0	-0.83	56 kV Incoming line	68 kV Thimphu-Gasa Line, Damji Substation & all outgoing Feeders	Trip	NA	NA	Western Grid Blackout due to 220 kV Tsirang-Jigmeling Line
6	30.09.2021	1727 hrs	30.09,2021	1732 hrs	0	0.22 & 0.16	ower Transformer	Incomer II & all outgoing feeders	Trip	50 N & 86 OPTD		Tripped due to earth fault & overcurrent of Outgoing Feeder

## October 2021

		Tripping R	eport for th	month of	OCTOBER	2021								
Sl. No.	Date of Tripping	Time of outages	Date of Normaliza tion			Duration of	MW before outage	Foeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	f Remarks
	(A) 66kV (	humdu swit	tching		8 9	Jan 32					d iff			
	200 22 MAR	erwer								14	1			
1	(B) 66/33k	V Watsa Su	5/10/2021	1104es		Steake	380000/	OCKV NP6 treaker	7th 1 and 7th 13	OC OCHAEF	OC OCH & XT plu mersed	Fdr. II Charcins	_	Type fallers as SSEV free at Conscisu
3	8/18/2021	17:73au	#10/2021	12379vs		(America)	380500	SSEV browner		MCKV pandy full from storce	MELV pagely that times source	MKV speck thi from onuce	Trepod	The past is 32K and it (130K20)
-				TA SCORE T		77.000	- Janeary	THIS T ACCURAGE	14.10010	proset sugger same some v	Trees indight the date to date	book and a man among	Language	
	(C) 66/33k	V Otakha S	abstation						100.00					
1	10/3/2021	4:01	10/3/2021	4:33	0	32	0	20MVA Transformer II	All the Outgoing feeders got effected as both the transformer was tripped.	Due to Failure of DC, The transformer got tripped	Nil	Olakha Substation	DC Failure	After rectification of the DC circuits, Reset the relay and test charged the transformer and hold normal.
2	10/3/2021	3:54	10/3/2021	4:33	0	39	2.8	20MVA Transfermer I	All the Outgoing feeders got effected as both the transformer was tripped.	Due to Failure of DC, The transformer got tripped	Nil	Olakha Substation	DC Failure	After rectification of the DC circuits, Reset the relay and test charged the transformer and hold normal.
3	10/8/2021	12:37	10/8/2021	12:40	0	3	4.18	20MVA Transformer II	All the Outgoing feeders got effected, as both the 20MVA Transformer was tripped.	Transformer was tripped while charging of 33kV incomer II	DIR. Over current and Earth fault portu relay 67 optd.1 General trip 2 UV operated. Indication; Bus under Voltage and Over current and earth fault operated.	Line Segments	Transies Fault	Reset the relay and test charged. Transformer hold normal.
4	10/8/2021	13:03	10/8/2021	13/17	0	14	0	20MVA Transformer II	All the Outgoing feeders got effected, as both the 20MVA Transformer was tripped.	Spring discharged the to tripping of 33kV Incomer I and II	Nil	Substation	Spring disclory	Due to repeated tripping of the 35kV incomer I & II, the HV breaker of 20MVA & II that got spring discharged, due to that charging of transformer could not a operated causally from local and remote from control cross. So after spring was charged from switch yard, Charged the Transformer and stood cormal.
3	10/8/2021	14:24	10/8/2021	14:25	0	1	3.53	20MVA Transformer II	All the Outgoing feeders got effected, as both the 20MVA Transformer was tripped.	Transformer was tripped while charging of 33kV incomer II	DIR. Over current and Earth fault ports relay 67 optd.1 General trip 2 UV operated. Indication; Bus under Voltage and Over current and earth fault operated.	Line Seguents		at Transformer was tripped while charging of 53kV incomer II. After isolating all t feeders , Charged the Transformer and stand normal.
7	10/8/2021	12 22	10/8/2021	12:36		14	1.66	66kV Olakha- Jemina line	All the 33kV Outgoing line was effected	To Change the Tap Position on off load Condition at Chhalcha end	Nil	At Chukha end	Shutdov	The supply was hand tripped from Chhalda end to change the Tap position on Of- load condition as to boost the voltage on line as per information received from BPSO.
8	10/8/2021	12:32	10/8/2021	12:36	0	4	4.21	20MVA Transformer I	All the Outgoing feeders got effected, as both the 20MVA Transformer was tripped.	Transformer was tripped while charging of 33kV incomer II	Under Voltages Operated along with 86 Tripping relay	Line Segments	Under Voltage	The Transformer was Tripped, while charging of 33kV incomer ii .
9	16/8/2021	13:03	10/8/2021	13:17	0	14	o	20MVA Transformer 1	All the Outgoing feeders got effected, as both the 20MVA Transformer was tripped.	Spring discharged due to tripping of 33kV Incomer I and II	Only 86 Tripping Relay Operated	Substation	Spring	Due to repeated tripping of the 33kV incomer [ & II, the HV breaker of 20MVA I & II had got spring discharged, due to that charging of transference could not operated manually from local and remote from control roca. So ofter spring was charged from switch yard, Charged the Transformer and stood normal.

											1		1	1
10	10/8/2021	13:16	10/8/2021	13:45	0	29	1	33KV DPH I Feeders V	All the 33kV outgoing feeders effected	Due to Change over the supply from Chinkha line	Over Current and Earth Fault along with Master relay Trip. Indication 1& 5	Substation		Due to Voltage Issued, the feeders was tripped, Reset the relays and test charge the feeders and stood normal.
11	10/8/2021	14:24	10/8/2021	14:25	0	1	3.38	20MVA Transformer I	All the Outgoing feeders got effected, as both the 20MVA. Transformer was tripped.	Transformer was tripped while charging of 33kV incomer II	Only 86 Tripping Relay Operated	Line Segments		The Transformer was Tripped while charging of 33kV Incomer II , Reset the rel and test charged Transformer hold normal.
12	********	7:16	*******	7:31		15	4.36	20MVA Transformer 1	All the Outgoing feeders got effected as both the transformer was tripped.	Due to Under Voltage	Indication: Bus under voltage opted. O/C and E/F along with tripping relay 86.	Line Segments	Transier Fault	Reset the relay and test charged Transformer hold normal.
13	angususa	10:23	********	11:11		29	3.08	20MVA Transformer I	All the Outgoing feeders get effected as both the transformer was tripped.	Due to Under Voltage	Indication: Bus under voltage opted. O/C and E/F along with tripping relay 86.	Line Segments	Trensi en Fault	Reset the relay and test charged. Transformer hold normal.
14	********	11:21	********	11:43		22	0	20MVA Transformer I	The feeders was not effected as the supply was fed from Transformer II	Hand Tripped	Nil	Line Segments		The Transformer was tripped after instruction form BPSO for testing of voltage, charged the transformer with charging code 1687 from BPSO and hold normal
15	********	12:08	dukukuku	12:09		1	3.49	20MVA Transformer II	The feeders was not effected as the supply was fed from 20MVA Transformer I	Tap Changing of Transformer	Nil	Substation	under	20MVA II hand tripped after getting clearance from BPSO to increase the tape position from 9 to 13 with opening code no 0378. Charged the transformer with closing code no 1688 and stand normal.
16	*******	10.46	*******	10:56		10	0.02	20MVA Transformer II	The feeders was not effected as the supply was fed from 20MVA Transformer (	Tap Changing of Transformer	Nil	Substation	under	20ht/A II hand tripped after getting order from BPSO to decrease the tape position from 13 to 9 with opening code no 0389 and charged the transformer with closing code no.1702 and stand normal.
	(D) 66/33/1	HkV Lobe	sa Substati	on										
1	02.10.2021	06:09hrs	02.10.2021	06:31hrs	0	22	24.620	66kV LSA-Dochula	NA	Under voltage at Dochula end	IDMT OC&EF relay	NA	NA	66kV LSA -Dochula tripped at 06:09 hrs, operating breaker open at our end and informed BPSO and line was charged at 06:31hrs with the charging code: 1674 66kV LSA -Dochula tripped at 20:52 hrs, operating breaker open at our end and
2	08.10.2021	20:52hrs	08.10.2021	20:58lars	0	6	25.090	66kV LSA-Dochula	NA.	NA.	Dist relay operated with 86 relay	NA	NA	informed BPSO and line was charged at 20:58hrs with the charging code:1676 and DR submitted to BPSO & C&PD
3	08.10,2021	21:02brs	08.10.2021	21:11hrs	0	9	22,990	66kV LSA-Dochula	NA	NA	Dist relay operated with \$6 relay	NA .	NA.	66kV LSA -Dochula tripped at 21:02 lirs, operating breaker open at our end and informed BPSO and line was charged at 21:11hrs with the charging code:1677 and DR submitted to BPSO & C&PD
4	08.10.2021	21:13 hrs	08.10.2021	21:19hrs	0	12	22.990	66kV LSA-Dochuia	NA.	NA .	Dist relay operated with 86 relay	NA NA	NA	66kV LSA -Dochula tripped at 21:13 hrs operating breaker open at our end and informed BPSO and line was charged at 21:19hrs with the charging code:1679 and DR submitted to BPSO & C&PD
6	03.10.2021	03:54hrs	03.10.2021	03:58lus	0	:4	-23.290	66kV LSA-Basochu		NA .	Stirelay operated	NA .		66kV LSA -Basochu feeder tripped at 03:54hrs operating brenker our end and was breaker closed at 03:58hrs .Supply was feeded fro Dochula at time of tripping LSA-Basochu feeder.
	(E) 66/33/1	II kV Pare	Substation											
1	08,10- .2021	12.24Hrs	2021	12.32Hrs	0	8	5.47	66kV Chumdo Line In	Its outgoings	Tripped from chukha	TA TA			
_	(F) 66/33/1	IkV Jemin	Substation	-			Control of the						-	
1	08.10,202 1	12:23	08.10.2021	12:27	0	4	09.72 Chundo & - 11.70 Chundu	66 kV lines, Chundu & Changedaphu	Hiackout	Supply failed from Chakha.	-	line segment		Supply failed from the Source.
1	02.10.202 1	06:08hrs	02.10.202 1	06:16hrs		8.00	-72.120	220kV Semtokha- Rurichu Line	Line and Semtokha  220kV Semtokha-Rurichu		Main-1 Optd, RYB Trip		Trasient	
2	03.10.202	03:55hrs	1	03:58hrs		3.00	-65.100	220kV Semfokha- Baricha Line SONVA-iI &	Line and Seastalcha Doctura Substation and		Mein-1 Optd, RYB Trip		Trasient	
3		21:16hrs	06.10.202	21:32hrs		16.00	39.310	20/SCMVA-II &	Dochula Substation and Dechenchaling Substation	W11 gauge of 40/50MVA lett off from the	1.V Backup optd, Rph Trip, 1>trip	40/50MVA transformer at Semtoldia SS	Тетрога	ny .
4	19.10.202	22:43hrs	19:10:202	22:48hrs		5.00	63.720		Dochala Substation	Fault Loop= L1-L2	Dist. Relay Optd., General Trip	0.000am	Trasient	
5	28.10.202	10:03 hrs	28.10.202	12:55hrs	1.00	52.00	41.360	220kV Semtokha-		Shutdown taken by Karma Wangda (Incharge		***************************************		
6	08.10,202	09:15hrs	25.10.202	19:20hrs	418.00	9.00	17.710	668V Smetokla-	66kV Bus-1, 50MVA-1 and	TLA(SELLahossa) to cut docum the troog as Shindown taken by Dawa Gyelishen, TPO				
,	18.10.202	10:27hrs	18.10.202	16:06hrs	5.00	39.00	31.320	Olaska line (ick) 668 V Semiosha-		Olabba for reconduting line with HTLS.  Temporary jumper connection at tower no.31.				
8	16.10.202	00:33lars	16:10:202	05:05hrs	1.00	32.00	17,690	60kV Semiokha-	Deckencholing is and Damji	Shuldown taken by SMG Semtokha for				
9	24.10.202	00:10hrs	24.10.202	01:37hrs	1.00	27.00	12,660	Dechenchaling Lina 6bkV Semiokha-		tightenion of loose pershiplis on line isolator Shuldown taken by Pema Wangeluk, SMC				
3	1	Actions	1	A CIO INTO	1,00	27.00	12,000	Dechencholina Lina	22	Sentolibs to ottend hotsort on Line isolator				

## November 2021

	-20 CES (100 CES)	Time of	Date of	Time of fault	Duration of	MW before	100002140000	Name of the Substation/lines affected	200000000000000000000000000000000000000	UNITS FOR SECURIS	Exact location of fault [Line segment/	######################################	************
	Date of Tripping	Outages	Normalization	was cleared	Outages (Hrs)	outage (MW)	Feeder Name	by the fault	Reasons of fault	Relay operations	Substation	Type of outages	Remarks
	/220/66/11 kV ! Above	Malbase Su	ostation	V/ 100									
1	15.11.2021	16:10	15.11,2021	16:16	0	33	200 MVA ICT	2	Tripped	PRD OPERATED,PRD tripped,86 optd	200 MVA ICT	Tripped	ICT got tripped due to on going maintenance work on spare phase ICT, while removing the connection of PRD of Sphare Phase ICT.
2	16.11,2021	9:49	16.11,2021	10:31	a	44	200 MVAICT	8	Tripped	OIL Surge relay optd. 86 aptd, OSR optd.	200 MVA ICT	Tripped	ICT got tripped due to on going maintenance work on spare plasse ICT, while removing the connection of PRD of Sphare Phase ICT.
- 1	B) 66/33kV Wats	sa Substation											
3 <b>1</b>	14/11/2021	8:02hrs	14/11/2021	8:14hrs		650MW	66KV SP6 breaker	Febr. 1 and Febr. II	O.C, OCH, EF & EFH	O/C, OCH, EF & EFH relay operated	66KV SF6 breaker charged offer resetting relays and supply found normal but the 33KV Breaker got mechanical problem as it cold not lock so kept the motor MCB off after consulting with Maintenance head.	Tripped	
	C) 66/33kV Olak	cha Substatio	п								130.00.0		
1	11/25/2021	18:16	11/25/2021	18:50	0	14.06	66/33EV 20MVA. Transformer II	All the Outgoing and Incomer feeders got effected as the Transformer I & II was tripped.	Due to Over Current and month Foult	Over current and earth finalt along with 86 trip relay	Otalche Substanion	Transiest	Reset the relays and charged the timesformer individually and found normal
12	11/25/2021	18:16	11/25/2021	18:50	ŭ.	14.06	66/33EV 20MVA, Transformer II	All the Outgoing and Incomer feeders got effected as the Transformer I & II was tripped.	Due to Over Current and corts Fault	Over current and earth finds along with 86 trip relay	Olakha Substation	Transicut	Reset the relays and charged the transformer individually and found normal
3	11/26/2021	20:58	11/25/2021	21:22	0	39.78	66kV Olakha- Seutokha Line	Olaidar substaticu	Orid failed	Nil	Line Segments	Disc Puncture	As per the information received from the Sentroldm end the supply was fail from source as the 220KV Sentroldm to Ruricha, the insulation disc was puncture at line.
	D) 66/33/11kV L									V	A-		10000000000000000000000000000000000000
	13:11:2021		23.11.2021	12:01hrs	0	17.170 25.200	66kV LSA-Dochula 66kV LSA-Dochula		NA NA	86 relay operated	NA .	NA NA	66kV LSA -Dochula tripped at 11/43 hrs operating breaker open at ou
	06.11.2021 06.11.2021		26.11.2021 27.11.2021	21:30tm 11:20tms	12	25.200 ±6.300	66kV LSA-Dochula		NA NA	87 relay operated NA	NA NA	NA NA	66kV LSA -Dockula tripped at 20:58 hrs ,operating breaker open 66kV LSA -Dockula Hand/code 0427)tripped at 23:02 hrs as per
	26.11.2021		26.11.2021	22:19hra	î	-23,290	66kV LSA-Basochu		NA NA	86rolay operated	NA NA	NA NA	66kV LSA -Basochu foeder tripped at 20:39hrs operating breaker oper
	G) 66/33/11kV D			40.1718.0	•		19961 0997 90099		1,771,	and plants	100		The second secon
1	26.11.2021	20:40hrs	26.11.2021	20:45hrs	0		66KV seutokha Inconer	whole fdr.	Supply failed from source				
2	26.11.2021	20:57hrs	26.11.2021	21:26hs	0		66KV sentokha Iroomer	whole fdr.	Supply failed from source				
- 1	T) 220kV Substati	Sea Somtol b				-	Income						
	26.11.2021	Lance and the	26.11.2021	21:22hrs		-60.680	220kV Sentokha- Chakha Line	Semiokhn Substation	Chi	tha and breaker opened during the test charge of	220kV Sentokha-Ruricha Line	Trasient	
-	26.11.2021	200000	27.11.2021	18:44brs	22.00	-66.040	220kV Sennokha- Rorichu Line	220kV Sentokha-Ruricha Liur and Sentokha Substation	L1-E (Insulator De-Cap at location tower RS-91	Zone-1, RYBph Trip, Fault Loop-L1-E	5.Hea	Permanent	
	K) 66/33kV Chan	ngidaphu Sub	station	0 1					001 800 000 000 000			C.S.	
1	26.11.2021	20 42hrs	26 11 2021	22.06hrs	1	-4,73	66kV Changidapho- Olakha line	66kV Chingidaphu-Olakha line	Grid Failed	Distance relay optd, Rph trip		Trasient	
	L) 66/33kV Damj	ii Substation											
1	04.11,2021	0.220 hrs	04.11.2021	0225 brs	0	0.17	Transfermer 2	Dunji Substation & all outgoing Feeders	Trip	IDMY	NA NA		Tripped due to earth fault on Punalcha Feeder H02 (B Phase Trip)
2	04.11.2021	1516 hrs	64.11.2021	1520 hrs	0	0.3	Transformer 2	Donji Substation & all outgoing Feeders	Trip	50 N	NA.		Tripped due to earth fault on Panakha Feeder H02 (B Phase Trip)
4	05.11.2021	2212 hrs	0611.2021	0006 lass	1	0	Transformer 1	NA NA	Trip	NA.	NA:		Transformer 1 which was kept under idle charge was trip the BUCH Trip
7	06.11.2021	1241 hrs	06.11.2021	1245 hrs	0	0.37	Transformer 2	Dungi Substation & all outgoing Feeders	Trip	50 N & B Phase Trip	NA NA		Tripped due to earth fault on Gasa Feeder
8	06.11.2021	1649 hrs	06.11.2021	1700 hrs	0	0	Transformer 1	NA NA	Trip	86 OPID	NA NA		Mile charge Trafe-1 Ref 615 BUCH Trip
9	06.11.2021	2052 hrs	06.11.2021	2105 hrs	0	0	Transformer 1	NA	Trip	86 OPTD	NA		lidle charge Trafe-1 Ref 615 BUCH Trip, Trafe-1 was charged on LV side with full load on 07.11.2021 at 0950 hrs
10	07.11.2021	1440 hrs	07.11.2021	1446 hrs	0	0.36	Transformer 1	Dongi Substation & all outgoing Feeders	NA.	86 OPTD	NA NA		Tripped due to over current on Panakhn Feeder
11	07.11.2021	1738 hrs.	07.11.2021	1742 hrs	ū	0	Transformer 1	Danji Salstation & all outgoing Feeders	NA NA	86 OPTD	NA.		BUCH Trip
	07.11.2021	2057 hrs 0948 hrs	07.11.2021 08.11.2021	2100 hrs 1106 hrs	26	0.38	Transformer 2	Demži Substation & all outgoing Feeders NA	NA Idle	86 OPID NA	NA NA		BUCH Trip  Transformer 2 (5 MVA) idle charge, full load given to 10 MVA, charged next day for Trafo-1 maintenance
	V/III SIAME S						Transformer 1	NA	Trip	86 OPTD	NA.		Idle sharge Trafe-1 Ref 615 BUCH Trip, after refilteration idle sharge on 12.11.2021 at 0300 kes and charged on LV side with full at 0945 ke
13	10.11,2021	1050 hrs	12.11.2021	0300 tes	40	0.35	THUSIOTHES T						on 12.11 2021 at 0300 hrs and charged on LV side with full at 0945 hr
13	1,111,711,014,111,1	1090 hrs 2040 hrs	12.11.2021 26.11.2021	0300 hrs 2045 hrs	40	+0.44		Dunji Substation & all outgoing Feeders	Trip	NA.	NA NA		on 12.11 2021 at 0.500 hrs and charged on LV side with full at 0.943 are Trip due to 66 kV Incoming Line due to 220 kV Grid Failuer
12 13 15 17 18	10.11,2021	2040 hrs 2058 hrs	26 11 2021 26 11 2021			+0.44	66 kV Incoming Line			NA NA	NA NA		

## December 2021

SI No.	Date of Tripping	Time of outages	Date of Normalization	Family was	Duration of Outages (Hrs)	MW before outage (MW)	Feeder Name	Name of the Substation/lines affected by the fault	Reasons of fault	Relay operations	Exact location of fault [Line segment/ Substation]	Type of outages	Remarks
	/220/66/11 kV N Above	Malbase Substa	tion										
1	01.12.2021	12:23	03.12.2021	13.31	49		200 MVA ICT	3	Tripped		200 MVA ICT	Tripped	33kV Tertiary delta connection LAR and Y phase got Blast and charged with code BPSO 1875
2	01.12.2021	12:24	02.12.2021	18:01	5		400kV TAL-MAL FOR III	200	Tripped		400kV TAL-MAL FOR III	Tripped	R- phase LA got blast and charged with code BPSO 1872.
3	08 12.2021	13:09	08.12.2021	13:19	0	-198	400EV TAL-MAL FOILEI	- 12	Tripped	O/C,Zone I tripped, optd	Zone ( 19.32km	Tripped	The feeder got tripped due to over current. II= 122.5A I2=4.057kAJ3=4.107kA
(B)66/3	VII kV Phuntshoi	ling Substation	Ü.							300000000000000000000000000000000000000			
-1	25.12.2021	14:57	25.12.2021	15.06	0	1.54	66kV Chukha feeder	66kV Chukha- Pling	DIST OPTD	DIST OPTD, 186 & 86	Line	Tripped on Fault	At 15:06hrs test charged after getting degrance from BPSO and stood normal.
SL No.	Date of Tripping	Time of outages	Date of Normalization	Time of fault was cleared	Duration of Ontages (Hrs)	Feeder Name	Name of the Substation/lines affacted by the fault	Reasons of fault	Relay operations	Exact location of fash [Line segment/ Substation]	Type of outages	Remarko	
	(A) 66kV Chumdu 01.12.2021	switching station 0217hrs	61.12.2021	9227hm		66kV Chuidus Inconstr	Fed from 66kV Jennina Incorper	1.124		Chande	-		
	(B) 66/33kV Watsa		[01.12.2021	022/hm		66kV Chuiche Incomer	Fed free block Jerman Incomer	transient finalt	СП сред	Chando	Trap		
1	29/12/2021	20:28hrs	29/12/2021	20:33hrs		66KV SF6 breaker	Fdr. I and Fdr. II	O/C, OCH, EF & EFH	O/C, OCH, EF & EFH relay operated	Feeder I Warakha	Tripped	Test charged but line could not hold and kept feeder I Wanakha isolator open and the line hold	
	(C) 66/33kV Olnkh	hn Substation						-200			9	55-50 VM-2 (1-1)	
3	12/1/2021	2:07	12/1/2021	2:26	0	66kV Sentokha- Obéda line	All the outgoing feeders and 33kV Incomer at Olikha was effected	Dist.Prote.Relay Opted.	DISTANCE PROTN RELAY-21 Optd.Indication 1,2,3 &12, 1. General trip. 2.Distance Opted, 3, Zone 1 Opted, 12 LBB Optd.Trip relay-86	Senitoklia Sobstation	Conductor Sessp	As per the information received from the Sentolda end, the supply was fail due to tripping of 66kV Dochula Line. As confirmed by the Shift personal at Sentolda end, It-Phase conductor map at Sentoldas Substation.	
2	12/10/2021	12:54	12/10/2021	12:59		66/33kV 20MVA, Transformer I	All the Outgoing feeders got offsected as the 35kV Incomer I & II was tripped.	protection operated	DIR.Over Current and Earth Fault along with Master Trip Relay + 86	Olakha Substituto	Transient Fault	As per telephosic talk received from ESD Ugyen Labeha at Lungtenphu Substation , Due to tripping of 35kV outgoing (Lungtenphi Fdr.) at 35kV Lungtenphi Substation and , the 66/33kV 20 MVA -1 was tripped at our end.	
3	12/10/2021	12:54	12/10/2021	12:59		66/33kV 20MVA. Transformer II	All the Outgoing and Incomer fooders got offected as the Transformer I & II was tripped.	Over Current and Earth fault protection operated	DIR.Over Current and Earth Fault along with Master Trip Relay - \$6	Olakha Substation	Transient Fault	As per relephonic talk received from ESD Ugyen Labchu at Lungsemphi Substation , Due to tripping of 35kV outgoing (Lungtenphi Fér.) at 35kV Lungtenphii Substation and , the 66/33kV 20 MVA -1 was tripped at our end.	
	(D) 66/33/11kV Lo 56kV LSA - Docks								S		8		
	01.12.2021	02:10hrs	01.12.2021	02:27hrs	0		10000	2000	7 5000000000000000000000000000000000000	50.045	1000	66cV LSA -Docfula tripped at 02:10 less and informed to BPSO, line charged as	
ick :	(F) 66/33/11kV Jes		01.12.2021	9232 (NS		66kV LSA-Dochula	NA	NA	O/C & E/F relay	NA NA	NA	per BPSO charging code 1861	
.1	01.12.2021	2:17	01.12.2021	2:26	0	66 kV Line, Chundo & Changedaphu	Black out	E/F	Earth Fault relay operated	Line segment		Both the lines tripped on Earth fault on 02:17 Hrs. test charged at 02:26 Hours & stood normal. Transient fault.	
	(H) 66/11kV Hoa S	Substation				Te ChingCorpini			8		9	OAPP SELECTION OF	
1	01.12.2621	2:08	01.12.2021	2:25	0	66kV Incomer	All the Seeders	Source fail	Nil	Chhukha power heuse	Source fail from Chhukha power house, neemelised the supply from the source.		
2	16.12.2021	16:35	16.12.2021	1640		666V Incomer	All the feeders	usknown	oc	Panglesia sa, Pano	Supply was researed from Paragbosa and after resetting all the relays.		
Э	30.12.2021	328	30.12.2021	5107	1	66kV Insenser	All the feeders	unknown	oc	Parighesa su Panu	Due to beavy mow laff at the and place, the restoration of supply was delayed. The supply was normalised after suppling the snow fall.		
4	30.12.2021	5:58	30.12.2021	6:05	0	66kV Incorner	All the Seeders	unknown	oc	Parghesa ss,Paro	Supply was resumed from Parabosa end after resetting all		
	(I) 220kV Substatic	on Semtokha							1		the relays.	1	3/
1	01.12.2021	02:02hrs	61.12.2021	12:06brs	10.00	66kV Seminklus- Dochula Line	Docinile Substation		Distance relay optil., Zone 1 trip	Semiokha substation	Permanud		
2	21,12,2021	18:55hrs	21.12.2621	19:31brs		40/50MVA Temsformer	No Interruption	Position to increase the 66kV side Voltage			- Marion		
(J)	66/33/11kV Pans												
1	16.12.2021	16.35Hrs 3.30Hrs	16.12.2021 30.12.2021	16.40Hrs 5.08Hrs	0	66kV chundo line in	Its outgoings	OC OC	Distance	66kV Line out	Transient	T. 17 0 L	
3	30.12.2021	3.30Hrs 5.58Hrs	30:12.2021	6.05Hrs	0	66kV Hos Line Out	Its outgoings and substation files its outgoings	OC.		66kV Line out	Long Transient	Tripped Has fde due to which it also tripped chundo bensker too	
	(K) 66/33kV Chang												
-1	01.12.2021	02-92hrs	61,12,2021	02:29hrs		66kV Changidaphs- Olasha line	56kV Changidapho-Olakha line	Due to Dochula line condutor supped at Sentokha substation	Distance relay oped, Rph Zone 1 trip		Trasient		
	(M) 66/11kV Docts	nia Substation							(1) (2)		8		
-1	26.11.2021	20:58hrs	21:33krs			substation black out	All DHI fama house	trip from source substation	BS relay			DHI farm bouse	